



Avaya Solution & Interoperability Test Lab

Application Notes for NextGen LA-6000 with Avaya Aura® Communication Manager 7.1 and Avaya Aura® Application Enablement Services 7.1 for VoIP call recording – Issue 1.0

Abstract

These Application Notes describe the configuration steps required for NextGen LA-6000 to interoperate with Avaya Aura® Communication Manager 7.1 and Avaya Aura® Application Enablement Services 7.1 for VoIP call recording.

In the compliance testing, NextGen LA-6000 uses the Avaya Aura® Application Enablement Services, Telephony Service API (TSAPI) interface to monitor calls, especially contact center agents to Avaya Aura® Communication Manager, and obtain call information and media associated with the monitored agents for call recording.

Readers should pay attention to **Section 2**, in particular the scope of testing as outlined in **Section 2.1** as well as any observations noted in **Section 2.2**, to ensure that their own use cases are adequately covered by this scope and results.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

1. Introduction

These Application Notes describe the configuration steps required for NextGen LA-6000 (LA-6000) to interoperate with Avaya Aura® Communication Manager (Communication Manager) 7.1 and Avaya Aura® Application Enablement Services (AES) 7.1 for VoIP call recording.

In the compliance testing, LA-6000 used the AES' TSAPI interface to monitor calls, especially contact center agents to Communication Manager, and obtained call information such call start and end time, caller IDs, etc., and thereby extract media associated with the calls for call recording from monitored ports. The media is obtained from monitored network ports of Avaya Aura® Media Server (AAMS), Medpro boards and/or Media Gateway Processor (MGP) to the LA-6000 server and extracted the Real-Time Transport Protocol (RTP) packets for the voice data. Voice recording is then stored on the NextGen VoISplus server which allow searching for voice records using cell data from web-browser.

2. General Test Approach and Test Results

The feature test cases were performed manually. Each call was handled manually on the station user with generation of unique audio content for the recordings. Necessary user actions such as hold and resume were performed from the user stations to test different call scenarios for Avaya 9600 Series H.323 IP Deskphones. It also included feature calls such as call park/unpark, call recovery from long hold call, call transfer and 3-way conference.

The serviceability test cases were performed manually by disconnecting/reconnecting the Ethernet cable to LA-6000 server, restarting TSAPI service on the AES, busying and releasing CTI link on the Communication Manager, interchange Communication Manager server and finally restarting the AES server.

The verification of tests included using the LA-6000 logs for proper message, using the to verify proper logging and playing back of the calls.

DevConnect compliance testing is conducted jointly by Avaya and DevConnect members. The jointly-defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect compliance testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member's solution.

Avaya recommends our customers implement Avaya solutions using appropriate security and encryption capabilities enabled by our products. The testing referenced in these DevConnect Application Notes included the enablement of supported encryption capabilities in the Avaya products. Readers should consult the appropriate Avaya product documentation for further information regarding security and encryption capabilities supported by those Avaya products.

Support for these security and encryption capabilities in any non-Avaya solution component is the responsibility of each individual vendor. Readers should consult the appropriate vendor-supplied product documentation for more information regarding those products.

For the testing associated with these Application Notes, the interface between Avaya systems and NextGen LA-6000 did not include use of any specific encryption features as requested by NextGen.

2.1. Interoperability Compliance Testing

The interoperability compliance test included feature and serviceability testing.

Feature testing focused on verifying the following on LA-6000 proper recordings, loggings and playback of calls:

- Inbound calls, external and internal calls
- Outbound calls, external and internal calls
- External and Internal Transfer calls
- 3-Party Conference calls
- Call Hold (including Long Hold recall) and Resume
- Call Park and Unpark
- Redirection on No Answer (RONA)

Serviceability testing focused on verifying the ability of LA-6000 to recover from adverse conditions, such as disconnecting/reconnecting the Ethernet cable to LA-6000 server, restarting TSAPI service, restarting the CTI link as well as AES and interchange of the Communication Manager server.

2.2. Test Results

All feature test cases were successfully completed. An observation to note is that media shuffling needs to be disabled to direct all voice traffic through media processors such as AAMS, Medpro board and MGP where traffic is monitored for RTP.

2.3. Support

Technical support on NextGen LA-6000 can be obtained through the following:

- **Phone:** +81-(0)50-5865-3607
- **Web:** <https://www.nextgen.co.jp/>

3. Reference Configuration

NextGen LA-6000 has a thin client web interface that can be used to review and playback the call recordings on the VoISplus server.

In the compliance testing, NextGen LA-6000 monitored the agent station extensions shown in the contact center device table below.

Device Type	Extension
VDN	14001
Skill Group	13001
Agent Station	10001,10002,10006
Agent ID	11001,11002,11003

Figure 1 below illustrates the test configuration consisting of a duplex pair of Avaya Aura® Communication Manager servers, Avaya G430 Media Gateway, Avaya Aura® Application Enablement server and Avaya Aura® Media Server. Avaya 9600 Series H.323 IP Deskphones are used as agent stations. NextGen LA-6000 server is installed on a virtualized Centos 7 server which communicates with the TSAPI Service on the Avaya Aura® Application Enablement Services server. A simulated public PSTN trunk connects to the system. The 9600 Series H.323 IP Deskphones are used to generate intraswitch calls (calls between telephones on the same system) and outbound/inbound calls to/from the PSTN.




Figure 1: Test Configuration

4. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided:

Equipment/Software	Release/Version
Avaya Aura® Communication Manager (Duplex)	7.1.2 (R017x.01.0.532.0-24184)
Avaya S8300D Server (w/ G430) running Avaya Aura® Communication Manager	7.1.2 (R017x.01.0.532.0-24184)
Avaya G430 Media Gateway: MGP	39.5.0
Avaya Aura® Media Server	7.8.0.333
Avaya Aura® Application Enablement Services	7.1.2 (7.1.2.0.0.3-0)
Avaya 9600 Series IP Deskphones: <ul style="list-style-type: none">• 9641G (H.323)• 9641 (H.323)	<ul style="list-style-type: none">• 6.6506• 6.6506
NextGen Centos Server <ul style="list-style-type: none">• AESMGR6K• LA-6000• VoISplus	7.4.1708 <ul style="list-style-type: none">• 1.0.9• 2.0-0b• 2.0-0b

5. Configure Avaya Aura® Communication Manager

This section provides the procedures for configuring Communication Manager. The procedures include the following areas:

- Verify Communication Manager License
- Administer AES and CTI link
- Administer Agent Stations
- Administer Agent IDs
- Disable Media Shuffling
- Administer IP Codec

5.1. Verify Communication Manager License

Log into the System Access Terminal (SAT) to verify that the Communication Manager license has proper permissions for features illustrated in these Application Notes. Use the **display system-parameters customer-options** command to verify that the **Computer Telephony Adjunct Links** customer option is set to **y** on **Page 4**. If this option is not set to **y**, then contact the Avaya sales team or business partner for a proper license file.

```
display system-parameters customer-options                                Page 4 of 12
                                OPTIONAL FEATURES

Abbreviated Dialing Enhanced List? y      Audible Message Waiting? y
Access Security Gateway (ASG)? n           Authorization Codes? y
Analog Trunk Incoming Call ID? y           CAS Branch? n
A/D Grp/Sys List Dialing Start at 01? y    CAS Main? n
Answer Supervision by Call Classifier? y    Change COR by FAC? n
ARS? y      Computer Telephony Adjunct Links? y
ARS/AAR Partitioning? y      Cvg Of Calls Redirected Off-net? y
ARS/AAR Dialing without FAC? n           DCS (Basic)? y
ASAI Link Core Capabilities? y           DCS Call Coverage? y
ASAI Link Plus Capabilities? y           DCS with Rerouting? y
Async. Transfer Mode (ATM) PNC? n
Async. Transfer Mode (ATM) Trunking? n    Digital Loss Plan Modification? y
ATM WAN Spare Processor? n               DS1 MSP? y
ATMS? y      DS1 Echo Cancellation? y
Attendant Vectoring? y
```

(NOTE: You must logoff & login to effect the permission changes.)

5.2. Administer AES and CTI Link

Enter the **change node-names ip procr** command. In the compliance-tested configuration, note the ip address of the Communication Manager with the node-name **procr** was utilized for connectivity to Avaya AES server.

change node-names ip procr		Page 1 of 2
IP NODE NAMES		
Name	IP Address	
procr	10.1.10.230	
procr6	::	

Enter the **change ip-services** command. On **Page 1**, configure the **Service Type** field to **AESVCS** and the **Enabled** field to **y**. The **Local Node** field should be set to the **procr**. During the compliance test, the default port was utilized in the **Local Port** field.

change ip-services		Page 1 of 4
IP SERVICES		
Service Type	Enabled	Local Node
AESVCS	y	procr

On **Page 4**, enter the hostname of the Avaya AES server in the **AE Services Server** field. The server name may be obtained by logging in to the Avaya AES server using Secure Shell (SSH) and running the **uname -a** command. Enter an alphanumeric password in the **Password** field and set the **Enabled** field to **y**. The same password will be configured on Avaya AES server in **Section 6.3**.

change ip-services		Page 4 of 4
AE Services Administration		
Server ID	AE Services Server	Password
1:		
2:	aes7x	xxxxxxxxxxxxxxxx

Add a CTI link using the **add cti-link n** command, where **n** is an available CTI link number. Enter an available extension number in the **Extension** field. Note that the CTI link number and extension number may vary. Enter **ADJ-IP** in the **Type** field, and a descriptive name in the **Name** field. Default values may be used in the remaining fields.

add cti-link 3		Page 1 of 3
CTI LINK		
CTI Link: 3		
Extension: 10093		
Type: ADJ-IP		
Name: TSAPI Service - AES7x		COR: 1

5.3. Administer Agent Stations

Modify each physical station used by the agents to allow the station to perform agent functions. Change the agent station using the **change station n** command, where **n** is the station extension number. Assigned agent login and logout buttons using abbreviated dialing for system, auto-in and aux-work etc., as required for agent stations.

Repeat this section for all agent stations in **Section 3**.

change station 10001		Page 4 of 5	
STATION			
SITE DATA			
Room:		Headset?	y
Jack:		Speaker?	n
Cable:		Mounting:	d
Floor:	#03-09/10	Cord Length:	0
Building:	Rutherford	Set Color:	blue
ABBREVIATED DIALING			
List1:	system	List2:	List3:
BUTTON ASSIGNMENTS			
1: call-appr	5: abrv-dial	List: 1	DC: 01
2: call-appr	6: abrv-dial	List: 1	DC: 02
3: call-appr	7: auto-in	Grp:	
4: call-park	8: aux-work	RC:	Grp:
voice-mail 10000			

5.4. Administer Agent IDs

Create agent IDs using the **add agent-loginID next** command. Enter the **Name** and **Password** for the agent ID.

Repeat this section for all agent stations in **Section 3**.

```
add agent-loginID 11001                                     Page 1 of 3
                                AGENT LOGINID

      Login ID: 11001                                         AAS? n
      Name: Agent #1                                         AUDIX? n
      TN: 1          Check skill TNs to match agent TN? n
      COR: 1
      Coverage Path:                                         LWC Reception: spe
      Security Code:                                         LWC Log External Calls? n
      Attribute:      AUDIX Name for Messaging:

                                LoginID for ISDN/SIP Display? n
                                Password:
                                Password (enter again):
                                Auto Answer: none
      AUX Agent Remains in LOA Queue: system                MIA Across Skills: system
      AUX Agent Considered Idle (MIA): system                ACW Agent Considered Idle: system
      Work Mode on Login: system                             Aux Work Reason Code Type: system
                                Logout Reason Code Type: system
                                Maximum time agent in ACW before logout (sec): system
                                Forced Agent Logout Time:      :
      WARNING: Agent must log in again before changes take effect
```

5.5. Disable Media Shuffling

Media shuffling is disabled to direct all voice traffic through media processors such as MGP, AAMS and Medpro boards where traffic is monitored for RTP. In the ip-network-region form of the agents, set the IP-IP Direct Audio to **no** for both **Intra-region** and **Inter-region**. Note the **Codec Set** used for the Deskphone which is **1** in the environment setup.

Repeat this for other ip-network-region where Deskphones utilized the media resources.

change ip-network-region 1		Page 1 of 20
IP NETWORK REGION		
Region: 1	NR Group: 1	
Location: 1	Authoritative Domain: sglab.com	
Name: Local	Stub Network Region: n	
MEDIA PARAMETERS		Intra-region IP-IP Direct Audio: no
Codec Set: 1		Inter-region IP-IP Direct Audio: no
UDP Port Min: 2048		IP Audio Hairpinning? n
UDP Port Max: 3999		
DIFFSERV/TOS PARAMETERS		
Call Control PHB Value: 46		
Audio PHB Value: 46		
Video PHB Value: 26		
802.1P/Q PARAMETERS		
Call Control 802.1p Priority: 6		
Audio 802.1p Priority: 6		
Video 802.1p Priority: 5		
AUDIO RESOURCE RESERVATION PARAMETERS		
H.323 IP ENDPOINTS		RSVP Enabled? n
H.323 Link Bounce Recovery? y		
Idle Traffic Interval (sec): 20		
Keep-Alive Interval (sec): 5		
Keep-Alive Count: 5		

5.6. Administer IP Codec

In the **IP Codec** form, set the first choice Audio Codec to **G.711MU** which is the codec supported by LA-6000.

change ip-codec-set 1				Page 1 of 2	
IP MEDIA PARAMETERS					
Codec Set: 1					
Audio		Silence		Frames	
Codec		Suppression		Per Pkt Size(ms)	
1:	G.711MU	n	2	20	
2:					
3:					
4:					
5:					
6:					
7:					
Media Encryption			Encrypted SRTP: best-effort		
1:	none				
2:					
3:					
4:					
5:					

6. Configure Avaya Aura® Application Enablement Services


This section provides the procedures for configuring AES. The procedures include the following areas:

- Launch OAM interface
- Verify license
- Administer Switch Connection
- Administer TSAPI link
- Administer H.323 gatekeeper
- Disable security database
- Restart TSAPI service
- Obtain Tlink name
- Administer NextGen user
- Administer CTI User permissions
- Enable TSAPI Service port

6.1. Launch OAM Interface

Access the OAM web-based interface by using the URL “https://ip-address” in an internet browser window, where “ip-address” is the ip address of the AES server.

The **Please login here** screen is displayed. Log in using the appropriate credentials.



The screenshot shows the Avaya Application Enablement Services Management Console login interface. At the top left is the Avaya logo. To its right, the text "Application Enablement Services" and "Management Console" is displayed. Below this is a thick red horizontal bar. In the center, there is a login box with the text "Please login here:" followed by "Username" and "Password" labels, each with a corresponding text input field. Below the input fields are two buttons: "Login" and "Reset". At the bottom of the page, another thick red horizontal bar is present, followed by the copyright notice: "Copyright © 2009-2016 Avaya Inc. All Rights Reserved."

The **Welcome to OAM** screen is displayed next.

The screenshot shows the Avaya Application Enablement Services Management Console. The top header includes the Avaya logo, the title "Application Enablement Services Management Console", and a welcome message with system details: "Welcome! User devconnect", "Last login: Thu May 24 16:14:34 2018 from 192.168.100.18", "Number of prior failed login attempts: 0", "HostName/IP: aes7x/10.1.10.70", "Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE", "SW Version: 7.1.2.0.0.3-0", "Server Date and Time: Thu May 24 16:41:01 SGT 2018", and "HA Status: Not Configured". A red navigation bar contains "Home", "Help", and "Logout". On the left, a sidebar lists menu items: AE Services, Communication Manager Interface, High Availability, Licensing, Maintenance, Networking, Security, Status, User Management, Utilities, and Help. The main content area is titled "Welcome to OAM" and contains a paragraph about the OAM Web's purpose, a bulleted list of administrative domains and their uses, and a note about administrator roles. The footer states "Copyright © 2009-2016 Avaya Inc. All Rights Reserved."

6.2. Verify License

Select **Licensing → WebLM Server Access** from the left pane of the home screen and note the **WebLM Server Address**. In this setup, it is the System Manager which host the WebLM server. Access the System Manager web-based interface by using the URL “https://ip-address/SMGR” in an internet browser window, where “ip-address” is the ip address of the System Manager. Log in with the appropriate credentials.

The screenshot shows the System Manager login page. On the left, a sidebar contains information about recommended access via FQDN, a link to "Go to central login for Single Sign-On", a note about IP address access, a list of cases where authentication might fail (first time login with "admin" account, expired/reset passwords), instructions to use the "Change Password" hyperlink, and a note about single sign-on between servers. The main area features a login form with "User ID:" and "Password:" labels, input fields, and "Log On" and "Cancel" buttons. A "Change Password" link is also present. At the bottom, a banner indicates "Supported Browsers: Internet Explorer 11.x or Firefox 48.0, 49.0 and 50.0."

From Home Page (not shown), go to **Services → Licenses**.

Select **Licensed products** → **APPL_ENAB** → **Application_Enablement** in the left pane to display the **Licensed Features** screen in the right pane. Scroll down the screen, and verify that there are sufficient licenses **TSAPI Simultaneous Users**, as shown below. Consult Avaya sales or business partner to obtain the license file.


Application Enablement (CTI) - Release: 7 - SID: 10503000
Standard License file

You are here: Licensed Products > Application_Enablement > View License Capacity

License installed on: August 11, 2017 6:42:55 AM +00:00

License File Host IDs: V1-FD-9E-A1-20-FC-01

Licensed Features

13 Items

Show
All
▼

Feature (License Keyword)	Expiration date	Licensed capacity
Device Media and Call Control VALUE_AES_DMCC_DMC	permanent	2500
AES ADVANCED LARGE SWITCH VALUE_AES_AEC_LARGE_ADVANCED	permanent	16
AES HA LARGE VALUE_AES_HA_LARGE	permanent	10
AES ADVANCED MEDIUM SWITCH VALUE_AES_AEC_MEDIUM_ADVANCED	permanent	16
Unified CC API Desktop Edition VALUE_AES_AEC_UNIFIED_CC_DESKTOP	permanent	2500
CVLAN ASAI VALUE_AES_CVLAN_ASAI	permanent	1
AES HA MEDIUM VALUE_AES_HA_MEDIUM	permanent	10
AES ADVANCED SMALL SWITCH VALUE_AES_AEC_SMALL_ADVANCED	permanent	16
DLG VALUE_AES_DLG	permanent	1
TSAPI Simultaneous Users VALUE_AES_TSAPI_USERS	permanent	2500
CVLAN Proprietary Links VALUE_AES_PROPRIETARY_LINKS	permanent	16

6.3. Administer Switch Connection

From the Home menu of AES, select **Communication Manager Interface** → **Switch Connections**. Enter a descriptive name for the switch connection and click **Add Connection**. In this configuration, **Duplex** is used.

The screenshot shows the Avaya Application Enablement Services Management Console. The top navigation bar includes 'Home | Help | Logout'. The left sidebar shows the 'Communication Manager Interface' menu with 'Switch Connections' selected. The main content area is titled 'Switch Connections' and contains a text input field with 'Duplex' and a red 'Add Connection' button. Below this is a table with columns: 'Connection Name', 'Processor Ethernet', 'Msg Period', and 'Number of Active Connections'.

The **Connection Details – Duplex** screen is displayed. For the **Switch Password** and **Confirm Switch Password** fields, enter the password that was administered in Communication Manager using the IP Services form in **Section 5.2**. Here we are using the **Processor Ethernet** as well for connection and the field needs to be checked. Click on **Apply** to affect changes.

The screenshot shows the 'Connection Details - Duplex' screen. The 'Switch Password' and 'Confirm Switch Password' fields are highlighted with red boxes. The 'Msg Period' is set to 30 minutes. The 'Provide AE Services certificate to switch' checkbox is checked. The 'Secure H323 Connection' checkbox is checked. The 'Processor Ethernet' checkbox is checked and highlighted with a red box. The 'Apply' button is highlighted with a red box.

The Switch Connections screen is displayed. Select the newly added switch connection name and click **Edit PE/CLAN IPs**.

Application Enablement Services
Management Console

Welcome: User devconnect
Last login: Thu May 24 16:14:34 2018 from 192.168.100.18
Number of prior failed login attempts: 0
HostName/IP: aes7x/10.1.10.70
Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE
SW Version: 7.1.2.0.0.3-0
Server Date and Time: Thu May 24 16:56:48 SGT 2018
HA Status: Not Configured

Communication Manager Interface | Switch Connections
Home | Help | Logout

AE Services
Communication Manager Interface
Switch Connections
Dial Plan
High Availability
Licensing
Maintenance

Switch Connections

Add Connection

Connection Name	Processor Ethernet	Msg Period	Number of Active Connections
<input checked="" type="radio"/> Duplex	Yes	30	1

Edit Connection
Edit PE/CLAN IPs
Edit H.323 Gatekeeper
Delete Connection
Survivability Hierarchy

On the **Edit Processor Ethernet IP – Duplex** screen, enter the host name or IP address of the PE/C-LAN used for AES connection. In this case, **10.1.10.230** is used, which corresponds to the **procr** address of the Communication Manager. Click **Add/Edit Name or IP**

Application Enablement Services
Management Console

Welcome: User devconnect
Last login: Thu May 24 16:14:34 2018 from 192.168.100.18
Number of prior failed login attempts: 0
HostName/IP: aes7x/10.1.10.70
Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE
SW Version: 7.1.2.0.0.3-0
Server Date and Time: Thu May 24 16:59:01 SGT 2018
HA Status: Not Configured

Communication Manager Interface | Switch Connections
Home | Help | Logout

AE Services
Communication Manager Interface
Switch Connections
Dial Plan

Edit Processor Ethernet IP - Duplex

Add/Edit Name or IP

Name or IP Address	Status
--------------------	--------

6.4. Administer TSAPI Link

To administer a TSAPI link, select **AE Services** → **TSAPI** → **TSAPI Links** from the left pane. Click **Add Link** on the right pane (not shown).

In the **Add TSAPI Links** screen, select the following values:

- **Link:** Select an available Link number from 1 to 16.
- **Switch Connection:** Administered switch connection in **Section 6.3**.
- **Switch CTI Link Number:** Corresponding CTI link number in **Section 5.2**.
- **ASAI Link Version:** Set to **8** for the latest version.
- **Security:** Select **Both** to allow for encrypted or unencrypted link.

Click **Apply Changes** to affect changes.

The screenshot displays the Avaya Application Enablement Services Management Console. The top header shows the Avaya logo, the title 'Application Enablement Services Management Console', and a welcome message for user 'devconnect'. The left sidebar contains a tree view with 'AE Services' expanded, showing options like CVLAN, DLG, DMCC, SMS, TSAPI (selected), and TWS. Under 'TSAPI', 'TSAPI Links' is selected. The main area is titled 'Edit TSAPI Links' and contains the following configuration fields:

- Link: 3
- Switch Connection: Duplex
- Switch CTI Link Number: 3
- ASAI Link Version: 8
- Security: Both

At the bottom of the configuration area are three buttons: 'Apply Changes' (highlighted with a red box), 'Cancel Changes', and 'Advanced Settings'.

6.5. Disable Security Database

Select **Security** → **Security Database** → **Control** from the left pane to display the **SDB Control for DMCC, TSAPI, JTAPI and Telephony Web Services** screen in the right pane. Clear the **Enable SDB for DMCC Service** and **Enable SDB for TSAPI Service, JTAPI and Telephony Web Services** if they are checked, and click **Apply Changes**.

The screenshot shows the Avaya Application Enablement Services Management Console. The left navigation pane has 'Security Database' and 'Control' highlighted. The main content area is titled 'SDB Control for DMCC, TSAPI, JTAPI and Telephony Web Services'. It contains two checkboxes: 'Enable SDB for DMCC Service' and 'Enable SDB for TSAPI Service, JTAPI and Telephony Web Services', both of which are unchecked. Below the checkboxes is an 'Apply Changes' button. The top right of the console displays system information: 'Welcome: User devconnect', 'Last login: Thu May 24 16:14:34 2018 from 192.168.100.18', 'Number of prior failed login attempts: 0', 'HostName/IP: aes7x/10.1.10.70', 'Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE', 'SW Version: 7.1.2.0.0.3-0', 'Server Date and Time: Thu May 24 17:10:54 SGT 2018', and 'HA Status: Not Configured'.

6.6. Restart TSAPI Service

Select **Maintenance** → **Service Controller** from the left pane to display the **Service Controller** screen in the right pane. Check the **TSAPI Service**, and click **Restart Service**.

The screenshot shows the Avaya Application Enablement Services Management Console. The left navigation pane has 'Maintenance' and 'Service Controller' highlighted. The main content area is titled 'Service Controller'. It contains a table with two columns: 'Service' and 'Controller Status'. The table lists several services, including ASAI Link Manager, DMCC Service, CVLAN Service, DLG Service, Transport Layer Service, and TSAPI Service. The 'TSAPI Service' row is highlighted, and its 'Controller Status' is 'Running'. Below the table is a note: 'For status on actual services, please use [Status and Control](#)'. At the bottom of the main content area are several buttons: 'Start', 'Stop', 'Restart Service' (highlighted), 'Restart AE Server', 'Restart Linux', and 'Restart Web Server'. The top right of the console displays system information: 'Welcome: User devconnect', 'Last login: Thu May 24 16:14:34 2018 from 192.168.100.18', 'Number of prior failed login attempts: 0', 'HostName/IP: aes7x/10.1.10.70', 'Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE', 'SW Version: 7.1.2.0.0.3-0', 'Server Date and Time: Thu May 24 17:15:08 SGT 2018', and 'HA Status: Not Configured'.

6.7. Obtain Tlink Name

Select **Security** → **Security Database** → **Tlinks** from the left pane. The **Tlinks** screen shows a listing of the Tlink names. A new Tlink name is automatically generated for the TSAPI service.

Locate the Tlink name associated with the relevant switch connection, which would use the name of the switch connection as part of the Tlink name. Make a note of the associated Tlink name, to be used later for configuring LA-6000.

In this case, the associated unencrypted Tlink name is **AVAYA#DUPLEX#CSTA#AES7X**, which is automatically assigned by the Avaya AES server. Note the use of the switch connection **Duplex** of **Section 5.3** as part of the Tlink name.

The screenshot displays the Avaya Application Enablement Services Management Console. The top header includes the Avaya logo, the title "Application Enablement Services Management Console", and a welcome message for user "devconnect" with system details. A red navigation bar contains "Security | Security Database | Tlinks" and links for "Home | Help | Logout". The left sidebar lists various services, with "Security" expanded to show "Security Database" and "Control". The main content area, titled "Tlinks", shows a "Tlink Name" section with two radio buttons. The first option, "AVAYA#DUPLEX#CSTA#AES7X", is selected and highlighted with a red box. The second option is "AVAYA#DUPLEX#CSTA-S#AES7X". A "Delete Tlink" button is located below the options.

6.8. Administer NextGen User

Select **User Management** → **User Admin** → **Add User** from the left pane to display the **Add User** screen in the right pane.

Enter desired values for **User Id**, **Common Name**, **Surname**, **User Password**, and **Confirm Password**. For **CT User**, select **Yes** from the drop-down list. Retain the default value in the remaining fields. Click **Apply** at the bottom of the screen (not shown below).

AVAYA

Application Enablement Services
Management Console

Welcome: User devconnect
Last login: Thu May 24 16:14:34 2018 from 192.168.100.18
Number of prior failed login attempts: 0
HostName/IP: aes7x/10.1.10.70
Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE
SW Version: 7.1.2.0.0.3-0
Server Date and Time: Thu May 24 17:22:38 SGT 2018
HA Status: Not Configured

User Management | User Admin | Add User

Home | Help | Logout

▶ AE Services

▶ Communication Manager

▶ Interface

▶ High Availability

▶ Licensing

▶ Maintenance

▶ Networking

▶ Security

▶ Status

▼ User Management

▶ Service Admin

▼ User Admin

▪ Add User

▪ Change User Password

▪ List All Users

▪ Modify Default Users

▪ Search Users

▶ Utilities

▶ Help

Add User

• User Password is required.
• Confirm Password is required.

Fields marked with * can not be empty.

* User Idnextgen

* Common Namenext

* Surnamengtgen

* User Password*****

* Confirm Password*****

Admin Note

Avaya RoleNone

Business Category

Car License

CM Home


Css Home

CT UserYes

Department Number

6.9. Administer CTI User Permissions

Select **Security** → **Security Database** → **CTI Users** → **List All Users** from the AES Management Console Home menu. Select the User ID created in **Section 5.9** and click **Edit**.



Application Enablement Services
Management Console

Welcome: User devconnect
Last login: Thu May 24 16:14:34 2018 from 192.168.100.18
Number of prior failed login attempts: 0
HostName/IP: aes7x/10.1.10.70
Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE
SW Version: 7.1.2.0.0.3-0
Server Date and Time: Thu May 24 17:29:29 SGT 2018
HA Status: Not Configured

Security | Security Database | CTI Users | List All Users

Home | Help | Logout

AE Services

Communication Manager Interface

High Availability

Licensing

Maintenance

Networking

Security

Account Management

Audit

Certificate Management

Enterprise Directory

Host AA

PAM

Security Database

Control

CTI Users

List All Users

Search Users

CTI Users

User ID	Common Name	Worktop Name	Device ID
<input type="radio"/> CRTADM	AMC	NONE	NONE
<input checked="" type="radio"/> nextgen	nextgen	NONE	NONE
<input type="radio"/> psadmin	psadmin	NONE	NONE

EditList All

Check the **Unrestricted Access** box. Click **Apply Changes**.

Edit CTI User

User Profile:

User ID
Common Name
Worktop Name
Unrestricted Access

nextgen
nextgen
NONE ▾
☒

Call and Device Control:

Call Origination/Termination and Device Status

None ▾

Call and Device Monitoring:

Device Monitoring
Calls On A Device Monitoring
Call Monitoring

None ▾
None ▾
☐

Routing Control:

Allow Routing on Listed Devices

None ▾

Apply Changes

Cancel Changes

6.10. Enable TSAPI Service Port

Select **Networking** → **Ports** from the left pane to display the **Ports** screen in the right pane.

In the **TSAPI Ports** section, select the radio button under the **Enabled** column, as shown below. Scroll down and click **Apply Changes** (not shown).

The screenshot shows the Avaya Application Enablement Services Management Console. The left sidebar contains a navigation menu with the following items: AE Services, Communication Manager Interface, High Availability, Licensing, Maintenance, Networking (expanded), AE Service IP (Local IP), Network Configure, Ports (highlighted with a red box), TCP/TLS Settings, Security, Status, User Management, Utilities, and Help. The main content area is titled 'Ports' and displays configuration for CVLAN Ports and TSAPI Ports. The TSAPI Ports section has a red box around the 'Enabled' radio button for the 'TSAPI Service Port'.

CVLAN Ports		Enabled	Disabled
Unencrypted TCP Port	9999	<input checked="" type="radio"/>	<input type="radio"/>
Encrypted TCP Port	9998	<input checked="" type="radio"/>	<input type="radio"/>

DLG Port		TCP Port	5678
TSAPI Ports			
TSAPI Service Port	450	<input checked="" type="radio"/>	<input type="radio"/>
Local TLINK Ports			
TCP Port Min	1024		
TCP Port Max	1039		
Unencrypted TLINK Ports			
TCP Port Min	1050		
TCP Port Max	1065		
Encrypted TLINK Ports			
TCP Port Min	1066		
TCP Port Max	1081		

7. Configure NextGen LA-6000

This section provides the procedures for configuring NextGen LA-6000. The AESMGR6K module on the LA-6000 server communicates with AES from the administrative ethernet port and the other ethernet port connects to the monitoring port of data switch, which mirror ports of Media Processors. Ensure that the monitoring ethernet ports are in promiscuous mode and all traffic is allowed on virtualized host server port. The VoISplus stores the call recording which is normally set up in a separate server. But in this compliance testing, the VoISplus function is installed on the same server with the LA-6000.

The procedures include the following areas:

- Administer Telephony TSAPI
- Administer Media Processor list and Monitor Port
- Administer Agent Station's IP address list
- Restart Services

The configuration of LA-6000 is performed by NextGen services engineers. The procedural steps are presented in these Application Notes for informational purposes. These Application Notes assume that the configurations of a site, server sizing, appropriate license and storage volumes are all in place and will not be covered. Refer to [3] in the reference section for the installation instructions.

7.1. Administer Telephony TSAPI

Log in to the LA-6000 console with the appropriate user login. Navigate to the `../NXS/conf` directory to locate the **La6Avaya.ini** file and view the file with vi editor. Verify the parameter **AesServerName** is set the same as Tlink name in **Section 6.7**. Verify the **LinkUserID** and **LinkPassword** is set as configured in **Section 6.8**. Check also that **AvayaEnable** is set to “1”.

```
LA6IP1 = "10.1.10.123"
AesServerName = "AVAYA#DUPLEX#CSTA#AES7X"
LinkUserID    = "nextgen"
LinkPassword  = "nextgen6000"
HoldSw = "1"    /* 1:Stop Recording while call-holding 0:Continue recording while
call-holding / Default:0
AvayaEnable = "1"
```

7.2. Administer Media Processor List and Monitor Port

On the console, navigate to the `../NXS/conf` directory to locate the **vliuser.ini** file and view the file with vi editor. Locate the parameter **NorthGWList** and verify the Media Processors' ip address. The Media Processor ip address could be a board on the Avaya G650 Media Gateway or the AAMS or the Media Gateway Processor (MGP) of Avaya G430 and G450 Media Gateway. In this compliance testing, only the ip address of AAMS is added where RTP stream of transcoded.

```
F0_Port::31060
V0_VID::0
Operation::0
@recorder
Idx_Text1::0
Idx_Text2::0
Idx_Text3::0
Idx_Text4::0
PetName::la6k
Divsz_Type::1
BKUP_Retention::-1
NorthGWList::10.1.10.13
PowerRestart::1
BKUP_Arrange_Time::02:00
BlackNumberList::
TransAlarm::0
Idx_Number1::0
Idx_Number2::0
Idx_Agent::0
Idx_DTMF::0
Divsz_Minutes::60
Idx_Extension::0
SouthGWList::
@ipcap0
NICName::ens192
F0_Netaddr::0.0.0.0
F0_Netmask::0
F0_Trans::2
F0_Network::1
V0_VID::0
Operation::1
```

On the lower portion of the vliuser.ini file on the previous page, locate the parameter @ipcap0. This is set to the name of the monitoring port which in this environment is ens192. This name can be identified through the *ifconfig* command which list the ethernet ports of the server.

7.3. Administer Agent Station's IP address list

On the console, navigate to the ../NXS/conf directory to locate the LaIdTable1.csv file and vi the file. Verify the ip address of the corresponding deskphones extension is correct.

```
10001,10.1.10.169
10002,10.1.10.180
10006,10.1.10.153
```

7.4. Restart Services

On the console, navigate to the ../NXS/bin directory. Execute the following nxs.sh command to restart the NXS service. Note that the user name is masked out for security reason.

```
[                ]$ ./nxs.sh stop
Stopping hamanager (PID:6915) ...
hamanager stopped.

[                ]$ ./nxs.sh start
Starting hamanager ...
[                ]$ Setting up watches.
Watches established.
Started logobserver.
start vli successfully.
AesManager6K started.
```

8. Verification Steps

This section provides the tests that can be performed to verify proper configuration of Avaya Aura® Communication Manager, Avaya Aura® Application Enablement Services, and NextGen LA-6000.

8.1. Verify Avaya Aura® Communication Manager


On Communication Manager, verify the status of the administered CTI link by using the **status aesvcs cti-link** command. Verify that the **Service State** is **established** for the CTI link number administered in **Section 5.3**, as shown below.

```
status aesvcs cti-link
```

AE SERVICES CTI LINK STATUS						
CTI Link	Version	Mnt Busy	AE Services Server	Service State	Msgs Sent	Msgs Rcvd
3	8	no	aes7x	established	194	194

8.2. Verify Avaya Aura® Application Enablement Services

For AES, verify the status of the TSAPI link by selecting the **Status → Status and Control → TSAPI Service Summary** from the left pane. The **TSAPI Link Details** screen is displayed. On the right pane of the screen. Verify that the **Status** column shows a **Talking** session with the nextgen user name from **Section 6.9**, and that the **State Devices** column shows **Online**. Click on the **User Status** below.



Application Enablement Services
Management Console

Welcome: User devconnect
Last login: Thu May 24 16:40:45 2018 from 192.168.100.18
Number of prior failed login attempts: 0
HostName/IP: aes7x/10.1.10.70
Server Offer Type: VIRTUAL_APPLIANCE_ON_VMWARE
SW Version: 7.1.2.0.0.3-0
Server Date and Time: Thu May 24 18:04:36 SGT 2018
HA Status: Not Configured

Status | Status and Control | TSAPI Service SummaryHome | Help | Logout

AE Services

Communication Manager Interface

High Availability

Licensing

Maintenance

Networking

Security

Status

Alarm Viewer

Log Manager

Logs

Status and Control

CVLAN Service Summary

DLG Services Summary

DMCC Service Summary

Switch Conn Summary

TSAPI Service Summary

TSAPI Link Details

☐ Enable page refresh every 60 seconds

Link	Switch Name	Switch CTI Link ID	Status	Since	State	Switch Version	Associations	Msgs to Switch	Msgs from Switch	Msgs Period
3	Duplex	3	Talking	Mon May 21 15:37:48 2018	Online	17	6	195	195	30

Online Offline

For service-wide information, choose one of the following:

TSAPI Service Status TLink Status User Status

Verify the nextgen user is listed under the **Open Streams** with the Tlink Name in **Section 5.13**.

CTI User Status

☐ Enable page refresh every seconds

CTI Users

Open Streams 1
Closed Streams 12

Open Streams

Name	Time Opened	Time Closed	Tlink Name
nextgen	Thu 24 May 2018 02:45:34 PM +08		AVAYA#DUPLEX#CSTA#AES7X

8.3. Verify NextGen LA-6000

Log in to the LA-6000 server with an appropriate login to verify TSAPI messages are received. Change directory to /home/<user>/NXS/log and type the command “tail -f La6Avaya.log”. Verify the messages “*** Health Check OK! ***” is shown and repeatedly displayed.

```
2018/05/24 17:53:16.031079
2018/05/24 17:53:16.031144 *** Health Check OK! ***
2018/05/24 17:53:26.026613
2018/05/24 17:53:26.026676 *** Health Check OK! ***
2018/05/24 17:53:36.041795
2018/05/24 17:53:36.041862 *** Health Check OK! ***
2018/05/24 17:53:46.006140
2018/05/24 17:53:46.006208 *** Health Check OK! ***
2018/05/24 17:53:56.028176
2018/05/24 17:53:56.028240 *** Health Check OK! ***
```

Make an inbound call to any of the agent. Verify the TSAPI monitoring messages are received from the logs.

```
2018/05/18 09:16:04.054393 [CSTA_DELIVERED]
2018/05/18 09:16:04.054426 Monitor Extension: 10001
2018/05/18 09:16:04.054457 Call Status: CS_ALERTING
2018/05/18 09:16:04.054485 <<CallInfo>>
2018/05/18 09:16:04.054514 CallID: 397
2018/05/18 09:16:04.054544 CallingDevice: 10006
2018/05/18 09:16:04.054573 CalledDevice: 10001
2018/05/18 09:16:04.054602 UCID: 00001003971526606160
2018/05/18 09:16:04.054632 TrunkGroup:
2018/05/18 09:16:04.054661 TrunkMember:
2018/05/18 09:16:04.054689 Direction: 2
2018/05/18 09:16:04.054718 CallingExtensionNo:
2018/05/18 09:16:04.054747 CalledExtensionNo: 10001
2018/05/18 09:16:04.054776 calls count: 0
2018/05/18 09:16:04.054905 [Incoming in]-10001 : Dest:10006 Self:10001
TerminalIP:10.1.10.169
2018/05/18 09:16:06.000425
2018/05/18 09:16:06.000485 *** Health Check OK! ***
2018/05/18 09:16:07.801720
2018/05/18 09:16:07.801790 [CSTA_CONNECTION_CLEARED]
2018/05/18 09:16:07.801823 Monitor Extension: 10001
```

```

2018/05/18 09:16:07.801854 Call Status: CS_ALERTING
2018/05/18 09:16:07.801922 <<CallInfo>>
2018/05/18 09:16:07.801959 CallID: 397
2018/05/18 09:16:07.801990 CallingDevice: 10006
2018/05/18 09:16:07.802019 CalledDevice: 10001
2018/05/18 09:16:07.802048 UCID: 00001003971526606160
2018/05/18 09:16:07.802078 TrunkGroup:
2018/05/18 09:16:07.802107 TrunkMember:
2018/05/18 09:16:07.802135 Direction: 2
2018/05/18 09:16:07.802164 CallingExtensionNo:
2018/05/18 09:16:07.802192 CalledExtensionNo: 10001
2018/05/18 09:16:07.802221 calls count: 0
2018/05/18 09:16:07.844906
2018/05/18 09:16:07.844952 [CSTA_CONNECTION_CLEARED]
2018/05/18 09:16:07.844984 Monitor Extension: 10001
2018/05/18 09:16:07.845014 Call Status: CS_NULL
2018/05/18 09:16:07.845043 <<CallInfo>>
2018/05/18 09:16:07.845073 CallID: 397
2018/05/18 09:16:07.845102 CallingDevice: 10006
2018/05/18 09:16:07.845131 CalledDevice: 10001
2018/05/18 09:16:07.845159 UCID: 00001003971526606160
2018/05/18 09:16:07.845189 TrunkGroup:
2018/05/18 09:16:07.845218 TrunkMember:
2018/05/18 09:16:07.845246 Direction: 2
2018/05/18 09:16:07.845275 CallingExtensionNo:
2018/05/18 09:16:07.845332 calls count: 0
2018/05/18 09:16:16.014822
2018/05/18 09:16:16.014906 *** Health Check OK! ***
2018/05/18 09:16:17.438397
2018/05/18 09:16:17.438464 [CSTA_DELIVERED]
2018/05/18 09:16:17.438497 Monitor Extension: 10001
2018/05/18 09:16:17.438527 Call Status: CS_ALERTING
2018/05/18 09:16:17.438556 <<CallInfo>>
2018/05/18 09:16:17.438585 CallID: 398
2018/05/18 09:16:17.438615 CallingDevice: 10006
2018/05/18 09:16:17.438645 CalledDevice: 10001
2018/05/18 09:16:17.438674 UCID: 00001003981526606176
2018/05/18 09:16:17.438704 TrunkGroup:
2018/05/18 09:16:17.438732 TrunkMember:
2018/05/18 09:16:17.438761 Direction: 2
2018/05/18 09:16:17.438790 CallingExtensionNo:
2018/05/18 09:16:17.438819 CalledExtensionNo: 10001
2018/05/18 09:16:17.438849 calls count: 0
2018/05/18 09:16:17.438982 [Incoming in]-10001 : Dest:10006 Self:10001
TerminalIP:10.1.10.169
2018/05/18 09:16:21.331049
2018/05/18 09:16:21.331111 [CSTA_ESTABLISHED]
2018/05/18 09:16:21.331144 Monitor Extension: 10001
2018/05/18 09:16:21.331174 Call Status: CS_CONNECT
2018/05/18 09:16:21.331203 <<CallInfo>>
2018/05/18 09:16:21.331232 CallID: 398
2018/05/18 09:16:21.331262 CallingDevice: 10006
2018/05/18 09:16:21.331291 CalledDevice: 10001
2018/05/18 09:16:21.331321 UCID: 00001003981526606176
2018/05/18 09:16:21.331350 TrunkGroup:
2018/05/18 09:16:21.331379 TrunkMember:
2018/05/18 09:16:21.331407 Direction: 2
2018/05/18 09:16:21.331435 CallingExtensionNo:
2018/05/18 09:16:21.331464 CalledExtensionNo: 10001
2018/05/18 09:16:21.331502 calls count: 1
2018/05/18 09:16:21.333492 [Answer]-10001 : Rec start Dest:10006 Self:10001
TerminalIP:10.1.10.169

```

```

2018/05/18 09:16:21.333536 Rec-ID:2
2018/05/18 09:16:21.424385
2018/05/18 09:16:21.424442 QueryDeviceInfo 10001
2018/05/18 09:16:21.424483 AgentID not found : 10001
2018/05/18 09:16:26.035095
2018/05/18 09:16:26.035164 *** Health Check OK! ***
2018/05/18 09:16:33.525265
2018/05/18 09:16:33.525338 [CSTA_CONNECTION_CLEARED]
2018/05/18 09:16:33.525379 Monitor Extension: 10001
2018/05/18 09:16:33.525411 Call Status: CS_NULL
2018/05/18 09:16:33.525454 <<CallInfo>>
2018/05/18 09:16:33.525489 CallID: 398
2018/05/18 09:16:33.525522 CallingDevice: 10006
2018/05/18 09:16:33.525568 CalledDevice: 10001
2018/05/18 09:16:33.525601 UCID: 00001003981526606176
2018/05/18 09:16:33.525642 TrunkGroup:
2018/05/18 09:16:33.525681 TrunkMember:
2018/05/18 09:16:33.525712 Direction: 2
2018/05/18 09:16:33.525753 CallingExtensionNo:
2018/05/18 09:16:33.525791 CalledExtensionNo: 10001
2018/05/18 09:16:33.525822 calls count: 1
2018/05/18 09:16:33.526433 [On Hook]-10001 : Rec stop TerminalIP:10.1.10.169
2018/05/18 09:16:33.526477 Rec-ID:2

```

From a PC, access the call recordings from the web-based interface by using the URL “http://ip-address” in an internet browser window, where “ip-address” is the ip address of the LA-6000 server. Normally, this is the ip address of the VoISplus server where call recordings are stored. But in our test environment, this storage server is residing on the same server as LA-6000.

Log on using appropriate credentials.



In the screen below, the inbound call to the agent call recordings can be found by search function using the appropriate criteria say the date and time.

The screenshot shows the VoIS+ search interface. The search criteria are as follows:

- 開始日時: 2018/05/24 00:00:00
- 終了日時: 2018/05/24 23:59:59
- 通話時間: 秒 (selected), 以上
- 相手先電話番号: (empty)
- 自社電話番号: (empty)
- 宛着信: (checked)
- 内線番号: (empty)
- 回線名: (empty)
- グループ: (empty)
- 対象機器: (empty)
- ユニットNo: (empty)
- チャンネルNo: (empty)
- DTMF: (empty)
- コメント: (empty)
- マーク: (empty)

Buttons: 検索, エクスポート, エクスポート形式 (CSV selected, Excel), クリア

The following call recording was made on the Ext 10001 using Agent ID 11001. Double click on the **speaker** icon.

The screenshot shows the search results table. The table has the following columns: 録音ID, 操作, マーク, 開始日時, 終了日時, 通話時間, 相手先電話番号, 自社電話番号, 宛着信, 内線番号, 回線名, グループ, コメント. The table contains 10 rows of data. Row 206 is highlighted with a red border.

録音ID	操作	マーク	開始日時	終了日時	通話時間	相手先電話番号	自社電話番号	宛着信	内線番号	回線名	グループ	コメント
202	[Speaker Icon]	☆	2018/05/23 10:09:04	2018/05/23 10:09:16	00:00:12	60000	10003	着信	10003		デフォルトグループ	
203	[Speaker Icon]	☆	2018/05/23 14:29:21	2018/05/23 14:29:30	00:00:09	60000	10003	着信	10003		デフォルトグループ	
204	[Speaker Icon]	☆	2018/05/23 14:49:14	2018/05/23 14:49:23	00:00:09	60000	10003	着信	10003		デフォルトグループ	
205	[Speaker Icon]	☆	2018/05/23 16:14:05	2018/05/23 16:14:15	00:00:10	60000	10007	着信	10007		デフォルトグループ	
206	[Speaker Icon]	☆	2018/05/23 16:22:29	2018/05/23 16:22:36	00:00:07	60000	11001	着信	10001	11001	デフォルトグループ	
207	[Speaker Icon]	☆	2018/05/23 16:33:34	2018/05/23 16:33:38	00:00:04	60000	11001	着信	10001	11001	デフォルトグループ	
208	[Speaker Icon]	☆	2018/05/23 16:40:07	2018/05/23 16:40:09	00:00:02	60000	11001	着信	10001	11001	デフォルトグループ	
209	[Speaker Icon]	☆	2018/05/23 16:49:24	2018/05/23 16:49:32	00:00:08	60000	11001	着信	10001	11001	デフォルトグループ	
210	[Speaker Icon]	☆	2018/05/23 16:53:35	2018/05/23 16:53:37	00:00:02	60000	11001	着信	10001	11001	デフォルトグループ	

1 - 10 件目 / 全11件

Verify the voice recording could be played back from the browser. Only IE and Chrome browsers are supported for online playback.

通話データの再生

録音ID	206
マーク	☆
開始日時	2018/05/23 16:22:29
終了日時	2018/05/23 16:22:36
通話時間	00:00:07
相手先電話番号	60000
自社電話番号	11001
発着信	着信
内線番号	10001
回線名	11001

波形表示

00:00:00 00:00:00 00:00:07

◀ -10秒 ▶ || ◻ +10秒 ▶ 🔊

ノイズキャンセル OFF 再生速度 1.0 倍速

閉じる

9. Conclusion

These Application Notes describe the configuration steps required for NextGen LA-6000 to successfully interoperate with Avaya Aura® Communication Manager 7.1 using Avaya Aura® Application Enablement Services 7.1 for VoIP call recording. All feature and serviceability test cases were completed.

10. Additional References

This section references the Avaya documentation that is relevant to these Application Notes.

The following Avaya product documentation can be found at <http://support.avaya.com>.

[1] *Administering Avaya Aura® Communication Manager*, Issue 5, Release 7.1.2, Feb 2018.

[2] *Avaya Aura® Application Enablement Services Documentation Library*, Release 7.1.2, December 2017.

The following product documentation can be obtained from NextGen.

[3] *LA-6000 Installation/Administration User's Guide*, Version 2.0

©2018 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at devconnect@avaya.com.