Avaya Solution & Interoperability Test Lab

Application Notes for Avaya Aura® Communication Manager 8.1, Avaya Aura® Session Manager 8.1, Avaya Experience Portal 8.0, and Avaya Session Border Controller for Enterprise 8.1 with Verizon Business IP Contact Center Services Suite – Issue 1.0

Abstract

These Application Notes describe a sample configuration of Avaya Aura® Communication Manager 8.1, Avaya Aura® Session Manager 8.1, Avaya Experience Portal 8.0, and Avaya Session Border Controller for Enterprise 8.1 with Verizon Business IP Contact Center (IPCC) Services suite. The Verizon Business IPCC Services suite includes the IP Toll Free VoIP Inbound and IP-IVR SIP trunk service offers. This service suite provides toll free inbound calling via standards-based SIP trunks as well as re-routing of inbound toll-free calls to alternate destinations based upon SIP messages (i.e., REFER) generated by Communication Manager. The Communication Manager Network Call Redirection (NCR) and SIP User-to-User Information (UUI) features can be utilized together to transmit UUI within SIP signaling messages to alternate destinations via the Verizon network. These Application Notes update previously published Application Notes with newer versions of Communication Manager, Session Manager, and Avaya Session Border Controller for Enterprise.

Readers should pay attention to **Section 2**, in particular the scope of testing as outlined in **Section 2.1** as well as any observations noted in **Section 2.2**, to ensure that their own use cases are adequately covered by this scope and results.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted in the Avaya Solution & Interoperability Test Lab, utilizing a Verizon Business Private IP (PIP) circuit connection to the production Verizon Business IPCC Services.

©2021 Avaya Inc. All Rights Reserved.

Table of Contents

1. Introduction 5
2. General Test Approach and Test Results 6
2.1. Interoperability Compliance Testing 6
2.2. Test Results 8
2.3. SIP Header Removal 9
2.4. Support 9
2.4.1 Avaya 9
2.4.2 Verizon 9
3. Reference Configuration 10
3.1. History Info and Diversion Headers 11
3.2. Call Flows – Avaya Aura® Communication Manager 12
3.2.1 Inbound IP Toll Free Call with no Network Call Redirection 12
3.2.2 Inbound IP Toll Free Call with Post-Answer Network Call Redirection 13
3.2.3 Inbound IP Toll Free Call with Unsuccessful Network Call Redirection 14
3.3. Call Flows – Avaya Experience Portal 15
3.3.1 Inbound IP Toll Free Call handled by Avaya Experience Portal 15
3.3.2 Inbound IP Toll Free Call redirected to Avaya Aura® Communication Manager 16
3.3.3 Inbound IP Toll Free Call redirected to PSTN number 17
4. Equipment and Software Validated 18
5. Configure Avaya Aura® Communication Manager 19
5.1. Verify Licensed Features 19
5.2. System-Parameters Features 21
5.3. Dial Plan 22
5.4. Node Names 22
5.5. Processor Ethernet Configuration 23
5.6. IP Codec Sets 24
5.6.1 Codecs for IP Network Region 1 (calls within the CPE) 24
5.6.2 Codecs for IP Network Region 2 (calls from Verizon) 25
5.7. Network Regions 26
5.7.1 IP Network Region 1 – Local CPE Region 26
5.7.2 IP Network Region 2 – Verizon Trunk Region 27
5.8. SIP Trunks 28
5.8.1 SIP Trunk for Inbound Verizon calls 28
5.8.2 Local SIP Trunk (Avaya SIP Telephone and Messaging Access) 32
5.9. Contact Center Configuration 33
5.9.1 Announcements 33
5.9.2 Post-Answer Redirection to a PSTN Destination 33
5.9.3 Post-Answer Redirection With UUI to a SIP Destination 34
5.9.4 ACD Configuration for Call Queued for Handling by Agent 36
5.10. Public Numbering 39
5.11. Private Numbering 40
5.12. Route Pattern for Calls within the CPE 41
5.13. Automatic Alternate Routing (AAR) Dialing 41
5.14. Avaya G430 Media Gateway Provisioning 42
5.15. Avaya Aura® Media Server Provisioning 43

©2021 Avaya Inc. All Rights Reserved.

5.16. Save Translations 44
5.17. Verify TLS Certificates – Communication Manager 45
6. Configure Avaya Aura® Session Manager 46
6.1. System Manager Login and Navigation 47
6.2. SIP Domain 48
6.3. Locations 48
6.3.1 Main Location 48
6.3.2 Common-SBCs Location 49
6.4. Configure Adaptations 50
6.4.1 Adaptation for Avaya Aura® Communication Manager Extensions 50
6.4.2 Adaptation for the Verizon Business IPCC Services 52
6.5. SIP Entities 52
6.5.1 Avaya Aura® Session Manager SIP Entity 53
6.5.2 Avaya Aura® Communication Manager SIP Entity – Public Trunk 55
6.5.3 Avaya Aura® Communication Manager SIP Entity – Local Trunk 56
6.5.4 Avaya Session Border Controller for Enterprise SIP Entity 56
6.5.5 Avaya Messaging SIP Entity 56
6.5.6 Avaya Experience Portal SIP Entity 56
6.6. Entity Links 57
6.6.1 Entity Link to Avaya Aura® Communication Manager – Public Trunk 57
6.6.2 Entity Link to Avaya Aura® Communication Manager – Local Trunk 57
6.6.3 Entity Link for the Verizon Business IPCC Services via the Avaya SBCE 58
6.6.4 Entity Link to Avaya Messaging 58
6.6.5 Entity Link to Avaya Experience Portal 58
6.7. Time Ranges 58
6.8. Routing Policies 59
6.8.1 Routing Policy for Verizon Routing to Avaya Aura® Communication Manager 59
6.8.2 Routing Policy for Inbound Routing to Avaya Messaging 60
6.8.3 Routing Policy for Inbound Calls to Experience Portal 60
6.9. Dial Patterns 61
6.10. Verify TLS Certificates – Session Manager 64
7. Avaya Experience Portal 66
7.1. Background 66
7.2. Logging In and Licensing 67
7.3. Verify TLS Certificates – Experience Portal 68
7.4. VoIP Connection 69
7.5. Speech Servers 70
7.6. Application References 71
7.7. MPP Servers and VoIP Settings 72
7.8. Configuring RFC2833 Event Value Offered by Experience Portal 74
8. Configure Avaya Session Border Controller for Enterprise 75
8.1. Device Management – Status 76
8.2. TLS Management 77
8.2.1 Verify TLS Certificates – Avaya Session Border Controller for Enterprise 77
8.2.2 Server Profiles 78
8.2.3 Client Profiles 79

©2021 Avaya Inc. All Rights Reserved.

8.3. Network Management 80
8.4. Media Interfaces 81
8.5. Signaling Interfaces 82
8.6. Server Interworking Profiles 83
8.6.1 Server Interworking Profile – Enterprise 83
8.6.2 Server Interworking Profile – Verizon 84
8.7. Signaling Manipulation 85
8.8. SIP Server Profiles 86
8.8.1 SIP Server Profile – Session Manager 86
8.8.2 SIP Server Profile – Verizon 88
8.9. Routing Profiles 90
8.9.1 Routing Profile – Session Manager 90
8.9.2 Routing Profile – Verizon 91
8.10. Topology Hiding Profiles 92
8.10.1 Topology Hiding – Enterprise 92
8.10.2 Topology Hiding – Verizon 93
8.11. Application Rules 94
8.12. Media Rules 95
8.12.1 Enterprise – Media Rule 95
8.12.2 Verizon – Media Rule 97
8.13. Signaling Rules 98
8.13.1 Signaling Rule - Enterprise 98
8.13.2 Signaling Rule - Verizon 99
8.14. Endpoint Policy Groups 99
8.14.1 Endpoint Policy Group – Enterprise 99
8.14.2 Endpoint Policy Groups – Verizon 100
8.15. Endpoint Flows – Server Flows 101
8.15.1 Server Flow – Enterprise 101
8.15.2 Server Flow – Verizon 102
9. Verizon Business IPCC Services Suite Configuration 103
9.1. Service Access Information 103
10. Verification Steps 104
10.1. Avaya Aura® Communication Manager Verifications 104
10.1.1 Example Incoming Call from PSTN via Verizon IPCC to Telephone 104
10.1.2 Example Incoming Call Referred via Call Vector to PSTN Destination 107
10.2. Avaya Aura® Session Manager Verification 109
10.3. Avaya Session Border Controller for Enterprise Verification 111
10.3.1 Incidents 111
10.3.2 Server Status 112
10.3.3 Diagnostics 113
10.3.4 Tracing 114
11. Conclusion 115
12. Additional References 116
12.1. Avaya 116
12.2. Verizon Business 116
13. Appendix A – Avaya Session Border Controller for Enterprise – Refer Handling 117

©2021 Avaya Inc. All Rights Reserved.

1. Introduction

These Application Notes describe a sample configuration of Avaya Aura® Communication Manager 8.1, Avaya Aura® Session Manager 8.1, Avaya Experience Portal 8.0, and Avaya Session Border Controller for Enterprise 8.0 with Verizon Business IP Contact Center (IPCC) Services suite. The Verizon Business IPCC Services suite includes the IP Toll Free VoIP Inbound and IP-IVR SIP trunk service offers. This service suite provides toll free inbound calling via standards-based SIP trunks as well as re-routing of inbound toll-free calls to alternate destinations based upon SIP messages (i.e., REFER) generated by Experience Portal or Communication Manager. The Communication Manager Network Call Redirection (NCR) and SIP User-to-User Information (UUI) features can be utilized together to transmit UUI within SIP signaling messages to alternate destinations via the Verizon network. These Application Notes update previously published Application Notes [VZ-IPCC] with newer versions of Session Manager, Communication Manager, and Avaya Session Border Controller for Enterprise.

In the sample configuration, an Avaya Session Border Controller for Enterprise (Avaya SBCE) is used as an edge device between the Avaya CPE and Verizon Business. The Avaya SBCE performs SIP header manipulation and provides topology hiding to convert the private Avaya CPE IP addressing to IP addressing or domains appropriate for the Verizon access method. Session Manager is used as the Avaya SIP trunking "hub" connecting to Communication Manager, the Avaya SBCE, and other applications.

The Verizon Business IPCC Services suite described in these Application Notes is designed for business customers. The suite provides inbound toll-free service via standards-based SIP trunks. Using SIP Network Call Redirection (NCR), trunk-to-trunk connections of certain inbound calls at Communication Manager can be avoided by requesting that the Verizon network transfer the inbound caller to an alternate destination. In addition, the Communication Manager SIP User-to-User Information (UUI) feature can be utilized with the SIP NCR feature to transmit UUI within SIP signaling messages to alternate destinations. This capability allows the service to transmit a limited amount of call-related data between call centers to enhance customer service and increase call center efficiency. Examples of UUI data might include a customer account number obtained during a database query or the best service routing data exchanged between sites using Communication Manager.

Verizon Business IPCC Services suite is a portfolio of IP Contact Center (IPCC) interaction services that includes VoIP Inbound and IP Interactive Voice Response (IP-IVR). Access to these features may use Internet Dedicated Access (IDA) or Private IP (PIP). PIP was used for the sample configuration described in these Application Notes. VoIP Inbound is the base service offering that offers core call routing and termination features. IP-IVR is an enhanced service offering that includes features such as menu-routing, custom transfer, and additional media capabilities.

For more information on the Verizon Business IP Contact Center service, visit https://enterprise.verizon.com/products/customer-experience-services/transport-and-intelligent-routing/ip-contact-center/

©2021 Avaya Inc. All Rights Reserved.

2. General Test Approach and Test Results

The test approach was manual testing of inbound and referred calls using the Verizon Business IPCC Services on a production Verizon PIP access circuit, as shown in **Figure 1**. Testing was successful. Test observations or limitations are described in **Section 2.2**.

See **Section 3.2** for an overview of key call flows and **Section 10** for detailed verifications and traces illustrating key call flows.

DevConnect Compliance Testing is conducted jointly by Avaya and DevConnect members. The jointly-defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect Compliance Testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member's solution.

Avaya recommends our customers implement Avaya solutions using appropriate security and encryption capabilities enabled by our products. The testing referenced in this DevConnect Application Note included the enablement of supported encryption capabilities in the Avaya products. Readers should consult the appropriate Avaya product documentation for further information regarding security and encryption capabilities supported by those Avaya products.

Support for these security and encryption capabilities in any non-Avaya solution component is the responsibility of each individual vendor. Readers should consult the appropriate vendor-supplied product documentation for more information regarding those products.

For the testing associated with this Application Note, the interface between Avaya systems and Verizon Business IPCC Services did not include use of any specific encryption features as requested by Verizon.

Encryption (TLS/SRTP) was used internal to the enterprise between Avaya products wherever possible.

2.1. Interoperability Compliance Testing

The interoperability compliance testing included the execution of test cases details in the Verizon-authored interoperability test plan.

- SIP OPTIONS monitoring of the health of the SIP trunks was verified. Both the Avaya enterprise equipment and Verizon Business can monitor health using SIP OPTIONS.
- Incoming calls from the PSTN were routed to the toll-free numbers assigned by Verizon Business to the Avaya location. Configuration was varied such that these incoming toll-free calls were directed to Communication Manager telephone extensions, and Communication Manager VDNs containing call routing logic to exercise SIP Network Call Redirection.
- Inbound caller interaction with Experience Portal applications, including prompting, caller DTMF input, wait treatment (e.g., announcements and/or music on hold) and Automatic Speech Recognition.

©2021 Avaya Inc. All Rights Reserved.

- Experience Portal use of SIP REFER to redirect inbound calls, via the Avaya SBCE, to the appropriate Communication Manager agent extension
- Call and two-way talk path establishment between callers and Communication Manager agents following redirection from Experience Portal
- Inbound calls to a self-service Experience Portal application which forwards the call to 8YY or any other PSTN number over Verizon IPCC service using SIP REFER
- Proper disconnect when either party hangs up an active call.
- Proper disconnect when the PSTN caller abandons (i.e., hangs up) a toll-free call before the call has been answered.
- Proper SIP 486 response and busy tone heard by the caller when a PSTN user calls a toll-free number directed to a busy user or resource when no redirection on busy conditions was configured (which would be unusual in a contact center).
- Proper termination of an inbound IP Toll Free call left in a ringing state for a relatively long duration, which again would be unusual in a contact center. In the sample configuration, Verizon sent a SIP CANCEL to cancel the call after approximately 35 seconds of ring no answer condition, returning busy tone to the PSTN caller.
- Privacy requests for inbound toll-free calls from the PSTN were verified. That is, when privacy is requested by a PSTN caller (e.g., dialing *67 from a mobile phone), the inbound toll-free call can be successfully completed while withholding presentation of the PSTN caller ID to user displays. (When the caller requests privacy, Verizon IPCC sends the caller ID in the P-Asserted-Identity header and includes “Privacy: id” which is honored by Communication Manager).
- Inbound toll-free call long holding time call stability. The Avaya CPE sends a re-INVITE with SDP to refresh the session at the configured session refresh interval specified on the Communication Manager trunk group handling the call. In the sample configuration, the session refresh re-INVITE was sent after 900 seconds (15 minutes), the interval configured for the trunk group in **Section 5.8.1**. The call continued with proper talk path.
- Telephony features such as hold and resume. When a Communication Manager user holds a call in the sample configuration, Communication Manager will send a re-INVITE to Verizon IP Toll Free service with a media attribute “sendonly”. The Verizon 200 OK to this re-INVITE will include media attribute “recvonly”. While the call remains on hold, RTP will flow from the Avaya CPE to Verizon, but no RTP will flow from Verizon to the Avaya CPE (i.e., as intended). When the user resumes the call from hold, bi-directional media path resumes. Although it would be unexpected in a contact center, calls on hold for longer than the session refresh interval were tested, and such calls could be resumed after the session refresh re-asserted the “sendonly” state.
- Transfer of toll-free calls between Communication Manager users.
- Incoming voice calls using the G.729A and G.711 ULAW codecs, and proper protocol procedures related to media.
- DTMF transmission using RFC2833. For inbound toll-free calls, PSTN users dialing post-answer DTMF digits are recognized properly by the Avaya CPE.
- Proper DiffServ markings for SIP signaling and RTP media flowing from the Avaya CPE to Verizon.
- Incoming fax calls using T.38.

©2021 Avaya Inc. All Rights Reserved.

- Remote Avaya SIP endpoints connected through Avaya SBCE were used along with local Avaya endpoints in the verification of these Application Notes.

2.2. Test Results

The interoperability compliance testing of the sample configuration was completed with successful results as described in **Section 2.1**. The following limitations are noted for the sample configuration described in these Application Notes.

- Verizon Business IPCC Services suite does not support History Info or Diversion Headers. The Avaya CPE will not send History-Info or Diversion header to Verizon IPCC in the sample configuration.
- Verizon Business IPCC Services suite does not support SIP 302 Redirect.
- Verizon Business IPCC Services suite does not support G.729 Annex B. When using G729, the Avaya CPE will always include "annexb=no" in SDP in the sample configuration.
- **Section 3.2.3** summarizes a call flow that would allow Communication Manager to continue the processing of a call upon failure of a vector-triggered REFER attempt to the PSTN. However, such call scenario could not be verified on the production Verizon circuit used for testing. On the production circuit, Verizon sent a BYE to terminate the call immediately upon encountering REFER transfer failures, so there was no opportunity for the call to continue being processed by the Communication Manager. See **Section 3.2.3** for additional information.
- During testing, Verizon's IP Interactive Voice Response (IP-IVR) service did not accept the SIP REFER method unless the URI in the Refer-To header included the IP address presented in the From header within the original SIP INVITE. This IP address was different from the IP address included in the Contact header. The Avaya SBCE Topology Hiding profile was used to populate the From header IP address in the Refer-To header for both the IP-IVR and IP Toll Free services. Calls were successfully diverted using REFER for both Verizon services with this Topology Hiding profile in place. See **Section 8.10.2** for additional information.

©2021 Avaya Inc. All Rights Reserved.

2.3. SIP Header Removal

To support advanced SIP telephony features in the Avaya Aura® enterprise environment, certain proprietary headers may be included in the SIP message sent toward Verizon. These extra headers can cause the SIP message to become larger than the specified Maximum Transmission Unit (MTU) and create fragmented UDP packets. These fragmented packets may not be re-assembled properly on the far-end by Verizon's equipment, for instance, when packets arrive out of order. To prevent fragmented packets, any unnecessary or proprietary headers should be removed from the SIP message before being sent to Verizon. Session Manager can remove these headers by specifying the "*eRHdrs*" parameter within the "*VerizonAdapter*" adaptation. See **Section 6.4.2**.

In the sample configuration, the following headers were removed:

- AV-Global-Session-ID
- Alert-Info
- Endpoint-View
- P-AV-Message-Id
- P-Charging-vector
- P-Location
- AV-Secure-Indication

To help reduce the packet size further, the Avaya SBCE can remove the "*epv*" parameter that may be included within the Contact header by applying a Sigma script to the Verizon server configuration. See **Section 8.7**.

2.4. Support

2.4.1 Avaya

For technical support on the Avaya products described in these Application Notes visit http://support.avaya.com

2.4.2 Verizon

For technical support on Verizon Business IPCC Services offer, visit online support at https://enterprise.verizon.com/support/

©2021 Avaya Inc. All Rights Reserved.

3. Reference Configuration

Figure 1 illustrates the sample configuration used for the DevConnect compliance testing. The Avaya CPE location simulates a customer site. The PIP service defines a secure MPLS connection between the Avaya CPE T1 connection and the Verizon Business IPCC Services node. At the edge of the Avaya CPE location is an Avaya Session Border Controller for Enterprise. The Avaya SBCE receives traffic from the Verizon Business IPCC Services on port 5060 and sends traffic to the Verizon Business IPCC Services using destination port 5072, using UDP for transport.



Figure 1: Avaya Interoperability Test Lab Configuration

©2021 Avaya Inc. All Rights Reserved.

The Verizon toll-free numbers were mapped by Session Manager to various Communication Manager extensions. The extension mappings were varied during the testing to allow inbound toll-free calls to terminate directly on user extensions or indirectly through hunt groups, vector directory numbers (VDNs) and vectors to user extensions and contact center agents.

The Avaya CPE environment was known to Verizon Business IPCC Services as FQDN "*adevc.avaya.globalipcom.com*". For efficiency, the Avaya CPE environment utilizing Session Manager Release 8.1 and Communication Manager Release 8.1 was shared among other ongoing test efforts at the Avaya Solutions and Interoperability Test lab. Access to the Verizon Business IPCC Services was added to a configuration that already used domain "*avayalab.com*" at the enterprise. As such, the Avaya SBCE is used to adapt the domains as needed. These Application Notes indicate the configuration that would not be required in cases where the CPE domain in Communication Manager and Session Manager match the CPE domain known to Verizon.

The following summarizes various header contents and manipulations for toll-free calls in the sample configuration:

- Verizon Business IPCC Services node sends the following in the initial INVITE to the CPE:
  - The CPE FQDN of ***adevc.avaya.globalipcom.com*** in the Request URI.
  - The Verizon Business IPCC Services gateway IP address in the From header.
  - The enterprise SBC outside IP address (e.g., 1.1.1.2) in the To header.
  - Sends the INVITE to Avaya CPE using destination port 5060 via UDP
- Avaya Session Border Controller for Enterprise sends Session Manager:
  - The Request URI contains ***avayalab.com.***
  - The host portion of the From header and PAI header contains ***avayalab.com***
  - The host portion of the To header contains ***avayalab.com***
  - Sends the packet to Session Manager using destination port 5061 via TLS
- Session Manager sends Communication Manager
  - The Request URI contains ***avayalab.com***, to match the shared Avaya SIL test environment.
  - Sends the packet to Communication Manager using destination port 5071 via TLS to allow Communication Manager to distinguish Verizon traffic from other traffic arriving from the same instance of Session Manager.

Note – The Fully Qualified Domain Names and IP addressing specified in these Application Notes apply only to the reference configuration shown in **Figure 1**. Verizon Business customers will use FQDNs and IP addressing appropriate for the unique customer environment.

3.1. History Info and Diversion Headers

The Verizon Business IPCC Services suite does not support SIP History Info headers or Diversion headers. Therefore, Communication Manager was provisioned not to send History Info headers or Diversion headers.

©2021 Avaya Inc. All Rights Reserved.

3.2. Call Flows – Avaya Aura® Communication Manager

To understand how inbound Verizon toll-free calls are handled by Session Manager and Communication Manager, key call flows are summarized in this section.

3.2.1 Inbound IP Toll Free Call with no Network Call Redirection

The first call scenario illustrated in **Figure 3** is an inbound Verizon IP Toll Free call that is routed to Communication Manager, which in turn routes the call to a vector, agent, or phone. No redirection is performed in this simple scenario. A detailed verification of such a call with Communication Manager traces can be found in **Section 10.1.1**.

1. A PSTN phone originates a call to a Verizon IP Toll Free number.
2. The PSTN routes the call to the Verizon IP Toll Free service network.
3. The Verizon IP Toll Free service routes the call to the Avaya Session Border Controller for Enterprise.
4. The Avaya Session Border Controller for Enterprise performs any configured SIP header modifications, and routes the call to Session Manager.
5. Session Manager applies any configured SIP header adaptations and digit conversions, and based on configured Routing Policies, determines where the call should be routed. In this case, Session Manager routes the call to Communication Manager using a unique port so that Communication Manager can distinguish this call as having arrived from Verizon IPCC.
6. Depending on the called number, Communication Manager routes the call to:
   a) a hunt group or vector, which in turn routes the call to an agent or phone, or
   b) directly to a phone.



Figure 3: Inbound Verizon IP Toll Free Call – No Redirection

©2021 Avaya Inc. All Rights Reserved.

3.2.2 Inbound IP Toll Free Call with Post-Answer Network Call Redirection

The second call scenario illustrated in **Figure 4** is an inbound Verizon IP Toll Free call that is routed to a Communication Manager Vector Directory Number (VDN) to invoke call handling logic in a vector. The vector answers the call and then redirects the call back to the Verizon IP Toll Free service for routing to an alternate destination. Note that Verizon IP Toll Free service does not support redirecting a call before it is answered (using a SIP 302), and therefore the vector must include a step that results in answering the call, such as playing an announcement, prior to redirecting the call using REFER.

A detailed verification of such call with Communication Manager traces can be found in **Section 10.1.2** for a Verizon IP Toll Free SIP-connected alternate destination. In this example, the Verizon IP Toll Free service can be used to pass User to User Information (UUI) from the redirecting site to the alternate destination.

1. Same as the first five steps in **Figure 3**.
2. Communication Manager routes the call to a vector, which answers the call, plays an announcement, and attempts to redirect the call by sending a SIP REFER message out the SIP trunk from which the inbound call arrived. The SIP REFER message specifies the alternate destination in the Refer-To header. The SIP REFER message passes back through Session Manager and the Avaya SBCE to the Verizon IP Toll Free service network.
3. The Verizon IP Toll Free service places a call to the target party contained in the Refer-To header. Upon answer, the calling party is connected to the target party.
4. The Verizon IP Toll Free service notifies the Avaya CPE that the referred call has been answered (NOTIFY/sipfrag 200 OK). Communication Manager sends a BYE. The calling party and the target party can talk. The trunk upon which the call arrived in Step 1 is idle.



Figure 4: Inbound Verizon IP Toll Free– Post-Answer SIP REFER Redirection Successful

©2021 Avaya Inc. All Rights Reserved.

3.2.3 Inbound IP Toll Free Call with Unsuccessful Network Call Redirection

The next call scenario illustrated in **Figure 5** is similar to the previous call scenario, except that the redirection is unsuccessful. In this case, Communication Manager can "take the call back" and continue vector processing. For example, the call may route to an alternative agent, phone, or announcement after unsuccessful NCR.

1. Same as **Figure 4**.
2. Same as **Figure 4**.
3. The Verizon IP Toll Free service places a call to the target party (alternate destination), but the target party is busy or otherwise unavailable.
4. The Verizon IP Toll Free service notifies the redirecting/referring party (Communication Manager) of the error condition.
5. Communication Manager routes the call to a local agent, phone, or announcement.

However, as noted in **Section 2.2**, this "unsuccessful transfer" scenario could not be verified on the production Verizon circuit used for testing. On the production circuit, Verizon sends a SIP BYE message which terminates Communication Manager vector processing for failure scenarios. For example, if a 486 Busy is received from the target of the REFER, Verizon will send a BYE immediately after a "NOTIFY/sipfrag 486 Busy Here", which precludes any further call processing by Communication Manager. As another example, in cases where mis-configuration is introduced to cause the Refer-To header to be malformed (e.g., no "+" in Refer-To), Verizon will similarly send a BYE immediately after a "NOTIFY/sipfrag 603 Server Internal Error".



Figure 5: Inbound Verizon IP Toll Free– Post-Answer SIP REFER Redirection Unsuccessful

©2021 Avaya Inc. All Rights Reserved.

3.3. Call Flows – Avaya Experience Portal

To understand how inbound Verizon toll-free calls are handled by Session Manager and Experience Portal, key call flows are summarized in this section.

3.3.1 Inbound IP Toll Free Call handled by Avaya Experience Portal

The first call scenario illustrated below is an inbound call arriving and remaining on Experience Portal.

1. A PSTN phone originates a call to a Verizon IP Toll Free number.
2. The PSTN routes the call to the Verizon IP Toll Free service network.
3. The Verizon IP Toll Free service routes the call to the Avaya SBCE.
4. The Avaya SBCE performs any necessary SIP header modifications and routes the call to Session Manager.
5. Session Manager applies any necessary SIP header adaptations and digit conversions, and based on configured Routing Policies, determines where the call should be routed next. In this case, Session Manager routes the call to Experience Portal.
6. Experience Portal matches the called party number to a VXML and/or CCXML application script, answers the call, and handles the call according to the directives specified in the application. In this scenario, the application sufficiently meets the caller's needs or requests, and thus the call does not need to be transferred to Communication Manager.



Figure 6: Inbound Call Handling Entirely by Avaya Experience Portal

©2021 Avaya Inc. All Rights Reserved.

3.3.2 Inbound IP Toll Free Call redirected to Avaya Aura® Communication Manager

The second call scenario illustrated below is an inbound call arriving on Experience Portal and transferred to Communication Manager without determining whether an agent is available or not.

1. Same as the first five steps from the first call scenario.
2. In this scenario, when the caller selects an option requesting an agent, Experience Portal redirects the call by sending a SIP REFER to the Avaya SBCE.
3. The Avaya SBCE sends a SIP INVITE to the Communication Manager (via Session Manager) for the selected skill. In addition, the Avaya SBCE places the inbound call on hold.
4. Communication Manager routes the call to the agent.
5. When the agent answers, the Avaya SBCE takes the call off hold and the caller is connected to the agent.



Figure 7: Avaya Experience Portal Transfers Call to Avaya Aura® Communication Manager

©2021 Avaya Inc. All Rights Reserved.

3.3.3 Inbound IP Toll Free Call redirected to PSTN number

The third call scenario illustrated below is an inbound call arriving on Experience Portal and forwarded to an 8YY number or any other PSTN number over the Verizon network.

1. Same as the first six steps from the first call scenario.
2. In this scenario, the application is sufficient to meet the caller's requests, and thus the call needs to be forwarded to another PSTN number. Based upon the selection, Experience Portal forwards the call to an appropriate PSTN number which can be a regular PSTN number or an 8YY number.



Figure 8: Inbound Call forwarded by Experience Portal to another PSTN number

©2021 Avaya Inc. All Rights Reserved.

4. Equipment and Software Validated

The following equipment and software were used in the sample configuration.

Equipment/Software	Release/Version
Avaya Aura® System Manager	8.1.3.1.1012244 Service Pack 1
Avaya Aura® Session Manager	8.1.3.1.813113
Avaya Aura® Communication Manager	8.1.3.1.0-FP3SP1 (patch 26766)
Avaya Session Border Controller for Enterprise	8.1.2.0-31-19809
Avaya Experience Portal	8.0.0.0.1424
Avaya Messaging	10.8 SP1
Avaya Aura® Media Server	8.0.2.163
Avaya G430 Media Gateway	41.34.1
Avaya 96x1 Series IP Deskphone (H.323)	6.8502
Avaya 96x1 Series IP Deskphone (SIP)	7.1.12.8
Avaya J100 IP Deskphones (J169, J179)	4.0.9.0.4
Avaya Workplace Client for Windows	3.17.0.65.16
Avaya Agent for Desktop	2.0.6.11.3003
Fax device	Ventafax 7.10

Table 1: Equipment and Software Used in the Sample Configuration

©2021 Avaya Inc. All Rights Reserved.

5. Configure Avaya Aura® Communication Manager

This section illustrates an example configuration allowing SIP signaling via the "Processor Ethernet" of Communication Manager to Session Manager.

Note – The initial installation, configuration, and licensing of the Avaya servers and media gateways for Communication Manager are assumed to have been previously completed and are not discussed in these Application Notes. Consult the documentation on the Reference section for further details, if necessary.

5.1. Verify Licensed Features

Note – This section describes steps to verify Communication Manager feature settings that are required for the reference configuration described in these Application Notes. Depending on access privileges and licensing, some or all of the following settings might only be viewed, and not modified. If any of the required features are not set, and cannot be configured, contact an authorized Avaya account representative to obtain the necessary licenses/access.

Step 1 - Enter the **display system-parameters customer-options** command. On **Page 2** of the form, verify **that** the **Maximum Administered SIP Trunks** number is sufficient for the number of expected SIP trunks.

```
display system-parameters customer-options                    Page   2 of  12
                                OPTIONAL FEATURES

IP PORT CAPACITIES                                            USED
                     Maximum Administered H.323 Trunks: 4000  0
           Maximum Concurrently Registered IP Stations: 2400  1
             Maximum Administered Remote Office Trunks: 4000  0
Maximum Concurrently Registered Remote Office Stations: 2400  0
              Maximum Concurrently Registered IP eCons: 68    0
  Max Concur Registered Unauthenticated H.323 Stations: 100   0
                       Maximum Video Capable Stations: 2400  3
                   Maximum Video Capable IP Softphones: 2400  10
                      Maximum Administered SIP Trunks: 4000  130
  Maximum Administered Ad-hoc Video Conferencing Ports: 4000  0
   Maximum Number of DS1 Boards with Echo Cancellation: 80    0
```


©2021 Avaya Inc. All Rights Reserved.

Step 2 - On **Page 4** of the form, verify that **ARS** is enabled.

```
display system-parameters customer-options                      Page   4 of  12
                                OPTIONAL FEATURES

    Abbreviated Dialing Enhanced List? y          Audible Message Waiting? y
        Access Security Gateway (ASG)? n              Authorization Codes? y
        Analog Trunk Incoming Call ID? y                      CAS Branch? n
 A/D Grp/Sys List Dialing Start at 01? y                        CAS Main? n
Answer Supervision by Call Classifier? y                 Change COR by FAC? n
                                   ARS? y  Computer Telephony Adjunct Links? y
                 ARS/AAR Partitioning? y   Cvg Of Calls Redirected Off-net? y
          ARS/AAR Dialing without FAC? n                       DCS (Basic)? y
          ASAI Link Core Capabilities? n                DCS Call Coverage? y
          ASAI Link Plus Capabilities? n               DCS with Rerouting? y
       Async. Transfer Mode (ATM) PNC? n
  Async. Transfer Mode (ATM) Trunking? n    Digital Loss Plan Modification? y
              ATM WAN Spare Processor? n                          DS1 MSP? y
                                   ATMS? y            DS1 Echo Cancellation? y
                  Attendant Vectoring? y
```

Step 3 - On **Page 5** of the form, verify that the **Enhanced EC500**, **IP Trunks**, and **ISDN-PRI,** features are **enabled**. If the use of SIP REFER messaging will be required verify that the **ISDN/SIP Network Call Redirection** feature is enabled. If the use of SRTP will be required verify that the **Media Encryption Over IP** feature is enabled.

```
display system-parameters customer-options                      Page   5 of  12
                                OPTIONAL FEATURES
   Emergency Access to Attendant? y                             IP Stations? y
            Enable 'dadmin' Login? y
            Enhanced Conferencing? y                      ISDN Feature Plus? n
                  Enhanced EC500? y       ISDN/SIP Network Call Redirection? y
    Enterprise Survivable Server? n                         ISDN-BRI Trunks? y
       Enterprise Wide Licensing? n                               ISDN-PRI? y
              ESS Administration? y              Local Survivable Processor? n
         Extended Cvg/Fwd Admin? y                   Malicious Call Trace? y
     External Device Alarm Admin? y                 Media Encryption Over IP? y
  Five Port Networks Max Per MCC? n    Mode Code for Centralized Voice Mail? n
                Flexible Billing? n
   Forced Entry of Account Codes? y                Multifrequency Signaling? y
      Global Call Classification? y          Multimedia Call Handling (Basic)? y
             Hospitality (Basic)? y       Multimedia Call Handling (Enhanced)? y
 Hospitality (G3V3 Enhancements)? y                Multimedia IP SIP Trunking? y
                       IP Trunks? y

           IP Attendant Consoles? y
```


©2021 Avaya Inc. All Rights Reserved.

Step 4 - On **Page 6** of the form, verify that the **Processor Ethernet** field is set to **y**.

```
display system-parameters customer-options                    Page   6 of  12
                                OPTIONAL FEATURES

                Multinational Locations? n            Station and Trunk MSP? y
 Multiple Level Precedence & Preemption? n      Station as Virtual Extension? y
                     Multiple Locations? n
                                                System Management Data Transfer? n
          Personal Station Access (PSA)? y              Tenant Partitioning? y
                          PNC Duplication? n       Terminal Trans. Init. (TTI)? y
                   Port Network Support? n              Time of Day Routing? y
                        Posted Messages? y       TN2501 VAL Maximum Capacity? y
                                                        Uniform Dialing Plan? y
                     Private Networking? y     Usage Allocation Enhancements? y
               Processor and System MSP? y
                     Processor Ethernet? y               Wideband Switching? y
                                                                 Wireless? n
                           Remote Office? y
          Restrict Call Forward Off Net? y
                  Secondary Data Module? y
```

5.2. System-Parameters Features

Step 1 - Enter the **display system-parameters features** command. On **Page 1** of the form, verify that the **Trunk-to-Trunk Transfer** is set to **all**.

```
change system-parameters features                             Page   1 of  19
                            FEATURE-RELATED SYSTEM PARAMETERS
                               Self Station Display Enabled? y
                                    Trunk-to-Trunk Transfer: all
                 Automatic Callback with Called Party Queuing? n
    Automatic Callback - No Answer Timeout Interval (rings): 3
                         Call Park Timeout Interval (minutes): 10
        Off-Premises Tone Detect Timeout Interval (seconds): 20
                                  AAR/ARS Dial Tone Required? y

              Music (or Silence) on Transferred Trunk Calls? all
              DID/Tie/ISDN/SIP Intercept Treatment: attendant
    Internal Auto-Answer of Attd-Extended/Transferred Calls: transferred
                  Automatic Circuit Assurance (ACA) Enabled? n


             Abbreviated Dial Programming by Assigned Lists? n
       Auto Abbreviated/Delayed Transition Interval (rings): 2
                    Protocol for Caller ID Analog Terminals: Bellcore
    Display Calling Number for Room to Room Caller ID Calls? n
```


©2021 Avaya Inc. All Rights Reserved.

5.3. Dial Plan

The dial plan defines how digit strings will be used locally by Communication Manager. The following dial plan was used in the reference configuration.

Step 1 - Enter the **change dialplan analysis** command to provision the following dial plan.

- 5-digit extensions with a **Call Type** of **ext** beginning with:
  - The digits **1**,**5**,**7** and **8** for Communication Manager extensions.
- 3-digit dial access code (indicated with a **Call Type** of **dac**), e.g., access code ***xx** for SIP Trunk Access Codes (TAC). See the trunk forms in **Section 5.8**.

```
change dialplan analysis                                        Page   1 of  12
                          DIAL PLAN ANALYSIS TABLE
                               Location: all            Percent Full: 1

    Dialed   Total  Call     Dialed   Total  Call     Dialed   Total  Call
    String   Length Type     String   Length Type     String   Length Type
 1             5  ext
 2             5  ext
 3             5  ext
 4             5  ext
 5             5  ext
 60            3  ext
 66            2  fac
 7             5  ext
 8             5  ext
 9             1  fac
 *             3  dac
```

5.4. Node Names

Node names define IP addresses to various Avaya components in the enterprise. In the reference configuration a Processor Ethernet (procr) based Communication Manager platform is used. Note that the Communication Manager procr name and IP address are entered during installation. The procr IP address was used to define the Communication Manager SIP Entities in **Section 6.5**.

Step 1 - Enter the **change node-names ip** command, and add a node name and IP address for the following:

- Session Manager SIP signaling interface (e.g., **SM** and **10.64.91.81**).
- Media Server (e.g., **AMS** and **10.64.91.86**). The Media Server node name is only needed if a Media Server is present.

```
change node-names ip                                            Page   1 of   2
                                  IP NODE NAMES
    Name                 IP Address
AMS                   10.64.91.86
SM                    10.64.91.81
default               0.0.0.0
procr                 10.64.91.75
procr6                ::
```


©2021 Avaya Inc. All Rights Reserved.

5.5. Processor Ethernet Configuration

The **display ip-interface procr** command can be used to verify the Processor Ethernet (procr) parameters defined during installation.

- Verify that **Enable Interface?**, **Allow H.323 Endpoints?**, and **Allow H248 Gateways?** fields are set to **y**.
- In the reference configuration the procr is assigned to **Network Region: 1**.
- The default values are used for the remaining parameters.

```
change ip-interface procr                                    Page   1 of   2
                                IP INTERFACES


                 Type: PROCR
                                                  Target socket load: 4800

      Enable Interface? y                        Allow H.323 Endpoints? y
                                                  Allow H.248 Gateways? y
        Network Region: 1                          Gatekeeper Priority: 5


                               IPV4 PARAMETERS
             Node Name: procr                   IP Address: 10.64.91.75


            Subnet Mask: /24
```


©2021 Avaya Inc. All Rights Reserved.

5.6. IP Codec Sets

Use the **change ip-codec-set** command to define a list of codecs to use for calls within the enterprise, and for calls between the enterprise and the service provider.

5.6.1 Codecs for IP Network Region 1 (calls within the CPE)

Step 1 - Enter the **change ip-codec-set x** command, where **x** is the number of an IP codec set used for internal calls (e.g., **1**). On **Page 1** of the **ip-codec-set** form, ensure that **G.711MU**, and **G.729A** are included in the codec list.

```
change ip-codec-set 1                                          Page   1 of   2
                        IP Codec Set
    Codec Set: 1

    Audio        Silence      Frames   Packet
    Codec        Suppression  Per Pkt  Size(ms)
 1: G.722-64K                   2        20
 2: G.711MU           n         2        20
 3: G.729A            n         2        20

     Media Encryption                  Encrypted SRTCP: enforce-unenc-srtcp
 1: 1-srtp-aescm128-hmac80
 2: none
```

Step 2 - On **Page 2** of the ip-codec-set form, set **FAX Mode** to **t.38-standard**, and **ECM** to **y**.

```
change ip-codec-set 1                                          Page   2 of   2

                        IP MEDIA PARAMETERS

                            Allow Direct-IP Multimedia? y
             Maximum Call Rate for Direct-IP Multimedia:   384:Kbits
     Maximum Call Rate for Priority Direct-IP Multimedia:   384:Kbits

                                      Redun-                        Packet
                        Mode          dancy                         Size(ms)
    FAX                 t.38-standard 0     ECM: y
    Modem               off           0
    TDD/TTY             US            3
    H.323 Clear-channel n             0
    SIP 64K Data        n             0                             20

Media Connection IP Address Type Preferences
 1: IPv4
 2:
```


©2021 Avaya Inc. All Rights Reserved.

5.6.2 Codecs for IP Network Region 2 (calls from Verizon)

This IP codec set will be used for Verizon Business IP Trunking calls. Repeat the steps in **Section 5.6.1** with the following changes:

On **Page 1**, provision the codecs in the order shown below.

```
change ip-codec-set 2                                          Page   1 of   2

                        IP MEDIA PARAMETERS
    Codec Set: 2

    Audio        Silence      Frames   Packet
    Codec        Suppression  Per Pkt  Size(ms)
 1: G.729A            n         2        20
 2: G.711MU           n         2        20
 3:


     Media Encryption                  Encrypted SRTCP: enforce-unenc-srtcp
 1: 1-srtp-aescm128-hmac80
 2: none
```

On **Page 2**, set **FAX Mode** to **t.38-G711-fallback**, **ECM** to **y**, and **FB-Timer** to **4**

```
change ip-codec-set 2                                          Page   2 of   2

                        IP MEDIA PARAMETERS

                            Allow Direct-IP Multimedia? y
             Maximum Call Rate for Direct-IP Multimedia:   384:Kbits
    Maximum Call Rate for Priority Direct-IP Multimedia:   384:Kbits

                                      Redun-                        Packet
                        Mode          dancy                         Size(ms)
    FAX                 t.38-G711-fallback 0     ECM: y  FB-Timer: 4
    Modem               off           0
    TDD/TTY             US            3
    H.323 Clear-channel n             0
    SIP 64K Data        n             0                             20


Media Connection IP Address Type Preferences
 1: IPv4
```


©2021 Avaya Inc. All Rights Reserved.

5.7. Network Regions

Network regions provide a means to logically group resources. In the shared Communication Manager configuration used for the testing, the Avaya G430 Media Gateway and Avaya Media Server are in region 1. To provide testing flexibility, network region 2 was associated with other components used specifically for the Verizon testing.

5.7.1 IP Network Region 1 – Local CPE Region

Step 1 - Enter **change ip-network-region x**, where **x** is the number of an unused IP network region (e.g., region **1**). This IP network region will be used to represent the local CPE. Populate the form with the following values:

- Enter a descriptive name (e.g., **Enterprise**).
- Enter the enterprise domain (e.g., **avayalab.com**) in the **Authoritative Domain** field.
- Enter **1** for the **Codec Set** parameter.
- **Intra-region IP-IP Audio Connections** – Set to **yes**, indicating that the RTP paths should be optimized to reduce the use of media resources when possible within the same region.
- **Inter-region IP-IP Audio Connections** – Set to **yes**, indicating that the RTP paths should be optimized to reduce the use of media resources when possible between regions.

```
change ip-network-region 1                                    Page   1 of  20
                              IP NETWORK REGION
  Region: 1
Location: 1       Authoritative Domain: avayalab.com
    Name: Enterprise            Stub Network Region: n
MEDIA PARAMETERS                Intra-region IP-IP Direct Audio: yes
      Codec Set: 1              Inter-region IP-IP Direct Audio: yes
   UDP Port Min: 2048                     IP Audio Hairpinning? n
   UDP Port Max: 3329
DIFFSERV/TOS PARAMETERS
 Call Control PHB Value: 46
        Audio PHB Value: 46
        Video PHB Value: 26
802.1P/Q PARAMETERS
 Call Control 802.1p Priority: 6
        Audio 802.1p Priority: 6
        Video 802.1p Priority: 5      AUDIO RESOURCE RESERVATION PARAMETERS
H.323 IP ENDPOINTS                                     RSVP Enabled? n
  H.323 Link Bounce Recovery? y
 Idle Traffic Interval (sec): 20
   Keep-Alive Interval (sec): 5
            Keep-Alive Count: 5
```


©2021 Avaya Inc. All Rights Reserved.

Step 2 - On **page 4** of the form:

- Verify that next to region **1** in the **dst rgn** column, the codec set is **1**.
- Next to region **2** in the **dst rgn** column, enter **2** for the codec set (this means region 1 is permitted to talk to region 2 and it will use codec set 2 to do so). The **direct WAN** and **Units** columns will self-populate with **y** and **No Limit** respectively.
- Let all other values default for this form.

```
change ip-network-region 1                                          Page   4 of  20

 Source Region: 1     Inter Network Region Connection Management     I       M
                                                                    G  A    t
 dst codec direct   WAN-BW-limits   Video      Intervening      Dyn  A  G    c
 rgn  set   WAN  Units    Total Norm  Prio Shr Regions          CAC  R  L    e
 1    1                                                             all
 2    2     y    NoLimit                                          n       t
```

5.7.2 IP Network Region 2 – Verizon Trunk Region

Repeat the steps in **Section 5.7.1** with the following changes:

Step 1 - On **Page 1** of the form (not shown):

- Enter a descriptive name (e.g., **Verizon**).
- Enter **2** for the **Codec Set** parameter.

Step 2 - On **Page 4** of the form:

- Set codec set **2** for **dst rgn 1**.
- Note that **dst rgn 2** is pre-populated with codec set **2** (from page 1 provisioning).

```
change ip-network-region 2                                          Page   4 of  20

 Source Region: 2     Inter Network Region Connection Management     I       M
                                                                    G  A    t
 dst codec direct   WAN-BW-limits   Video      Intervening      Dyn  A  G    c
 rgn  set   WAN  Units    Total Norm  Prio Shr Regions          CAC  R  L    e
 1    2     y    NoLimit                                          n       t
 2    2                                                             all
 3
```


©2021 Avaya Inc. All Rights Reserved.

5.8. SIP Trunks

SIP trunks are defined on Communication Manager by provisioning a Signaling Group and a corresponding Trunk Group. Two SIP trunks are defined on Communication Manager in the reference configuration:

- Inbound Verizon IPCC access – SIP Trunk 2. This trunk will use TLS port 5071.
- Internal CPE access (e.g., Avaya SIP telephones, Messaging, etc.) – SIP Trunk 3. This trunk will use TLS port 5061.

Note – Although TLS is used as the transport protocols between the Avaya CPE components, UDP was used between the Avaya SBCE and the Verizon Business IPCC Services. See the note in **Section 6.5** regarding the use of TLS transport protocols in the CPE.

5.8.1 SIP Trunk for Inbound Verizon calls

This section describes the steps for administering the SIP trunk to Session Manager used for Verizon IPCC service calls. Trunk 1 is defined. This trunk corresponds to the Session Manager **CM-TG2** SIP Entity defined later in **Section 6.5.2**.

5.8.1.1 Signaling Group 2

Step 1 - Enter the **add signaling-group x** command, where **x** is the number of an unused signaling group (e.g., **2**), and provision the following:

- **Group Type** – Set to **sip**.
- **Transport Method** – Set to **tls**.
- Verify that **IMS Enabled?** is set to **n**.
- Verify that **Peer Detection Enabled?** is set to **y**. The system will auto detect and set the **Peer Server** to **SM**.
- **Near-end Node Name** – Set to the node name of the **procr** noted in **Section 5.4**.
- **Far-end Node Name** – Set to the node name of Session Manager as administered in **Section 5.4** (e.g., **SM**).
- **Near-end Listen Port** and **Far-end Listen Port** – Set to **5071**.
- **Far-end Network Region** – Set the IP network region to **2**, as set in **Section 5.7.2**.
- **Far-end Domain** – Enter **avayalab.com**.
- **DTMF over IP** – Set to **rtp-payload** to enable Communication Manager to use DTMF according to RFC 2833.
- **Direct IP-IP Audio Connections** – Set to **y**, indicating that the RTP paths should be optimized directly to the associated stations, to reduce the use of media resources on the Avaya Media Gateway when possible (known as shuffling).

©2021 Avaya Inc. All Rights Reserved.

```
change signaling-group 2                                        Page   1 of   2
                              SIGNALING GROUP

 Group Number: 2              Group Type: sip
  IMS Enabled? n        Transport Method: tls
       Q-SIP? n
    IP Video? n                                    Enforce SIPS URI for SRTP? y
  Peer Detection Enabled? y  Peer Server: SM
 Prepend '+' to Outgoing Calling/Alerting/Diverting/Connected Public Numbers? y
Remove '+' from Incoming Called/Calling/Alerting/Diverting/Connected Numbers? n
Alert Incoming SIP Crisis Calls? n
   Near-end Node Name: procr                Far-end Node Name: SM
 Near-end Listen Port: 5071               Far-end Listen Port: 5071
                                       Far-end Network Region: 2

Far-end Domain: avayalab.com
                                            Bypass If IP Threshold Exceeded? n
Incoming Dialog Loopbacks: eliminate                 RFC 3389 Comfort Noise? n
        DTMF over IP: rtp-payload            Direct IP-IP Audio Connections? y
Session Establishment Timer(min): 3                    IP Audio Hairpinning? n
        Enable Layer 3 Test? y                  Initial IP-IP Direct Media? n
H.323 Station Outgoing Direct Media? n          Alternate Route Timer(sec): 6
```

Use the default parameters on **page 2** of the form (not shown).

5.8.1.2 Trunk Group 2

Step 1 - Enter the **add trunk-group x** command, where **x** is the number of an unused trunk group (e.g., **1**). On **Page 1** of the **trunk-group** form, provision the following:

- **Group Type** – Set to **sip**.
- **Group Name** – Enter a descriptive name (e.g., **Verizon IPCC**).
- **TAC** – Enter a trunk access code that is consistent with the dial plan (e.g., ***02**).
- **Direction** – Set to **incoming**.
- **Service Type** – Set to **public-ntwrk**.
- **Signaling Group** – Set to the signaling group administered in **Section 5.8.1.1** (e.g., **2**).
- **Number of Members** – Enter the maximum number of simultaneous calls desired on this trunk group (based on licensing) (e.g., **10**).

```
add trunk-group 2                                               Page   1 of  21
                              TRUNK GROUP

Group Number: 2                  Group Type: sip           CDR Reports: y
  Group Name: Verizon IPCC               COR: 1        TN: 1        TAC: *02
   Direction: incoming       Outgoing Display? n
 Dial Access? n                                  Night Service:

Service Type: public-ntwrk          Auth Code? n
                                          Member Assignment Method: auto
                                                    Signaling Group: 2
                                                  Number of Members: 10
```


©2021 Avaya Inc. All Rights Reserved.

Step 2 - On **Page 2** of the **Trunk Group** form:

- Set the **Preferred Minimum Session Refresh Interval (sec):** to **900**. This entry will actually cause a value of 1800 to be generated in the SIP Session-Expires header pertaining to active call session refresh.

```
add trunk-group 2                                                Page   2 of  21
      Group Type: sip

TRUNK PARAMETERS

     Unicode Name: auto

                                          Redirect On OPTIM Failure: 5000

            SCCAN? n                                Digital Loss Group: 18
                      Preferred Minimum Session Refresh Interval(sec): 900

 Disconnect Supervision - In? y  Out? y


             XOIP Treatment: auto    Delay Call Setup When Accessed Via IGAR? n


 Caller ID for Service Link Call to H.323 1xC: station-extension
```

Step 3 - On **Page 3** of the **Trunk Group** form:

- Set **Numbering Format** to **public**.

```
add trunk-group 2                                                Page   3 of  21
TRUNK FEATURES
          ACA Assignment? n            Measured: none
                                                          Maintenance Tests? y

                      Numbering Format: public
                                                UUI Treatment: service-provider

                                                 Replace Restricted Numbers? y
                                                Replace Unavailable Numbers? y

                                                  Hold/Unhold Notifications? y
                                 Modify Tandem Calling Number: no

 Show ANSWERED BY on Display? y
```


©2021 Avaya Inc. All Rights Reserved.

Step 4 - On **Page 4** of the **Trunk Group** form:

- Verify **Network Call Redirection** is set to **y**.
- Set **Telephone Event Payload Type** to the RTP payload type recommended by Verizon (e.g., **101**).
- Set **Convert 180 to 183 for Early Media** to **y**. Verizon recommends that inbound calls to the enterprise result in a 183 with SDP rather than a 180 with SDP.

Note – The Verizon Business IPCC Services do not support the Diversion header or the History-Info header, and therefore both **Support Request History** and **Send Diversion Header** are set to "**n**".

```
add trunk-group 2                                              Page   4 of  21
                            PROTOCOL VARIATIONS

                                        Mark Users as Phone? n
Prepend '+' to Calling/Alerting/Diverting/Connected Number? n
                      Send Transferring Party Information? n
                                  Network Call Redirection? y
          Build Refer-To URI of REFER From Contact For NCR? n
                                    Send Diversion Header? n
                                   Support Request History? n
                              Telephone Event Payload Type: 101


                         Convert 180 to 183 for Early Media? y
                  Always Use re-INVITE for Display Updates? n
                        Identity for Calling Party Display: P-Asserted-Identity
            Block Sending Calling Party Location in INVITE? n
                 Accept Redirect to Blank User Destination? n
                                          Enable Q-SIP? n

          Interworking of ISDN Clearing with In-Band Tones: keep-channel-active
                                Request URI Contents: may-have-extra-digits
```


©2021 Avaya Inc. All Rights Reserved.

5.8.2 Local SIP Trunk (Avaya SIP Telephone and Messaging Access)

Trunk 3 corresponds to the Session Manager **CM-TG3** SIP Entity defined later in **Section 6.5.3**.

5.8.2.1 Signaling Group 3

Repeat the steps in **Section 5.8.1.1** with the following changes:

Step 1 - Enter the **add signaling-group x** command, where **x** is the number of an unused signaling group (e.g., **3**).

Step 2 - Set the following parameters on page 1:

- **Near-end Listen Port** and **Far-end Listen Port** – Set to **5061**.
- **Far-end Network Region** – Set to the IP network region **1**, as defined in **Section 5.7.1**.

5.8.2.2 Trunk Group 3

Repeat the steps in **Section 5.8.1.2** with the following changes:

Step 1 - Enter the **add trunk-group x** command, where **x** is the number of an unused trunk group (e.g., **3**). On **Page 1** of the **trunk-group** form:

- **Group Name** – Enter a descriptive name (e.g., **SM Enterprise**).
- **TAC** – Enter a trunk access code that is consistent with the dial plan (e.g., ***03**).
- **Direction** – Set to **two-way**.
- **Service Type** – Set to **tie**.
- **Signaling Group** – Set to the number of the signaling group administered in **Section 5.8.2.1** (e.g., **3**).

Step 2 - On **Page 2** of the **Trunk Group** form:

- Same as **Section 5.8.1.2**

Step 3 - On **Page 3** of the **Trunk Group** form:

- Set **Numbering Format** to **private**.

Step 4 - On **Page 4** of the **Trunk Group** form:

- Set **Network Call Redirection** to **n**.
- Set **Send Diversion Header** to **n**.
- Verify **Identity for Calling Party Display** is set to **P-Asserted-Identity** (default).

Use default values for all other settings.

©2021 Avaya Inc. All Rights Reserved.

5.9. Contact Center Configuration

This section describes the basic commands used to configure Vector Directory Numbers (VDNs) and corresponding vectors. These vectors contain steps that invoke the Communication Manager SIP Network Call Redirection (NCR) functionality. These Application Notes provide rudimentary vector definitions to demonstrate and test the SIP NCR and UUI functionalities. In general, call centers will use vector functionality that is more complex and tailored to individual needs. Call centers may also use customer hosts running applications used in conjunction with Application Enablement Services (AES) to define call routing and provide associated UUI. The definition and documentation of those complex applications and associated vectors are beyond the scope of these Application Notes.

5.9.1 Announcements

Various announcements will be used within the vectors. In the sample configuration, these announcements were sourced by the Avaya G430 Media Gateway. The following abridged list command summarizes the announcements used in conjunction with the vectors in this section. To add an announcement extension, use the command **add announcement <extension>** (not shown).

```
list announcement

                         ANNOUNCEMENTS/AUDIO SOURCES
Announcement                                                Source      Num of
Extension            Type       Name                     Pt/Bd/Grp    Files
11001                integrated callcenter-main           005V9       1
11002                integ-mus  holdmusic                 005V9       1
11003                integrated disconnect                005V9       1
11004                integrated no_agents                 005V9       1
11005                integrated dtmf_test                 005V9       1
11006                integrated please_wait               005V9       1
11007                integrated REFER_Test                005V9       1
```

5.9.2 Post-Answer Redirection to a PSTN Destination

This section provides an example configuration of a vector that will use post-answer redirection to a PSTN destination. A corresponding detailed verification is provided in **Section 10.1.2**. In this example, the inbound toll-free call is routed to VDN 10001 shown in the following screen. The originally dialed Verizon IP Toll Free number may be mapped to VDN 10001 by Session Manager digit conversion, or via the incoming call handling treatment for the Communication Manager trunk group handling the call.

©2021 Avaya Inc. All Rights Reserved.

```
display vdn 10001                                              Page   1 of   3
                          VECTOR DIRECTORY NUMBER

                            Extension: 10001
                                Name*: Refer-to-PSTN
                          Destination: Vector Number        2
                  Attendant Vectoring? n
                 Meet-me Conferencing? n
                   Allow VDN Override? n
                                  COR: 1
                                  TN*: 1
                             Measured: none
```

VDN 10001 is associated with vector 2, which is shown below. Vector 2 plays an announcement (step 03) to answer the call. After the announcement, the **route-to number** (step 05) includes **~r+17863310799** where the number 786-331-0799 is a PSTN destination. This step causes a REFER message to be sent where the Refer-To header includes "+17863310799" as the user portion. Note that Verizon Business IPCC Services require the "+" in the Refer-To header for this type of call redirection.

```
display vector 2                                               Page   1 of   6
                                CALL VECTOR

    Number: 2               Name: Refer-to-PSTN
Multimedia? n      Attendant Vectoring? n    Meet-me Conf? n           Lock? n
     Basic? y   EAS? y   G3V4 Enhanced? y   ANI/II-Digits? y   ASAI Routing? y
 Prompting? y   LAI? y  G3V4 Adv Route? y   CINFO? y   BSR? y   Holidays? y
 Variables? y   3.0 Enhanced? y
01 wait-time    2   secs hearing ringback
02 #    Play announcement to caller in step 3. This answers the call.
03 announcement 11006
04 #    Refer the call to PSTN Destination in step 5 below.
05 route-to     number ~r+17863310799   with cov n if unconditionally
06 #    If Refer fails queue to skill 1
07 queue-to     skill 1    pri m
08
```

5.9.3 Post-Answer Redirection With UUI to a SIP Destination

This section provides an example of post-answer redirection with UUI passed to a SIP destination. In this example, the inbound call is routed to VDN 10003 shown in the following screen. The originally dialed Verizon toll-free number may be mapped to VDN 10003 by Session Manager digit conversion, or via the incoming call handling treatment for the Communication Manager trunk group handling the call.

©2021 Avaya Inc. All Rights Reserved.

```
display vdn 10003                                              Page   1 of   3
                            VECTOR DIRECTORY NUMBER

                              Extension: 10003
                                  Name*: REFER with UUI
                            Destination: Vector Number        3
                     Attendant Vectoring? n
                    Meet-me Conferencing? n
                      Allow VDN Override? n
                                    COR: 1
                                    TN*: 1
                               Measured: none
```

To facilitate testing of NCR with UUI, the following vector variables were defined.

```
change variables                                               Page   1 of  39
                              VARIABLES FOR VECTORS

Var Description                 Type    Scope Length Start Assignment       VAC
A   uui                         asaiuui L     16     1
B   uui                         asaiuui L     16     17
C
```

VDN 10003 is associated with vector 3, which is shown below. Vector 3 sets data in the vector variables A and B (steps 03 and 04) and plays an announcement to answer the call (step 05). After the announcement, the **route-to** number step includes **~r+18668512649**. This step causes a REFER message to be sent where the Refer-To header includes **+18668512649** as the user portion. The Refer-To header will also contain the UUI set in variables A and B. Verizon will include this UUI in the INVITE ultimately sent to the SIP-connected target of the REFER, which is toll-free number "18668512649". In the sample configuration, where only one location was used, 866-851-2649 is another toll-free number assigned to the same circuit as the original call. In practice, NCR with UUI would allow Communication Manager to send call or customer-related data along with the call to another contact center.

```
display vector 3                                               Page   1 of   6
                                  CALL VECTOR

    Number: 3                Name: Refer-with-UUI
Multimedia? n      Attendant Vectoring? n    Meet-me Conf? n           Lock? n
     Basic? y   EAS? y   G3V4 Enhanced? y   ANI/II-Digits? y   ASAI Routing? y
 Prompting? y   LAI? y  G3V4 Adv Route? y   CINFO? y   BSR? y   Holidays? y
 Variables? y   3.0 Enhanced? y
01 wait-time    2   secs hearing ringback
02 set          A      = none   CATR  1234567890123456
03 set          B      = none   CATR  7890123456789012
04 #    Play announcement to answer call and route to ~r to cause Refer
05 announcement 11007
06 route-to     number ~r+18668512649   with cov n if unconditionally
07 #    If Refer fails play announcement and disconnect
08 disconnect   after announcement 11003
```


©2021 Avaya Inc. All Rights Reserved.

5.9.4 ACD Configuration for Call Queued for Handling by Agent

This section provides a simple example configuration for VDN, vector, hunt group, and agent logins used to queue inbound Verizon IPCC calls for handling by an agent.

The following screens show an example ACD hunt group. On page 1, note the bolded values.

```
display hunt-group 1                                          Page   1 of   4
                                HUNT GROUP

           Group Number: 1                                 ACD? y
             Group Name: Agent Group                     Queue? y
        Group Extension: 19991                          Vector? y
             Group Type: ucd-mia
                     TN: 1
                    COR: 1                      MM Early Answer? n
          Security Code:                  Local Agent Preference? n
 ISDN/SIP Caller Display:

            Queue Limit: unlimited
```

The following screens show an example ACD hunt group. On the abbreviated page 2 shown below, note Skill is set to **y**.

```
display hunt-group 1                                          Page   2 of   4
                                HUNT GROUP

                    Skill? y      Expected Call Handling Time (sec): 180
                      AAS? n        Service Level Target (% in sec): 80 in 20
```


©2021 Avaya Inc. All Rights Reserved.

VDN 10004, shown below, is associated with vector 4.

```
display vdn 10004                                              Page   1 of   3
                            VECTOR DIRECTORY NUMBER

                              Extension: 10004
                                  Name*: Sales
                            Destination: Vector Number        4
                     Attendant Vectoring? n
                    Meet-me Conferencing? n
                      Allow VDN Override? n
                                    COR: 1
```

In this simple example, vector 4 briefly plays ring back, then queues the call to skill 1. Announcement 11004 is a simple recurring announcement. If an agent is immediately available to handle the call, the call will be delivered to the agent. If an agent is not immediately available, the call will be queued, and the caller will hear the announcement. Once an agent becomes available, the call will be delivered to the agent.

```
display vector 4                                               Page   1 of   6
                                  CALL VECTOR

    Number: 4                Name: Sales
Multimedia? n      Attendant Vectoring? n    Meet-me Conf? n           Lock? n
     Basic? y   EAS? y   G3V4 Enhanced? y   ANI/II-Digits? y   ASAI Routing? y
 Prompting? y   LAI? y  G3V4 Adv Route? y   CINFO? y   BSR? y   Holidays? y
 Variables? y   3.0 Enhanced? y
01 #    Wait hearing ringback
02 wait-time    2   secs hearing ringback
03 #    Simple queue to skill with recurring announcement until available
04 queue-to     skill 1    pri m
05 announcement 11004
06 wait-time    30  secs hearing music
07 goto step    5             if unconditionally
08 stop
```

The following screen illustrates an example agent-loginID 20001. In the sample configuration, an Avaya one-X® Deskphone logged in using agent-loginID 20001 and the configured Password to staff and take calls for skill 1.

©2021 Avaya Inc. All Rights Reserved.

```
change agent-loginID 20001                                    Page   1 of   2
                                AGENT LOGINID

               Login ID: 20001                                  AAS? n
                   Name: Agent 1                              AUDIX? n
                     TN: 1        Check skill TNs to match agent TN? n
                    COR: 1
          Coverage Path: 1                           LWC Reception: spe
          Security Code:                     LWC Log External Calls? n
          Attribute:                        AUDIX Name for Messaging:

                                       LoginID for ISDN/SIP Display? n
                                                           Password:
                                             Password (enter again):
                                                       Auto Answer: station
                                                  MIA Across Skills: system
                                           ACW Agent Considered Idle: system
                                           Aux Work Reason Code Type: system
                                             Logout Reason Code Type: system
```

The following abridged screen shows Page 2 for agent-loginID 20001. Note that the Skill Number (**SN**) has been set to 1.

```
change agent-loginID 20001                                    Page   2 of   2
                                AGENT LOGINID
     Direct Agent Skill:                              Service Objective? n
Call Handling Preference: skill-level               Local Call Preference? n

    SN   RL SL          SN   RL SL
 1: 1       1       16:                 31:                 46:
 2:                 17:                 32:                 47:
 3:                 18:                 33:                 48:
```

To enable a telephone or one-X® Agent client to log in with the agent-loginID shown above, ensure that **Expert Agent Selection (EAS) Enabled** is set to **y** as shown in the screen below.

```
change system-parameters features                             Page  11 of  19
                        FEATURE-RELATED SYSTEM PARAMETERS
CALL CENTER SYSTEM PARAMETERS
  EAS
         Expert Agent Selection (EAS) Enabled? y
        Minimum Agent-LoginID Password Length: 4
```


©2021 Avaya Inc. All Rights Reserved.

5.10. Public Numbering

In the reference configuration, the public-unknown-numbering form, (used in conjunction with the **Numbering Format: public** setting in **Section 5.8.1.2**), is used to convert Communication Manager local extensions to Verizon public numbers, for inclusion in any SIP headers directed to the Verizon Business IPCC Services via the public trunk.

Step 1 - Enter **change public-unknown-numbering 5 ext-digits xxxxx**, where xxxxx is the 5-digit extension number to change.

Step 2 - Add each Communication Manager Vector Directory Numbers (VDN) and their corresponding Verizon DNIS numbers (for the public trunk to Verizon). Communication Manager will insert these Verizon DNIS numbers in E.164 format into the From, Contact, and PAI headers as appropriate:

- **Ext Len** – Enter the total number of digits in the local extension range (e.g., **5**).
- **Ext Code –** Enter a Communication Manager extension (e.g., **10001**).
- **Trk Grp(s)** – Enter the number of the Public trunk group (e.g., **2**).
- **Private Prefix** – Enter the corresponding Verizon DNIS number (e.g., **18668523221**).
- **Total Len** – Enter the total number of digits after the digit conversion (e.g., **11**).

```
change public-unknown-numbering 0                              Page   1 of   2
                     NUMBERING - PUBLIC/UNKNOWN FORMAT
                                          Total
Ext Ext           Trk       CPN            CPN
Len Code          Grp(s)    Prefix         Len
                                                 Total Administered: 16
 5  10001         2         18668523221    11       Maximum Entries: 240
 5  10003         2         18668510107    11
 5  10004         2         18668502380    11    Note: If an entry applies to
```

Note – Without this configuration, calls to the VDNs would result in a 5-digit user portion of the Contact header in the 183 with SDP and 200 OK returned to Verizon. Although this did not present any user-perceivable problem in the sample configuration, the configuration in the bolded rows above illustrate how to cause Communication Manager to populate the Contact header with user portions that correspond with a Verizon Business IPCC number. In the course of the testing, multiple Verizon toll-free numbers were associated with different Communication Manager extensions and functions.

©2021 Avaya Inc. All Rights Reserved.

5.11. Private Numbering

In the reference configuration, the private-numbering form, (used in conjunction with the **Numbering Format: private** setting in **Section 5.8.2.2**), is used to send Communication Manager local extension numbers to Session Manager, for inclusion in any SIP headers directed to SIP endpoints and Messaging.

Step 1 - Add all Communication Manager local extension patterns (for the local trunk).

- **Ext Len** – Enter the total number of digits in the local extension range (e.g., **5**).
- **Ext Code –** Enter the Communication Manager extension patterns defined in the Dial Plan in **Section 6.3** (e.g., **14** and **20**).
- **Trk Grp(s)** – Enter the number of the Local trunk group (e.g., **3**).
- **Total Len** - Enter the total number of digits after the digit conversion (e.g., **5**).

```
change private-numbering 0                                      Page   1 of   2
                           NUMBERING - PRIVATE FORMAT

Ext Ext            Trk        Private          Total
Len Code           Grp(s)     Prefix           Len
 5  10             3                           5     Total Administered: 6
 5  11             3                           5        Maximum Entries: 540
 5  12             3                           5
 5  14             3                           5
 5  20             3                           5
```


©2021 Avaya Inc. All Rights Reserved.

5.12. Route Pattern for Calls within the CPE

This form defines the Route pattern for the local SIP trunk, based on the route-pattern selected by the AAR table in **Section 5.13** (e.g., calls to Avaya SIP telephone extensions or Messaging).

Step 1 - Enter the **change route-pattern 3** command and enter the following:

- In the **Grp No** column enter **3** for SIP trunk 3 (local trunk).
- In the **FRL** column enter **0** (zero).
- In the **Numbering Format** column, across from line **1**, enter **lev0-pvt**.

```
change route-pattern 3                                          Page   1 of   3
                  Pattern Number: 3      Pattern Name: ToSM Enterprise
    SCCAN? n    Secure SIP? n     Used for SIP stations? y
    Primary SM: SM              Secondary SM:
    Grp FRL NPA Pfx Hop Toll No.  Inserted                          DCS/ IXC
    No          Mrk Lmt List Del  Digits                            QSIG
                            Dgts                                    Intw
 1: 3    0                                                           n   user
 2:                                                                  n   user
 3:                                                                  n   user

     BCC VALUE  TSC CA-TSC    ITC BCIE Service/Feature PARM Sub  Numbering LAR
    0 1 2 M 4 W     Request                                Dgts Format
1: y y y y y n  n            rest                                lev0-pvt  none
```

5.13. Automatic Alternate Routing (AAR) Dialing

AAR is used for outbound calls within the CPE.

Step 1 - Enter the **change aar analysis 0** command and enter the following:

- **Dialed String -** In the reference configuration all SIP telephones used extensions in the range 50xxx, therefore enter **50**.
- **Min** & **Max** – Enter **5**
- **Route Pattern** – Enter **3**
- **Call Type** – Enter **lev0**

Step 2 - Repeat **Step 1**, and create entries for other different SIP extension ranges, Messaging access extension**,** etc. as needed.

```
change aar analysis 0                                           Page   1 of   2
                           AAR DIGIT ANALYSIS TABLE
                                 Location: all            Percent Full: 1

          Dialed           Total     Route    Call   Node  ANI
          String          Min  Max  Pattern   Type   Num   Reqd
    50                    5    5     3        lev0         n
```


©2021 Avaya Inc. All Rights Reserved.

5.14. Avaya G430 Media Gateway Provisioning

In the reference configuration, a G430 Media Gateway is provisioned. The G430 is located in the Main site and is used for local DSP resources, announcements, Music On Hold, etc.

Note – Only the Media Gateway provisioning associated with the G430 registration to Communication Manager is shown below. For additional information on G430 provisioning, see [**7**] on the References section.

Step 1 - Use SSH to connect to the G430 (not shown). Note that the Media Gateway prompt will contain "???" if the Media Gateway is not registered to Communication Manager (e.g., ***G430-???(super)#***).

Step 2 - Enter the **show system** command and copy down the G430 serial number.

Step 3 - Enter the **set mgc list x.x.x.x** command where x.x.x.x is the IP address of the Communication Manager Processor Ethernet (e.g., **10.64.91.75**, see **Section 5.4**).

Step 4 - Enter the **copy run start** command to save the G430 configuration.

Step 5 - **From** Communication Manager SAT, enter **add media-gateway x** where x is an available Media Gateway identifier (e.g., **1**).

Step 6 - On the Media Gateway form (not shown), enter the following parameters:

- Set **Type** = **g430**.
- Set **Name** = a descriptive name (e.g., **G430-1**).
- Set **Serial Number** = enter the serial number copied from **Step 2**.
- Set the **Link Encryption Type** parameter as desired (**any-ptls/tls** was used in the reference configuration).
- Set **Network Region** = **1**.

Wait a few minutes for the G430 to register to Communication Manager. When the Media Gateway registers, the G430 SSH connection prompt will change to reflect the Media Gateway Identifier assigned in **Step 5** (e.g., ***G430-001(super)#***).

Step 7 - Enter the **display media-gateway 1** command and verify that the G430 has registered.

```
display media-gateway 1                                        Page   1 of   2
                            MEDIA GATEWAY 1

                    Type: g430
                    Name: G430-1
              Serial No: 11IS31439520
   Link Encryption Type: any-ptls/tls       Enable CF? n
         Network Region: 1                   Location: 1
        Use for IP Sync? n                  Site Data:
          Recovery Rule: none

             Registered?  y
  FW Version/HW Vintage: 41 .34  .1  /1
       MGP IPV4 Address: 10.64.91.91
       MGP IPV6 Address:
  Controller IP Address: 10.64.91.75
            MAC Address: 00:1b:4f:53:37:69

  Mutual Authentication? optional
```


©2021 Avaya Inc. All Rights Reserved.

5.15. Avaya Aura® Media Server Provisioning

In the reference configuration, an Avaya Aura® Media Server is provisioned. The Media Server is located in the Main site and is used, along with the G430 Media Gateway, for local DSP resources, announcements, and Music On Hold.

Note – Only the Media Server provisioning associated with Communication Manager is shown below. See [**8**] and [**9**] on the Additional References section for additional information.

Step 1 - Access the Media Server Element Manager web interface by typing "**https://x.x.x.x:8443**" (where x.x.x.x is the IP address of the Media Server) (not shown).

Step 2 - On the Media Server Element Manager, navigate to **Home → System Configuration → Signaling Protocols → SIP →Node and Routes** and add the Communication Manager Procr interface IP address (e.g., **10.64.91.75**, see **Section 5.4**) as a trusted node (not shown).

Step 3 - On Communication Manager, enter the **add signaling-group x** command where x is an unused signaling group (e.g., **80**), and provision the following:

- **Group Type** – Set to **sip**.
- **Transport Method** – Set to **tls**
- Verify that **Peer Detection Enabled?** – Set to **n**.
- **Peer Server** to **AMS**.
- **Near-end Node Name** – Set to the node name of the **procr** noted in **Section 5.4**.
- **Far-end Node Name** – Set to the node name of Media Server as administered in **Section 5.4** (e.g., **AMS**).
- **Near-end Listen Port** and **Far-end Listen Port** – Set to **5061**.
- **Far-end Network Region** – Set the IP network region to **1**, as set in **Section 5.7.1**.
- **Far-end Domain** – Automatically populated with the IP address of the Media Server.

```
add signaling-group 80                                          Page   1 of   2
                              SIGNALING GROUP

 Group Number: 80              Group Type: sip
                         Transport Method: tls


  Peer Detection Enabled? n  Peer Server: AMS



   Near-end Node Name: procr                Far-end Node Name: AMS
 Near-end Listen Port: 5061               Far-end Listen Port: 5061
                                       Far-end Network Region: 1

Far-end Domain: 10.64.91.86
```


©2021 Avaya Inc. All Rights Reserved.

Step 4 - On Communication Manager, enter the **add media-server x** command where x is an available Media Server identifier (e.g., **1**). Enter the following parameters:

- Signaling **Group** – Enter the signaling group previously configured for Media Server (e.g., **80**).
- **Voip Channel License Limit** – Enter the number of VoIP channels for this Media Server (based on licensing) (e.g., **300**).
- **Dedicated Voip Channel Licenses** – Enter the number of VoIP channels licensed to this Media Server (e.g., **300**)
- Remaining fields are automatically populated based on the signaling group provisioning for the Media Server.

```
add media-server 1                                              Page   1 of   1
                                MEDIA SERVER

                    Media Server ID: 1

                    Signaling Group: 80
         Voip Channel License Limit: 300
    Dedicated Voip Channel Licenses: 300

                         Node Name: AMS
                     Network Region: 1
                           Location: 1
          Announcement Storage Area: ANNC-be99ad1a-1f39-41e5-ba04-000c29f8f3f3
```

5.16. Save Translations

After the Communication Manager provisioning is completed, enter the command **save translation**.

©2021 Avaya Inc. All Rights Reserved.

5.17. Verify TLS Certificates – Communication Manager

Note – Testing was done with System Manager signed identity certificates. The procedure to create and obtain these certificates is outside the scope of these Application Notes.

In the reference configuration, TLS transport is used for the communication between Session Manager and Communication Manager. The following procedures show how to verify the certificates used by Communication Manager.

Step 1 - **From** a web browser, type in "https://<ip-address>", where "<ip-address>" is the IP address or FQDN of Communication Manager. Follow the prompted steps to enter appropriate **Logon ID** and **Password** credentials to log in (not shown).

Step 2 - **Click** on **Administration** at the top of the page and select **Server (Maintenance)** (not shown). Click on **Security → Trusted Certificate** and verify the System Manager CA certificate is present in the Communication Manager trusted repository.



Step 3 - Click on **Security → Server/Application Certificates** and verify the server identity certificate, signed by the System Manager CA is present in the Communication Manager certificate repository.



©2021 Avaya Inc. All Rights Reserved.

6. Configure Avaya Aura® Session Manager

This section provides the procedures for configuring Session Manager to process inbound and outbound calls between Communication Manager and the Avaya SBCE. In the reference configuration, all Session Manager provisioning is performed via System Manager.

- Define a SIP Domain.
- Define a Location for Customer Premises Equipment (CPE).
- Configure the Adaptation Modules that will be associated with the SIP Entities for Communication Manager and the Avaya SBCE.
- Define SIP Entities corresponding to Session Manager, Communication Manager, the Avaya SBCE, Messaging and Experience Portal.
- Define Entity Links describing the SIP trunks between Session Manager, Communication Manager, Messaging and Experience Portal, as well as the SIP trunks between the Session Manager and the Avaya SBCE.
- Define Routing Policies associated with the Communication Manager, Messaging, Experience Portal and the Avaya SBCE.
- Define Dial Patterns, which govern which Routing Policy will be selected for inbound and outbound call routing.
- Verify TLS Certificates.

Note – These Application Notes assume that basic System Manager and Session Manager administration has already been performed. Consult [**1**] - [**4**] in the Additional References section for further details.

©2021 Avaya Inc. All Rights Reserved.

6.1. System Manager Login and Navigation

Session Manager configuration is accomplished by accessing the browser-based GUI of System Manager, using the URL **http://<ip-address>/SMGR**, where **<ip-address>** is the IP address of System Manager. In the **Log On** screen (not shown), enter appropriate **User ID** and **Password** and press the **Log On** button. Once logged in, **Home** screen is displayed. From the **Home** screen, under the **Elements** heading, select **Routing**.



The navigation tree displayed in the left pane below will be referenced in subsequent sections to navigate to items requiring configuration. Most items discussed in this section will be located under the **Routing** element shown below.



©2021 Avaya Inc. All Rights Reserved.

6.2. SIP Domain

Step 1 - Select **Domains** from the left navigation menu. In the reference configuration, domain **avayalab.com** was defined.

Step 2 - Click **New**. Enter the following values and use default values for remaining fields.

- **Name:** Enter the enterprise SIP Domain Name. In the sample screen below, **avayalab.com** is shown.
- **Type:** Verify **sip** is selected.
- **Notes:** Add a brief description.

Step 3 - Click **Commit** to save.



6.3. Locations

Locations are used to identify logical and/or physical locations where SIP Entities reside. In the reference configuration, two Locations are specified:

- **Main** – The customer site containing System Manager, Session Manager, Communication Manager and local SIP endpoints.
- **Common-SBCs** – Avaya SBCE

6.3.1 Main Location

Step 1 - Select **Locations** from the left navigational menu. Click **New** (not shown). In the **General** section, enter the following values and use default values for remaining fields.

- **Name:** Enter a descriptive name for the Location (e.g., **Main**).
- **Notes:** Add a brief description.

Step 2 – Default values are used on all the remaining fields.

Step 3 - Click **Commit** to save.

©2021 Avaya Inc. All Rights Reserved.



6.3.2 Common-SBCs Location

To configure the Avaya SBCE Location, repeat the steps in **Section 6.3.1** with the following changes:

- **Name –** Enter a descriptive name (e.g., **Common-SBCs**).

©2021 Avaya Inc. All Rights Reserved.

6.4. Configure Adaptations

Session Manager can be configured to use Adaptation Modules to convert SIP headers sent from Verizon to Communication Manger.

- Calls from Verizon - Modification of SIP messages sent to Communication Manager extensions/VDNs. The Verizon called number digit string in the Request URI is replaced with the associated Communication Manager extensions defined for Agent skill queue VDNs/telephones.

6.4.1 Adaptation for Avaya Aura® Communication Manager Extensions

The Adaptation administered in this section is used for modification of SIP messages to Communication Manager extensions from Verizon.

Step 1 - In the **left** pane under **Routing**, click on **Adaptations**. In the **Adaptations** page, click on **New** (not shown).

Step 2 - In the **Adaptation Details** page, enter:

1. A descriptive **Name**, (e.g., **CM-TG2-VzIPCC**).
2. Select **DigitConversionAdapter** from the **Module Name** drop down.
3. Select **Name-Value Parameter** from the **Module Parameter Type** drop down:
   - **Name**: **fromto** **Value**: **true**
     - This adapts the From and To headers along with the Request-Line and PAI headers.
   - **Name**: **osrcd** **Value**: **avayalab.com**
     - This enables the source domain to be overwritten with “avayalab.com”. For example, for inbound PSTN calls from Verizon to Communication Manager, the PAI header will contain “avayalab.com”.

Note – Depending on the Communication Manager configuration, it may not be necessary for Session Manager to adapt the domain in this fashion.



©2021 Avaya Inc. All Rights Reserved.

Step 3 - Scroll down to the **Digit Conversion for Outgoing Calls from SM** section (the inbound toll-free numbers from Verizon that need to be replaced with their associated Communication Manager extensions before being sent to Communication Manager).

Example – destination extension: 8668502380 is a DNIS string sent in the Request URI by the Verizon Business IPCC Services that is associated with Communication Manager VDN 10004.

- Enter **8668502380** in the **Matching Pattern** column.
- Enter **10** in the **Min/Max** columns.
- Enter **10** in the **Delete Digits** column.
- Enter **10004** in the **Insert Digits** column.
- Specify that this should be applied to the SIP **destination** headers in the **Address to modify** column.
- Enter any desired notes.

Step 4 - **Repeat Step 3** for all additional Verizon DNIS numbers/Communication manager extensions.

Step 5 - Click on **Commit**.

Note – No **Digit Conversion for Incoming Calls to SM** were required in the reference configuration.

Digit Conversion for Outgoing Calls from SM

Add | Remove

6 Items | Filter: Enable

Matching Pattern	Min	Max	Phone Context	Delete Digits	Insert Digits	Address to modify	Adaptation Data	Notes
* +	* 12	* 12		* 2		origination		E.164 Calling Number Conversion
* 8668502380	* 10	* 10		* 10	10004	destination		Call Center
* 8668506850	* 10	* 10		* 10	14000	destination		DTMF Test
* 8668510107	* 10	* 10		* 10	10003	destination		REFER with UUI
* 8668512649	* 10	* 10		* 10	12003	destination		Refer-To Target of UUI Test VDN
* 8668523221	* 10	* 10		* 10	10001	destination		Refer-To PSTN Test VDN

Select : All, None

©2021 Avaya Inc. All Rights Reserved.

6.4.2 Adaptation for the Verizon Business IPCC Services

The Adaptation administered in this section is used for modification of SIP messages from Communication Manager to Verizon. Repeat the steps in **Section 6.4.1** with the following changes.

Step 1 - In the **Adaptation Details** page, enter:

1. A descriptive **Name**, (e.g., **SBC1-Adaptation for Verizon**).
2. Select **VerizonAdapter** from the **Module Name** drop down menu.

Step 2 - In the **Module Parameter Type** field select **Name-Value Parameter** from the menu.

Step 3 - In the **Name-Value Parameter** table, enter the following:

1. **Name** – Enter **eRHdrs**
   - **Value** – Enter the following Avaya headers to be removed by Session Manager. **"AV-Global-Session-ID, Alert-Info, Endpoint-View, P-AV-Message-Id, P-Charging-Vector, P-Location, AV-Correlation-ID, Av-Secure-Indication"**



6.5. SIP Entities

In this section, SIP Entities are administered for the following SIP network elements:

- Session Manager (**Section 6.5.1**).
- Communication Manager for Verizon trunk access (**Section 6.5.2**) – This entity, and its associated Entity Link (using TLS with port 5071), is for calls from Verizon and Communication Manager via the Avaya SBCE.
- Communication Manager for local trunk access (**Section 6.5.3**) – This entity, and its associated Entity Link (using TLS with port 5061), is primarily for traffic between Avaya SIP telephones and Communication Manager, as well as calls to Messaging.
- Avaya SBCE (**Section 6.5.4**) – This entity, and its associated Entity Link (using TLS and port 5061), is for calls from the Verizon Business IPCC Services via the Avaya SBCE.
- Messaging (**Section 6.5.5**) – This entity, and its associated Entity Link (using TLS and port 5061), is for calls to/from Messaging.
- Experience Portal (**Section 6.5.6**) – This entity, and its associated Entity Link (using TLS and port 5061), is for calls to/from Experience Portal.

©2021 Avaya Inc. All Rights Reserved.

Note – In the reference configuration, TLS is used as the transport protocol between Session Manager and Communication Manager (ports 5061 and 5071), and to the Avaya SBCE (port 5061). The connection between the Avaya SBCE and the Verizon Business IPCC Services uses UDP/5072 per Verizon requirements.

6.5.1 Avaya Aura® Session Manager SIP Entity

Step 1- In the left pane under **Routing**, click on **SIP Entities**. In the **SIP Entities** page click on **New** (not shown).

Step 2 - In the **General** section of the **SIP Entity Details** page, provision the following:

- **Name –** Enter a descriptive name (e.g., **Session Manager**).
- **FQDN or IP Address –** Enter the IP address of Session Manager signaling interface, (*not* the management interface), provisioned during installation (e.g., **10.64.91.81**).
- **Type –** Verify **Session Manager** is selected.
- **Location** – Select location **Main** (**Section 6.3.1**).
- **Outbound Proxy** – (Optional) Leave blank or select another SIP Entity. For calls to SIP domains for which Session Manager is not authoritative, Session Manager routes those calls to this **Outbound Proxy** or to another SIP proxy discovered through DNS if **Outbound Proxy** is not specified.
- **Time Zone** – Select the time zone in which Session Manager resides.
- **Minimum TLS Version** – Select the TLS version, or select **Use Global Settings** to use the default TLS version, configurable at the global level (**Elements→Session Manager→Global Settings**).

Step 3 - In the **Monitoring** section of the **SIP Entity Details** page configure as follows:

- Select **Use Session Manager Configuration** for **SIP Link Monitoring** field.
- Use the default values for the remaining parameters.



©2021 Avaya Inc. All Rights Reserved.

Step 4 - Scrolling down to the **Listen Port** section of the **SIP Entity Details** page. This section defines a default set of ports that Session Manager will use to listen for SIP requests, typically from registered SIP endpoints. Session Manager can also listen on additional ports defined elsewhere such as the ports specified in the SIP Entity Link definition in **Section 6.6**. Click on **Add** and provision entries as follows:

- **Port –** Enter **5061**
- **Protocol –** Select **TLS**
- **Default Domain –** Select a SIP domain administered in **Section 6.2** (e.g., **avayalab.com**)
- Check **Endpoint**.

Step 5 - **Repeat Step 4** to provision entries for any other listening ports used by Session Manager, for example:

- **5060** for **Port** and **TCP** for **Protocol**
- **5060** for **Port** and **UDP** for **Protocol**

Step 6 - Enter any notes as desired and leave all other fields on the page blank/default.

Step 7 - Click on **Commit**.



Note – The **Entity Links** section of the form (not shown) will be automatically populated when the Entity Links are defined in **Section 6.6**. The **SIP Responses to an OPTIONS Request** section of the form is not used in the reference configuration.

©2021 Avaya Inc. All Rights Reserved.

6.5.2 Avaya Aura® Communication Manager SIP Entity – Public Trunk

Step 1 - In the **SIP Entities** page, click on **New** (not shown).

Step 2 - In the **General** section of the **SIP Entity Details** page, provision the following:

- **Name –** Enter a descriptive name (e.g., **CM-TG2**).
- **FQDN or IP Address –** Enter the IP address of Communication Manager Processor Ethernet (procr) described in **Section 5.4** (e.g., **10.64.91.75**).
- **Type –** Select **CM**.
- **Adaptation –** Select the Adaptation **CM-TG2-VzIPCC** administered in **Section 6.4.1**.
- **Location** – Select a Location **Main** administered in **Section 6.3.1**.
- **Time Zone** – Select the time zone in which Communication Manager resides.
- In the **SIP Link Monitoring** section of the **SIP Entity Details** page select:
  - Select **Use Session Manager Configuration** for **SIP Link Monitoring** and the **CRLF Keep Alive Monitoring** fields. Use the default values for the remaining parameters.

Step 3 - Click on **Commit**.



©2021 Avaya Inc. All Rights Reserved.

6.5.3 Avaya Aura® Communication Manager SIP Entity – Local Trunk

To configure the Communication Manager Local trunk SIP Entity, repeat the steps in **Section 6.5.2** with the following changes:

- **Name –** Enter a descriptive name (e.g., **CM-TG3**).
- **Adaptations** – Leave this field blank.

6.5.4 Avaya Session Border Controller for Enterprise SIP Entity

Repeat the steps in **Section 6.5.2** with the following changes:

- **Name –** Enter a descriptive name (e.g., **SBC1**).
- **FQDN or IP Address –** Enter the IP address of the A1 (private) interface of the Avaya SBCE (e.g., **10.64.91.50**, see **Section 8.5**).
- **Type –** Select **SIP Trunk**.
- **Adaptations –** Select Adaptation **SBC1-Adaptation for Verizon** (**Section 6.4.2**).
- **Location –** Select Location **Common-SBCs** administered in **Section 6.3.2**

6.5.5 Avaya Messaging SIP Entity

Repeat the steps in **Section 6.5.2** with the following changes:

- **Name –** Enter a descriptive name (e.g., **Aura Messaging**).
- **FQDN or IP Address –** Enter the IP address of Messaging (e.g., **10.64.91.145**).
- **Type –** Select **Messaging**.
- **Adaptations –** Leave this field blank.

6.5.6 Avaya Experience Portal SIP Entity

Repeat the steps in **Section 6.5.2** with the following changes:

- **Name –** Enter a descriptive name (e.g., **ExperiencePortal**).
- **FQDN or IP Address –** Enter the IP address of Experience Portal (e.g., **10.64.91.90**).
- **Type –** Select **Voice Portal**.
- **Adaptations –** Leave this field blank.

©2021 Avaya Inc. All Rights Reserved.

6.6. Entity Links

In this section, Entity Links are administered for the following connections:

- Session Manager to Communication Manager Public trunk (**Section 6.6.1**).
- Session Manager to Communication Manager Local trunk (**Section 6.6.2**).
- Session Manager to Avaya SBCE (**Section 6.6.3**).
- Session Manager to Messaging (**Section 6.6.4**).
- Session Manager to Experience Portal (**Section 6.6.5**).

Note – Once the Entity Links have been committed, the link information will also appear on the associated SIP Entity pages configured in **Section 6.5**.

6.6.1 Entity Link to Avaya Aura® Communication Manager – Public Trunk

Step 1 - In the left pane under **Routing**, click on **Entity Links**, then click on **New** (not shown).

Step 2 - Continuing in the **Entity Links** page, provision the following:

- **Name** – Enter a descriptive name for this link to Communication Manager (e.g., **SM to CM TG2**).
- **SIP Entity 1** – Select the SIP Entity administered in **Section 6.5.1** for Session Manager (e.g., **Session Manager**).
- **Protocol** – Select **TLS** (see **Section 5.8.1**).
- SIP Entity 1 **Port** – Enter **5071**.
- **SIP Entity 2** – Select the SIP Entity administered in **Section 6.5.2** for the Communication Manager public entity (e.g., **CM-TG2**).
- SIP Entity 2 **Port** – Enter **5071** (see **Section 5.8.1**).
- **Connection Policy** – Select **trusted**.
- Leave other fields as default.

Step 3 - Click on **Commit**.



6.6.2 Entity Link to Avaya Aura® Communication Manager – Local Trunk

To configure this Entity Link, repeat the steps in **Section 6.6.1**, with the following changes:

- **Name** – Enter a descriptive name for this link to Communication Manager (e.g., **SM to CM TG3**).
- SIP Entity 1 **Port** – Enter **5061**.
- **SIP Entity 2** – Select the SIP Entity administered in **Section 6.5.3** for the Communication Manager local entity (e.g., **CM-TG3**).
- SIP Entity 2 **Port** – Enter **5061** (see **Section 5.8.12**).

©2021 Avaya Inc. All Rights Reserved.

6.6.3 Entity Link for the Verizon Business IPCC Services via the Avaya SBCE

To configure this Entity Link, repeat the steps in **Section 6.6.1**, with the following changes:

- **Name** – Enter a descriptive name for this link to the Avaya SBCE (e.g., **SM to SBC1**).
- SIP Entity 1 **Port** – Enter **5061**.
- **SIP Entity 2** – Select the SIP Entity administered in **Section 6.5.4** for the Avaya SBCE entity (e.g., **SBC1**).
- SIP Entity 2 **Port** – Enter **5061**.

6.6.4 Entity Link to Avaya Messaging

To configure this Entity Link, repeat the steps in **Section 6.6.1**, with the following changes:

- **Name** – Enter a descriptive name for this link to Messaging (e.g., **SM to AAM**).
- SIP Entity 1 **Port** – Enter **5061**.
- **SIP Entity 2** – Select the SIP Entity administered in **Section 6.5.5** for the Messaging entity (e.g., **Aura Messaging**).
- SIP Entity 2 **Port** – Enter **5061**.

6.6.5 Entity Link to Avaya Experience Portal

To configure this Entity Link, repeat the steps in **Section 6.6.1**, with the following changes:

- **Name** – Enter a descriptive name for this link to Messaging (e.g., **SM to ExperiencePortal**).
- **SIP Entity 1 Port** – Enter **5061**.
- **SIP Entity 2** – Select the SIP Entity administered in **Section 6.5.6** for the Experience Portal entity (e.g., **ExperiencePortal**).
- **SIP Entity 2 Port** – Enter **5061**.

6.7. Time Ranges

Step 1 - In the left pane under **Routing**, click on **Time Ranges**. In the **Time Ranges** page click on **New** (not shown).

Step 2 - Continuing in the **Time Ranges** page, enter a descriptive **Name**, check the checkbox(s) for the desired day(s) of the week, and enter the desired **Start Time** and **End Time**.

Step 3 - Click on **Commit** (not shown). Repeat these steps to provision additional time ranges as required.



©2021 Avaya Inc. All Rights Reserved.

6.8. Routing Policies

In this section, the following Routing Policies are administered:

- Inbound calls to Communication Manager extensions (**Section 6.8.1**).
- Inbound calls to Avaya Messaging (**Section 6.8.2**).
- Inbound calls to Experience Portal (**Section 6.8.3**).

6.8.1 Routing Policy for Verizon Routing to Avaya Aura® Communication Manager

This Routing Policy is used for inbound calls from Verizon.

Step 1 - In the left pane under **Routing**, click on **Routing Policies**. In the **Routing Policies** page click on **New** (not shown).

Step 2 - In the **General** section of the **Routing Policy Details** page, enter a descriptive **Name** for routing Verizon calls to Communication Manager (e.g., **To CM TG2**), and ensure that the **Disabled** checkbox is unchecked to activate this Routing Policy.

Step 3 - In the **SIP Entity as Destination** section of the **Routing Policy Details** page, click on **Select** and the **SIP Entities** list page will open.



Step 4 - In the **SIP Entities** list page, select the SIP Entity administered in **Section 6.5.2** for the Communication Manager public SIP Entity (**CM-TG2**), and click on **Select**.



©2021 Avaya Inc. All Rights Reserved.

Step 5 - Returning to the **Routing Policy Details** page in the **Time of Day** section, click on **Add**.
Step 6 - In the **Time Range List** page (not shown), check the checkbox(s) corresponding to one or more Time Ranges administered in **Section 6.7**, and click on **Select**.
Step 7 - Returning to the **Routing Policy Details** page in the **Time of Day** section, enter a **Ranking** of **0**.
Step 8 - No **Regular Expressions** were used in the reference configuration.
Step 9 - Click on **Commit**.

Note – Once the **Dial Patterns** are defined (**Section 6.9**) they will appear in the **Dial Pattern** section of this form.



6.8.2 Routing Policy for Inbound Routing to Avaya Messaging

This routing policy is for inbound calls to Avaya Messaging for message retrieval. Repeat the steps in **Section 6.8.1** with the following differences:

- Enter a descriptive **Name** (e.g., **To Messaging**), and ensure that the **Disabled** checkbox is unchecked to activate this Routing Policy.
- In the **SIP Entities** list page, select the SIP Entity administered in **Section 6.5.5** for Messaging (e.g., **Avaya Messaging**).

6.8.3 Routing Policy for Inbound Calls to Experience Portal

This routing policy is for inbound calls to Experience Portal. Repeat the steps in **Section 6.8.1** with the following differences:

- Enter a descriptive **Name** (e.g., **To Experience Portal**), and ensure that the **Disabled** checkbox is unchecked to activate this Routing Policy.
- In the **SIP Entities** list page, select the SIP Entity administered in **Section 6.5.6** for Experience Portal (e.g., **ExperiencePortal**).

©2021 Avaya Inc. All Rights Reserved.

6.9. Dial Patterns

In this section, Dial Patterns are administered matching Inbound PSTN calls via the Verizon Business IPCC Services to Communication Manager.

Note – Session Manager release 8.1 incorporates new functionality with the addition of Origination Dial Pattern sets. This configuration is optional. Origination Dial Pattern sets can be created to include digits patterns, that can be matched by Session Manager to make more granular routing decisions, allowing the use of different routes or call restriction for calls arriving to Session Manager from the same Originating Location. This is done by matching the number present on the From header of the call. More information can be found on [**2**] in the References section.

Origination Dial Patterns were not used in the reference configuration.

If Origination Dial Patterns are to be used in the customer configuration, **Enable Flexible Routing** needs to be checked under **Elements → Session Manager → Global Settings**.



©2021 Avaya Inc. All Rights Reserved.

In the reference configuration inbound calls from the Verizon Business IPCC Services sent 10 DNIS digits in the SIP Request URI. The DNIS pattern must be matched for further call processing.

Step 1 - In the left pane under **Routing**, click on **Dial Patterns**. In the **Dial Patterns** page click on **New** (not shown).

Step 2 - In the **General** section of the **Dial Pattern Details** page, provision the following:

- **Pattern** – Enter **8668502380**. Note – The Adaptation defined for Communication Manager in **Section 6.4.1** will convert the various 866-xxx-xxxx toll-free numbers into their corresponding Communication Manager extensions.
- **Min** and **Max** – Enter **10**.
- **SIP Domain** – Select the enterprise SIP domain, e.g., **avayalab.com**.



Step 3 - Scroll down to the **Originating Locations, Origination Dial Pattern Sets, and Routing Policies** section of the **Dial Pattern Details** page and click on **Add**.

©2021 Avaya Inc. All Rights Reserved.

Step 4 - In the **Originating Location**, check the checkbox corresponding to the Avaya SBCE location, e.g., **Common-SBCs**.

Step 5 - In the **Routing Policies** section, check the checkbox corresponding to the Routing Policy administered for routing calls to the Communication Manager public trunk in **Section 6.8.1** (e.g., **To CM TG2**), and click on **Select**.



Step 6 - Returning to the **Dial Pattern Details** page click on **Commit**.

Step 7 - Repeat **Steps 1-6** for any additional inbound dial patterns from Verizon.



©2021 Avaya Inc. All Rights Reserved.

6.10. Verify TLS Certificates – Session Manager

Note – Testing was done with System Manager signed identity certificates. The procedure to obtain and install certificates is outside the scope of these Application Notes.

The following procedures show how to verify the certificates used by Session Manager.

Step 1 - From the **Home** screen, under the **Services** heading, select **Inventory**.



Step 2 - In the left pane under **Inventory**, click on **Manage Elements** and select the Session Manager element, e.g., **Session Manager**. Click on **More Actions → Manage Trusted Certificates**.



©2021 Avaya Inc. All Rights Reserved.

Step 3 - Verify the **System** Manager Certificate Authority certificate is listed in the trusted store, **SECURITY_MODULE_SIP**. Click **Done** to return to the previous screen.



Step 4 - With **Session Manager** selected, click on **More Actions → Manage Identity Certificates** (not shown).

Step 5 - Verify the **Security Module SIP** service has a valid identity certificate signed by System Manager. If the **Subject Details** and **Subject Alternative Name** fields of the System Manager signed certificate need to be updated, click **Replace**, otherwise click **Done** (not shown).



©2021 Avaya Inc. All Rights Reserved.

7. Avaya Experience Portal

These Application Notes assume that the necessary Experience Portal licenses have been installed and basic Experience Portal administration has already been performed. Consult [**14**] and [**15**] in the Additional References section for further details if necessary.

7.1. Background

Experience Portal consists of one or more Media Processing Platform (MPP) servers and an Experience Portal Manager (EPM) server. A single "server configuration" was used in the reference configuration. This consisted of a single MPP and EPM, running on a VMware environment, including an Apache Tomcat Application Server (hosting the Voice XML (VXML) and/or Call Control XML (CCXML) application scripts), that provide the directives to Experience Portal for handling the inbound calls.

References to the Voice XML and/or Call Control XML applications are administered on Experience Portal, along with one or more called numbers for each application reference. When an inbound call arrives at Experience Portal, the called party DNIS number is matched against those administered called numbers. If a match is found, then the corresponding application is accessed to handle the call. If no match is found, Experience Portal informs the caller that the call cannot be handled, and disconnects the call[1].

For the sample configuration described in these Application Notes, a simple VXML test application was used to exercise various SIP call flow scenarios with the Verizon IPCC service. In production, enterprises can develop their own VXML and/or CCXML applications to meet specific customer self-service needs, or consult Avaya Professional Services and/or authorized Avaya Business Partners. The development and deployment of VXML and CCXML applications is beyond the scope of these Application Notes.

[1] An application may be configured with "inbound default" as the called number, to process all inbound calls that do not match any other application references.

©2021 Avaya Inc. All Rights Reserved.

7.2. Logging In and Licensing

This section describes the steps on Experience Portal for administering a SIP connection to the Session Manager.

Step 1 - Launch a web browser, enter http://<IP address of the Avaya EPM server>/ in the URL, log in with the appropriate credentials and the following screen is displayed.

Note – All page navigation described in the following sections will utilize the menu shown on the left pane of the screenshot below.



Step 2 - In the left pane, navigate to **Security→Licensing**. On the **Licensing** page, verify that Experience Portal is properly licensed. If required licenses are not enabled, contact an authorized Avaya account representative to obtain the licenses.



©2021 Avaya Inc. All Rights Reserved.

7.3. Verify TLS Certificates – Experience Portal

In the reference configuration, TLS transport is used for the communication between Session Manager and Experience Portal. Follow the steps below to verify the certificates used by Experience Portal.

Note – Testing was done with System Manager signed identity certificates. The procedure to create and obtain these certificates is outside the scope of these Application Notes.

Step 1 – In the left pane, navigate to **Security → Certificates**. On the **Trusted Certificates** tab, verify the System Manager CA certificate is present in the certificate repository.



Step 2 – Select the **EP Signing Certificate → Certificate tab** and verify the server identity certificate, signed by the System Manager CA is present.



©2021 Avaya Inc. All Rights Reserved.

7.4. VoIP Connection

This section defines a SIP trunk between Experience Portal and Session Manager .

Step 1 - In the left pane, navigate to **System Configuration→VoIP Connections**. On the **VoIP Connections** page, select the **SIP** tab and click **Add** to add a SIP trunk.

Note – Only ***one*** SIP trunk can be active at any given time on Experience Portal.



Step 2 - Configure a SIP connection as follows:

- **Name** – Set to a descriptive name (e.g., **SM8**).
- **Enable** – Set to **Yes**.
- **Proxy Server Transport** – Set to **TLS**.
- Select **Proxy Servers**, and enter:
  - **Proxy Server Address** = **10.64.91.81** (the IP address of the Session Manager signaling interface defined in **Section 6.5.1**).
  - **Port** = **5061**
  - **Priority** = **0** (default)
  - **Weight** = **0** (default)
- **Listener Port** – Set to **5061**.
- **SIP Domain** – Set to **avayalab.com** (see **Section 6.2)**.
- **Consultative Transfer** – Select **REFER**. Consultative Call Transfer using SIP INVITE is not supported on the IPCC service (inbound calls only)
- **SIP Reject Response Code** – Select **ASM (503)**.
- **Maximum Simultaneous Calls** – Set to a number in accordance with licensed capacity. In the reference configuration a value of **10** was used.
- Select **All Calls can be either inbound or outbound**.
- **SRTP Enable** = **Yes**
- **Encryption Algorithm** = **AES_CM_128**
- **Authentication Algorithm** = **HMAC_SHA1_80**
- **RTCP Encryption Enabled** = **No**
- **RTP Authentication Enabled** = **Yes**
- Use default values for all other fields.
- Click **Save**.

©2021 Avaya Inc. All Rights Reserved.



7.5. Speech Servers

The installation and administration of the ASR and TSR Speech Servers are beyond the scope of this document. Some of the values shown below were defined during the Speech Server installations. Note that in the reference configuration the ASR and TTS servers used the same IP address.



©2021 Avaya Inc. All Rights Reserved.

7.6. Application References

This section describes the steps for administering a reference to the VXML and/or CCXML applications residing on the application server. In the sample configuration, the applications were co-resident on one Experience Portal server, with IP Address 10.64.90.91.

Step 1 - In the left pane, navigate to **System Configuration→Applications**. On the **Applications** page (not shown), click **Add** to add an application and configure as follows:

- **Name** – Set to a descriptive name (e.g., **Test-ccxml**).
- **Enable** – Set to **Yes**. This field determines which application(s) will be executed based on their defined criteria.
- **Type** – Select **VoiceXML**, **CCXML**, or **CCXML/VoiceXML** according to the application type.
- **VoiceXML** and/or **CCXML URL** – Enter the necessary URL(s) to access the VXML and/or CCXML application(s) on the application server. In the sample screen below, the Experience Portal test application on a single server is referenced.
- **Speech Servers ASR** and **TTS** – Select the appropriate ASR and/or TTS servers as necessary.
- **Application Launch** – Set to **Inbound**.
- **Called Number** – Enter the number to match against an inbound SIP INVITE message and click **Add**. In the sample configuration illustrated in these Application Notes, the dialed Verizon IPCC toll-free number 866-851-2649 was used. Repeat to define additional called party numbers as needed. Inbound Verizon Business calls with these called party numbers will be handled by the application defined in this section.



©2021 Avaya Inc. All Rights Reserved.

7.7. MPP Servers and VoIP Settings

This section illustrates the procedure for viewing or changing the MPP Settings. In the sample configuration, the MPP Server is co-resident on a single server with the Experience Portal Management server (EPM).

Step 1 - In the left pane, navigate to **System Configuration→MPP Servers** and the following screen is displayed. Click **Add**.



Step 2 - Enter any descriptive name in the **Name** field (e.g., **mpp1**) and the IP address of the MPP server in the **Host Address** field and click **Continue** (not shown).

Step 3 - The certificate page will open. Check the **Trust this certificate** box (not shown). Once complete, click **Save**.



©2021 Avaya Inc. All Rights Reserved.

Step 4 - Click **VoIP Settings** tab on the screen displayed in **Step 1**, and the following screen is displayed.

- In the Port Ranges section, default ports were used.



- In the Codecs section set:
  - Set **Packet Time** to **20**.
  - Verify the **G729 Codec** is enabled.
  - Set **G729 Discontinuous Transmission** to **No** (G.729A).
  - Set the **Offer Order** to the preferred codec. In the sample configuration, **G729** is the first codec, followed by **G711ulaw**, then **G711aLaw**.
- Use default values for all other fields.

Step 5 - Click on **Save**.



©2021 Avaya Inc. All Rights Reserved.

7.8. Configuring RFC2833 Event Value Offered by Experience Portal

The configuration change example noted in this section is not required for any of the call flows illustrated in these Application Notes. For incoming calls from Verizon services to Experience Portal, Verizon specifies the value 101 for the RFC2833 telephone-events that signal DTMF digits entered by the user. When Experience Portal answers, the SDP from Experience Portal matches this Verizon offered value.

When Experience Portal sends an INVITE with SDP as part of an INVITE-based transfer (e.g., bridged transfer), Experience Portal offers the SDP. By default, Experience specifies the value 127 for the RFC2833 telephone-events. Optionally, the value that is offered by Experience Portal can be changed, and this section outlines the procedure that can be performed by an Avaya authorized representative.

- Access Experience Portal via the command line interface.
- Navigate to the following directory: /opt/Avaya/ ExperiencePortal /MPP/config
- Edit the file mppconfig.xml.
- Search for the parameter "mpp.sip.rfc2833.payload". If there is no such parameter specified, add a line such as the following to the file, where the value 101 is the value to be used for the RFC2833 events. If the parameter is already specified in the file, simply edit the value assigned to the parameter.
  <parameter name="mpp.sip.rfc2833.payload">101</parameter>
- In the verification of these Application Notes, the line was added directly above the line where the sip.session.expires parameter is configured.

After saving the file with the change, restart the MPP server for the change to take effect. As shown below, the MPP may be restarted using the **Restart** button available via the Experience Portal GUI at **System Management → MPP Manager**.
Note that the **State** column shows when the MPP is running after the restart.



©2021 Avaya Inc. All Rights Reserved.

8. Configure Avaya Session Border Controller for Enterprise

This section covers the configuration of the Avaya SBCE. It is assumed that the initial provisioning of the Avaya SBCE, including the assignment of the management interface IP Address and license installation have already been completed; hence these tasks are not covered in these Application Notes. For more information on the installation and provisioning of the Avaya SBCE consult the Avaya SBCE documentation in the **Additional References** section.

Use a WEB browser to access the Element Management Server (EMS) web interface, and enter https://*ipaddress*/sbc in the address field of the web browser, where *ipaddress* is the management LAN IP address of the Avaya SBCE. Log in using the appropriate credentials.

The EMS Dashboard page of the Avaya SBCE will appear. Note that the installed software version is displayed. Verify that the **License State** is **OK**. The SBCE will only operate for a short time without a valid license. Contact your Avaya representative to obtain a license.

Note – The provisioning described in the following sections use the menu options listed in the left-hand column shown below.



©2021 Avaya Inc. All Rights Reserved.

8.1. Device Management – Status

Select **Device Management** on the left-hand menu. A list of installed devices is shown on the **Devices** tab on the right pane. In the case of the sample configuration, a single device named **SBCE8-90** is shown. Verify that the **Status** column shows **Commissioned**. If not, contact your Avaya representative. To view the configuration of this device, click **View** on the screen below.

Note – Certain Avaya SBCE configuration changes require that the underlying application be restarted. To do so, click on **Restart Application** shown below.



The **System Information** screen shows the **Network Configuration**, **DNS Configuration** and **Management IP(s)** information provided during installation, corresponding to **Figure 1**. In the shared test environment, the highlighted **A1** and **B1** IP addresses are the ones relevant to the configuration of the SIP trunk to Verizon. Other IP addresses assigned to interfaces **A1** and **B2** on the screen below are used to support remote workers and are not the focus of these Application Notes. Note that the **Management IP** must be on a separate subnet from the IP interfaces designated for SIP traffic.



©2021 Avaya Inc. All Rights Reserved.

8.2. TLS Management

Note – Testing was done with System Manager signed identity certificates. The procedure to create and obtain these certificates is outside the scope of these Application Notes.

In the reference configuration, TLS transport is used for the communication between Session Manager and Avaya SBCE. The following procedures show how to create the client and server profiles to support the TLS connection.

8.2.1 Verify TLS Certificates – Avaya Session Border Controller for Enterprise

To access the SBCE configuration menus, select the SBCE device from the top navigation menu.



Step 1 - Select **TLS Management → Certificates** from the left-hand menu. Verify the following:

- System Manager CA certificate is present in the **Installed CA Certificates** area.
- System Manager CA signed identity certificate is present in the **Installed Certificates** area.
- Private key associated with the identity certificate is present in the **Installed Keys** area.



©2021 Avaya Inc. All Rights Reserved.

8.2.2 Server Profiles

Step 1 - Select **TLS Management → Server Profiles** and click on **Add**. Enter the following:

- **Profile Name:** enter descriptive name.
- **Certificate:** select the identity certificate, e.g., **sbce8_90.pem**, from pull down menu.
- **Peer Verification** = **None**.
- Click **Next**.

Step 2 - Accept default values for the next screen (not shown) and click **Finish**.



The following screen shows the completed TLS **Server Profile** form:



©2021 Avaya Inc. All Rights Reserved.

8.2.3 Client Profiles

Step 1 - Select **TLS Management → Server Profiles** and click on **Add**. Enter the following:

- **Profile Name:** enter descriptive name.
- **Certificate:** select the identity certificate, e.g., **sbce8_90.pem**, from pull down menu.
- **Peer Verification** = **Required**.
- **Peer Certificate Authorities:** select the CA certificate used to verify the certificate received from Session Manager, e.g., **SystemManager8CA.pem**.
- **Verification Depth:** enter **1**. Click **Next**.

Step 2 - Accept default values for the next screen (not shown) and click **Finish**.



The following screen shows the completed TLS **Client Profile** form:



©2021 Avaya Inc. All Rights Reserved.

8.3. Network Management

The Network Management screen is where the network interface settings are configured and enabled. During the installation process of Avaya SBCE, certain network-specific information is defined such as device IP address(es), public IP address(es), netmask, gateway, etc., to interface the device to the network. It is this information that populates the various Network Management tab displays, which can be edited as needed to optimize device performance and network efficiency.

Step 1 - Select **Networks & Flows → Network Management** from the menu on the left-hand side.

Step 2 - The **Interfaces** tab displays the enabled/disabled interfaces. In the reference configuration, interfaces A1 and B1 are used.



Step 3 - Select the **Networks** tab to display the IP provisioning for the A1 and B1 interfaces. These values are normally specified during installation. These can be modified by selecting **Edit**; however, some of these values may not be changed if associated provisioning is in use.

- **A1**: **10.64.91.50** – "Inside" IP address, toward Session Manager.
- **B1: 1.1.1.2** – "Outside" IP address toward the Verizon SIP trunk. This address is known to Verizon.



©2021 Avaya Inc. All Rights Reserved.

8.4. Media Interfaces

Media Interfaces are created to specify the IP address and port range in which the Avaya SBCE will accept media streams on each interface. Packets leaving the interfaces of the Avaya SBCE will advertise this IP address, and one of the ports in this range as the listening IP address and port in which the SBCE will accept media from the connected server. Create a SIP Media Interface for both the inside and outside IP interfaces.

Step 1 - Select **Network & Flows → Media Interface** from the menu on the left-hand side.
Step 2 - Select **Add** (not shown). The **Add Media Interface** window will open. Enter the following:

- **Name**: Enter an appropriate name (e.g., **Inside-Med-50**).
- **IP Address**: Select **Inside-A1 (A1,VLAN0)** and **10.64.91.50** from the drop-down menus.
- **Port Range**: **35000** – **40000**.

Step 3 - Click **Finish**.



Step 4 - Select **Add** (not shown). The **Add Media Interface** window will open. Enter the following:

- **Name**: Enter an appropriate name (e.g., **Vz-Med-B1**).
- **IP Address**: Select **Verizon-B1 (B1,VLAN0)** and **1.1.1.2** from the drop-down menus.
- **Port Range**: **35000** – **40000**.

Step 5 - Click **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.5. Signaling Interfaces

The Signaling Interface screen is where the SIP signaling ports are defined. Avaya SBCE will listen for SIP requests on the defined ports. Create a Signaling Interface for both the inside and outside IP interfaces.

Step 1 - Select **Network & Flows → Signaling Interface** from the menu on the left-hand side.
Step 2 - Select **Add** (not shown) and enter the following:

- **Name**: Enter an appropriate name (e.g., **Inside-Sig-50**).
- **IP Address**: Select **Inside A1 (A1,VLAN0)** and **10.64.91.50**.
- **TLS Port**: **5061**.
- **TLS Profile**: Select the TLS server profile created in **Section 8.2.2** (e.g., **Inside_Server**)

Step 3 - Click **Finish**.



Step 4 - Select **Add** (not shown), and enter the following:

- **Name**: Enter an appropriate name (e.g., **Vz-Sig-B1**).
- **IP Address**: Select **Verizon B1 (B1,VLAN0)** and **1.1.1.2**.
- **UDP Port**: **5060**.

Step 5 - Click **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.6. Server Interworking Profiles

The Server Interworking Profile includes parameters to make the Avaya SBCE function in an enterprise VoIP network using different implementations of the SIP protocol. There are default profiles available that may be used as is, or modified, or new profiles can be configured as described below. Create separate Server Interworking Profiles for the enterprise and the service provider.

8.6.1 Server Interworking Profile – Enterprise

In the sample configuration, the enterprise Server Interworking profile was cloned from the default **avaya-ru** profile and then modified.

Step 1 - Select **Configuration Profiles → Server Interworking** from the left-hand menu.
Step 2 - Select the pre-defined **avaya-ru** profile and click the **Clone** button.
Step 3 - Enter profile name: (e.g., **Enterprise Interwork**), and click **Finish** to continue.



Step 4 - The new Enterprise Interwork profile will be listed. Select it, scroll to the bottom of the Profile screen, and click on **Edit**.
Step 5 - The **General** screen will open.

- Check **T38 Support**.
- All other options can be left with default values. Click **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.6.2 Server Interworking Profile – Verizon

In the sample configuration, the Server Interworking profile for Verizon was created by adding a new profile.

Note – See **Section 13** for additional steps necessary for Experience Portal to redirect calls to Communication Manager using SIP REFER.

Step 1 - Select **Add Profile** and enter a profile name: (e.g., **SIP Provider Interw**) and click **Next** (not shown).

Step 2 - The **General** screen will open (not shown):

- Check **T38 Support**.
- All other options can be left as default.
- Click **Next**.

Step 3 - The **SIP Timers** and **Privacy** screens will open (not shown), accept default values for these screens by clicking **Next**.

Step 4 - The **Advanced/DTMF** screen will open:

- In the **Record Routes** field, check **Both Sides**.
- All other options can be left as default.
- Click **Finish** (not shown).



©2021 Avaya Inc. All Rights Reserved.

8.7. Signaling Manipulation

Signaling Manipulations are SigMa scripts the Avaya SBCE can use to manipulate SIP headers/messages. In the reference configuration, one signaling manipulation script is used.

Note – Use of the Signaling Manipulation scripts require higher processing requirements on the Avaya SBCE. Therefore, this method of header manipulation should only be used in cases where the use of Server Interworking Profiles (**Section 8.6**) or Signaling Rules (**Section 8.13**) does not meet the desired result. Refer to **[11]** in the Additional References section for information on the Avaya SBCE scripting language.

The script can be created externally as a regular text file and pasted in the Signaling Manipulation screen, or they can be written directly in the page using the embedded Sigma Editor.

A Sigma script was created during the compliance test to remove the epv parameter from the outbound Contact header. See **Section 2.3**.

Step 1 - Select **Configuration Profiles → Signaling Manipulation** from the menu on the left.
Step 2 - Click **Add Script** (not shown) and the script editor window will open.
Step 3 - Enter a name for the script in the **Title** box (e.g., **Verizon IPCC Script**). The following script is defined:

```
within session "ALL"
{
 act on message where %DIRECTION="OUTBOUND" and %ENTRY_POINT="POST_ROUTING"
  {
//Remove epv parameter from Contact header to hide internal topology
        remove(%HEADERS["Contact"][1].URI.PARAMS["epv"]);
      }
}
```

Step 4 - **Click** on **Save**. The script editor will test for any errors, and the window will close. This script will be applied to the Verizon Server Configuration later in **Section 8.8.2**.



©2021 Avaya Inc. All Rights Reserved.

8.8. SIP Server Profiles

The **SIP Server Profile** contains parameters to configure and manage various SIP call server-specific parameters such as TCP and UDP port assignments, heartbeat signaling parameters, DoS security statistics, and trusted domains.

8.8.1 SIP Server Profile – Session Manager

This section defines the SIP Server Profile for the Avaya SBCE connection to Session Manager.

Step 1 - Select **Services → SIP Servers** from the left-hand menu.
Step 2 - Select **Add** and the **Profile Name** window will open. Enter a Profile Name (e.g., **SM8**) and click **Next**.



Step 3 - The **Add Server Configuration Profile** window will open.

- Select **Server Type**: **Call Server**.
- **SIP Domain**: Leave blank (default).
- **DNS Query Type**: Select **NONE/A** (default).
- **TLS Client Profile**: Select the profile create in **Section 8.2.3** (e.g., **Inside-Client**).
- **IP Address**: **10.64.91.81** (Session Manager Security Module IP address).
- Select **Port**: **5061**, **Transport**: **TLS**.
- If adding the profile, click **Next** (not shown) to proceed. If editing an existing profile, click **Finish** and proceed to the next tab.



Step 4 – Default values can be used on the **Authentication** tab.

©2021 Avaya Inc. All Rights Reserved.

Step 5 – On the **Heartbeat** tab, check the **Enable Heartbeat** box to have the Avaya SBCE source "heartbeats" toward Session Manager. This configuration is optional.

- Select **OPTIONS** from the **Method** drop-down menu.
- Select the desired frequency that the SBCE will source OPTIONS toward Session Manager.
- Make logical entries in the **From URI** and **To URI** fields that will be used in the OPTIONS headers.



Step 6 – Default values are used on the **Registration** and **Ping** tabs.

Step 7 – On the **Advanced** tab:

- Select the **Enterprise Interwork** (created in **Section 8.6.1**), for **Interworking Profile**.
- Since TLS transport is specified in **Step 3**, then the **Enable Grooming** option should be enabled.
- In the **Signaling Manipulation Script** field select **none**.
- Select **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.8.2 SIP Server Profile – Verizon

Repeat the steps in **Section 8.8.1**, with the following changes, to create a SIP Server Profile for the Avaya SBCE connection to Verizon.

Step 1 - Select **Add** and enter a Profile Name (e.g., **Verizon IPCC**) and select **Next** (not shown).
Step 2 - On the **General** window, enter the following:

- **Server Type:** Select **Trunk Server**.
- **IP Address: 172.30.205.55** (Verizon-provided IP address).
- Select **Port: 5072**, **Transport**: **UDP**, as specified by Verizon.
- If adding the profile, click **Next** (not shown). If editing an existing profile, click **Finish** and proceed to the next tab.



Step 4 – Default values are used on the **Authentication** tab.

©2021 Avaya Inc. All Rights Reserved.

Step 5 – On the **Heartbeat** tab, check the **Enable Heartbeat** box to optionally have the Avaya SBCE source "heartbeats" toward Verizon. The screen below shows the values used in the reference configuration.



Step 6 – Default values are used on the **Registration** and **Ping** tabs.

Step 7 – On the **Advanced** window, enter the following:

- **Enable Grooming** is not used for UDP connections and is left unchecked.
- Select the **SIP Provider Interwk** (created in **Section 8.6.2**), for **Interworking Profile**.
- Select the **Vz IPCC Script** (created in **Section 8.7**) for **Signaling Manipulation Script**.
- Select **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.9. Routing Profiles

Routing profiles define a specific set of packet routing criteria that are used in conjunction with other types of domain policies to identify a particular call flow and thereby ascertain which security features will be applied to those packets. Parameters defined by Routing Profiles include packet transport settings, name server addresses and resolution methods, next hop routing information, and packet transport types. Separate Routing Profiles were created in the reference configuration for Session Manager and Verizon.

8.9.1 Routing Profile – Session Manager

This provisioning defines the Routing Profile for the connection to Session Manager.

Step 1 - Select **Global Profiles → Routing** from the left-hand menu, and select **Add** (not shown)
Step 2 - Enter a **Profile Name**: (e.g., **Route to SM8**) and click **Next**.



Step 3 – The Routing Profile window will open. The parameters in the top portion of the profile are left at their default settings. Click the **Add** button.
Step 4 - The **Next-Hop Address** window will open. Populate the following fields:

- **Priority/Weight** = **1**
- **Server Configuration** = **SM8** (from **Section 8.8.1**).
- **Next Hop Address:** Verify that the **10.64.91.81:5061 (TLS)** entry from the drop-down menu is selected (Session Manager IP address). Also note that the **Transport** field is grayed out.
- Click on **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.9.2 Routing Profile – Verizon

Repeat the steps in **Section 8.9.1**, with the following changes, to add a Routing Profile for the Avaya SBCE connection to Verizon.

Step 1 - On the **Global Profiles → Routing Profile** window, enter a Profile Name: (e.g., **Route to Vz IPCC**).

Step 2 - On the **Next-Hop Address** window, populate the following fields:

- **Priority/Weight** = **1**
- **Server Configuration** = **Verizon IPCC** (**from Section 8.8.2**).
- **Next Hop Address:** verify that **172.30.205.55:5072 (UDP)** is selected.

Step 3 - Click **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.10. Topology Hiding Profiles

The **Topology Hiding** profile manage how various source, destination and routing information in SIP and SDP message headers are substituted or changed to maintain the security of the network. It hides the topology of the enterprise network from external networks.

Topology Hiding can also be used as an interoperability tool to adapt the host portion of the SIP headers, to the IP addresses or domains expected on the service provider and the enterprise networks.

8.10.1 Topology Hiding – Enterprise

In the sample configuration, the enterprise Topology Hiding Profile was cloned from the **default** profile and then modified.

Step 1 - Select **Configuration Profiles → Topology Hiding** from the left-hand menu.
Step 2 - Select the pre-defined **default** profile and click the **Clone** button.
Step 3 - Enter profile name: (e.g., **Enterprise-Topology**), and click **Finish** to continue.



Step 4 - Edit the newly created **Enterprise-Topology** profile.
Step 5 - For the **Request-Line**, **To** and **From** headers select **Overwrite** under the **Replace Action** column. Enter the domain of the enterprise (e.g., **avayalab.com**) on the **Overwrite Value** field.
Step 6 - Click **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.10.2 Topology Hiding – Verizon

Repeat the steps in **Section 8.10.1**, with the following changes, to create a Topology Hiding Profile for the Avaya SBCE connection to Verizon.

- Enter a Profile Name (e.g., **Vz IPCC Topology**).
- Overwrite the headers as shown below with the FQDNs known by Verizon.

Note – The Refer-To header's domain is overwritten with the IP address presented in the original INVITE from Verizon's IP-IVR service. See **Section 2.2**. If the IP-IVR service is not used, the Refer-To header can retain the default **Replace Action** of "**Auto**".



©2021 Avaya Inc. All Rights Reserved.

8.11. Application Rules

Application Rules define which types of SIP-based Unified Communications (UC) applications the Avaya SBCE security device will protect: voice, video, and/or Instant Messaging (IM). In addition, you can determine the maximum number of concurrent voice and video sessions the network will process in order to prevent resource exhaustion.

Step 1 - Select **Domain Policies →Application Rules** from the left-hand side menu.
Step 2 - Select the **default-trunk** rule.
Step 3 - Select the **Clone** button, and the **Clone Rule** window will open (not shown).

- In the **Clone Name** field enter the new Application Rule name (e.g., **sip-trunk**).
- Click **Finish** (not shown). The completed **Application Rule** is shown below.



©2021 Avaya Inc. All Rights Reserved.

8.12. Media Rules

Media Rules define packet parameters for the RTP media, such as encryption techniques and QoS settings. Separate media rules are created for Verizon and Session Manager.

8.12.1 Enterprise – Media Rule

In the sample configuration, the default Media Rule **avaya-low-med-enc** was cloned to create the enterprise Media Rule, and modified as shown below:

Step 1 - Select **Domain Policies → Media Rules** from the left-hand side menu (not shown).
Step 2 - From the Media Rules menu, select the **avaya-low-med-enc** rule.
Step 3 - Select **Clone** button, and the **Clone Rule** window will open.

- In the **Clone Name** field enter the new Media Rule name (e.g., **enterprise-med-rule**)
- Click **Finish.** The newly created rule will be displayed.

Step 4 - On the **enterprise med rule** just created, select the **Encryption** tab.

- Click the **Edit** button and the **Media Encryption** window will open.
- In the **Audio Encryption** section, select **RTP** for **Preferred Format #2**.
- In the **Video Encryption** section, select **RTP** for **Preferred Format #2**.
- In the **Miscellaneous** section, select **Capability Negotiation**.

Step 5 - Click **Finish**.



©2021 Avaya Inc. All Rights Reserved.

The completed **enterprise-med-rule** is shown on the screen below.



©2021 Avaya Inc. All Rights Reserved.

8.12.2 Verizon – Media Rule

Repeat the steps in **Section 8.12.1**, with the following changes, to create a Media Rule for Verizon.

1. Clone the **default-low-med** profile.
2. In the **Clone Name** field enter the new Media Rule name (e.g., **Vz-trk-med-rule**).

The completed **Vz-trk-med-rule** is shown on the screen below.



DSCP default value **EF** for expedited forwarding (as specified by Verizon) is used for Media **QoS**.



©2021 Avaya Inc. All Rights Reserved.

8.13. Signaling Rules

Signaling Rules define the action to be taken (Allow, Block, Block with Response, etc.) for each type of SIP-specific signaling request and response message. In the reference configuration, Signaling Rules are used to define QoS parameters for the SIP signaling packets.

8.13.1 Signaling Rule - Enterprise

Step 1 - Select **Domain Policies → Signaling Rules** from the left-hand side menu (not shown).
Step 2 - From the Signaling Rules menu, select the **default** rule.
Step 3 - Select the **Clone** button and the **Clone Rule** window will open.

- In the **Rule Name** field enter the new Signaling Rule name (e.g., **enterprise-sig-rule)**
- Click **Finish**. The newly created rule will be displayed.



Step 4 – On the **enterprise-sig-rule** newly created, select the **Signaling QoS** tab and enter the following:

- Click the **Edit** button and the **Signaling QOS** window will open.
- Verify that **Enabled** is selected.
- Select **DCSP**.
- Select **Value** = **EF**.

Step 5 - Click **Finish**.



©2021 Avaya Inc. All Rights Reserved.

8.13.2 Signaling Rule - Verizon

Repeat the steps in **Section 8.13.1**, with the following changes, to create a Media Rule for Verizon.

- Clone the **default** rule.
- In the **Clone Name** field enter the new Media Rule name (e.g., **Vz-trk-sig-rule**).
- On the **Signaling QoS tab** select **Value** = **AF32**.

The completed **Vz-trk-sig-rule** is shown on the screen below.



8.14. Endpoint Policy Groups

The rules created under the Domain Policy are assigned to an Endpoint Policy Group. The Endpoint Policy Group is then applied to a Server Flow in **Section 8.15**.

8.14.1 Endpoint Policy Group – Enterprise

Step 1 - Select **Domain Policies → End Point Policy Groups** from the left-hand side menu.
Step 2 - Select **Add** .

- **Name**: **enterprise-trk-policy**.
- Click **Next**.



©2021 Avaya Inc. All Rights Reserved.

Step 3 – On the **Policy Group** window (not shown), select the following.

- **Application Rule**: **sip-trunk** (created in **Section 8.11**).
- **Border Rule**: **default**.
- **Media Rule**: **enterprise-med-rule** (created in **Section 8.12.1**).
- **Security Rule**: **default-low**.
- **Signaling Rule**: **enterprise-sig-rule** (created in **Section 8.13.1**).

Step 4 - Select **Finish**.

The completed Policy Group **enterprise-trk-policy** is shown on the screen below.



8.14.2 Endpoint Policy Groups – Verizon

Step 1 - Repeat steps **1** through **4** from **Section 8.14.1** with the following changes:

- **Group Name**: **Vz-policy-grp**.
- **Media Rule**: **Vz-trk-med-rule** (created in **Section 8.12.2**).
- **Signaling Rule**: **Vz-trk-sig-rule** (created in **Section 8.13.2**).

The completed Policy Group **Vz-policy-grp** is shown on the screen below.



©2021 Avaya Inc. All Rights Reserved.

8.15. Endpoint Flows – Server Flows

Server Flows combine the interfaces, polices, and profiles defined in the previous sections into inbound and outbound flows. When a packet is received by Avaya SBCE, the content of the packet (IP addresses, SIP URIs, etc.) is used to determine which flow it matches, so that the appropriate policies can be applied. Create separate Server Flows for the enterprise and the Verizon IP Contact Center Service.

8.15.1 Server Flow – Enterprise

Step 1 - Select **Device Specific Settings → Endpoint Flows** from the menu on the left-hand side (not shown).

Step 2 - Select the **Server Flows** tab (not shown).

Step 3 - Select **Add**, (not shown) and enter the following:

- **Flow Name**: Enter a name for the flow, e.g., **SM8 Flow for Verizon IPCC**.
- **Server Configuration**: **SM8** (**Section 8.8.1**).
- **URI Group**: *****
- **Transport**: *****
- **Remote Subnet**: *****
- **Received Interface**: **Vz-Sig-B1** (**Section 8.5**). Note that this is the interface where the reverse flow (inbound traffic) is expected.
- **Signaling Interface**: **Inside-Sig-50** (**Section 8.5**).
- **Media Interface**: **Inside-Med-50** (**Section 8.4**).
- **End Point Policy Group**: **enterprise-trk-policy** (**Section 8.14.1**).
- **Routing Profile**: **Route to Vz IPCC** (**Section 8.9.2**).
- **Topology Hiding Profile**: **Enterprise-Topology** (**Section 8.10.1**).
- Let other fields at their default values.

Step 4 - Click **Finish** (not shown).



©2021 Avaya Inc. All Rights Reserved.

8.15.2 Server Flow – Verizon

Step 1 - Repeat steps **1** through **4** from **Section 8.15.1**, with the following changes:

- **Flow Name**: **Verizon IPCC Flow for SM8**.
- **Server Configuration**: **Verizon IPCC** (**Section 8.8.2**).
- **URI Group**: *****
- **Transport**: *****
- **Remote Subnet**: *****
- **Received Interface**: **Inside-Sig-50** (**Section 8.5**). Note that this is the interface where the reverse flow (outbound traffic) is expected.
- **Signaling Interface**: **Vz-Sig-B1 (Section 8.5**).
- **Media Interface**: **Vz-Med-B1** (**Section 8.4**).
- **End Point Policy Group**: **Vz-policy-grp** (**Section 8.14.2**).
- **Routing Profile**: **Route to SM8** (**Section 8.9.1**).
- **Topology Hiding Profile**: **Vz IPCC Topology** (**Section 8.10.2**).



©2021 Avaya Inc. All Rights Reserved.

9. Verizon Business IPCC Services Suite Configuration

Information regarding Verizon Business IPCC Services suite offer can be found at https://www.verizon.com/business/products/contact-center-cx-solutions/contact-center-network/ip-contact-center or by contacting a Verizon Business sales representative.

The reference configuration described in these Application Notes was located in the Avaya Solutions and Interoperability Test Lab. Access to the Verizon Business IPCC Services suite was via a Verizon Private IP (PIP) T1 connection. Verizon Business provided all of the necessary service provisioning.

9.1. Service Access Information

The following service access information (FQDN, IP addressing, ports, toll free numbers) was provided by Verizon for the sample configuration.

CPE (Avaya)	Verizon Network
adevc.avaya.globalipcom.com ***UDP port 5060***	***172.30.205.55*** ***UDP Port 5072***

Toll Free Numbers
866-850-2380
866-851-0107
866-851-2649
866-852-3221
866-850-6850

©2021 Avaya Inc. All Rights Reserved.

10. Verification Steps

This section provides example verifications of the Avaya configuration with Verizon Business IP Contact Center service.

10.1. Avaya Aura® Communication Manager Verifications

This section illustrates verifications from Communication Manager.

10.1.1 Example Incoming Call from PSTN via Verizon IPCC to Telephone

Incoming PSTN calls arrive from Verizon at Avaya SBCE, which sends the call to Session Manager. Session Manager sends the call to Communication Manager. On Communication Manager, the incoming call arrives via signaling group 2, trunk group 2.

The following edited Communication Manager **list trace tac** trace output shows a call incoming on trunk group 2. The PSTN telephone dialed 866-850-2380. Session Manager mapped the number received from Verizon to the extension of a Communication Manager telephone (x50231). Extension 50231 is an IP Telephone with IP address 192.168.7.103 in Region 1. Initially, the Media Server (10.64.91.86) is used. The annotations in the edited trace highlight key behaviors.

```
list trace tac *02                                                    Page   1

                                LIST TRACE
time            data
--------Incoming call arrives to Communication Manager-----------------
07:26:59 TRACE STARTED 06/16/2021 CM Release String cold-01.0.890.0-26766
07:27:04 SIP<INVITE sips:50231@avayalab.com SIP/2.0
07:27:04     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
07:27:04     active trunk-group 2 member 1    cid 0x550
--------Communication Manager sends 183 with SDP-------------------------
07:27:04 SIP>SIP/2.0 183 Session Progress
07:27:04     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
07:27:04     dial 50231
07:27:04     ring station      50231 cid 0x550
--------Media Server at 10.64.91.86 on media path----------------------
07:27:04     Alerting party  uses public-unknown-numbering
07:27:04     G729 ss:off ps:20
             rgn:2 [10.64.91.50]:35518
             rgn:1 [10.64.91.86]:6120
07:27:04     G72264K ss:off ps:20
             rgn:1 [192.168.7.103]:20414
             rgn:1 [10.64.91.86]:6122
---Extension 50231 answers the call, Communication Manager sends 200 OK------
07:27:07 SIP>SIP/2.0 200 OK
07:27:07     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
07:27:07     active station      50231 cid 0x550
07:27:07     Connected party  uses public-unknown-numbering
07:27:07 SIP<ACK sips:+17329450231@10.64.91.75:5071;transport=tls;as
07:27:07 SIP<m=1 SIP/2.0
07:27:07     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510

<continued on next page>
```


©2021 Avaya Inc. All Rights Reserved.

Once the call is answered, the final RTP media path is “ip-direct” from the IP Telephone (192.168.7.103) to the “inside” of the Avaya SBCE (10.64.91.50) in Region 2. The Media Server is no longer involved in the media path.

```
list trace tac *02                                                    Page   2

                                LIST TRACE
time           data
---Communication Manager sends re-INVITE for direct IP-IP media (shuffling)--
07:27:07 SIP>INVITE sips:+17863310799@10.64.91.50:5061;transport=tls
07:27:07 SIP>;gsid=9baa308c-c5b6-43b6-bd8f-c52beeef4862;sipappsessio
07:27:07 SIP>nid=app-1rc2h4yw05bn4;wlssfcid=sip-12dgn3pv91m3e;asm=1
07:27:07 SIP>SIP/2.0
07:27:07     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
07:27:07 SIP<SIP/2.0 100 Trying
07:27:07     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
----Communication Manager receives 200 OK with SDP to the re-INVITE---------
07:27:07 SIP<SIP/2.0 200 OK
07:27:07     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
----Communication Manager sends ACK with SDP-------------------------------
07:27:07 SIP>ACK sips:+17863310799@10.64.91.50:5061;transport=tls;gs
07:27:07 SIP>id=9baa308c-c5b6-43b6-bd8f-c52beeef4862;sipappsessionid
07:27:07 SIP>=app-1rc2h4yw05bn4;wlssfcid=sip-12dgn3pv91m3e;asm=1 SIP
07:27:07 SIP>/2.0
07:27:07     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
---Final media path is IP-direct, from telephone (192.168.7.103) to the
SBCE A1 interface (10.64.91.50)-----------------------------------------
07:27:07     G729A ss:off ps:20
             rgn:2 [10.64.91.50]:35518
             rgn:1 [192.168.7.103]:20414
07:27:07     G729 ss:off ps:20
             rgn:1 [192.168.7.103]:20414
             rgn:2 [10.64.91.50]:35518
---Extension hangs up, Communication Manager sends BYE------------------
07:28:21 SIP>BYE sips:+17863310799@10.64.91.50:5061;transport=tls;gs
07:28:21 SIP>id=9baa308c-c5b6-43b6-bd8f-c52beeef4862;sipappsessionid
07:28:21 SIP>=app-1rc2h4yw05bn4;wlssfcid=sip-12dgn3pv91m3e;asm=1 SIP
07:28:21 SIP>/2.0
07:28:21     Call-ID: 63e77749b40e817b2c9d4c6ecaf32510
07:28:21     idle station      50231 cid 0x550
```


©2021 Avaya Inc. All Rights Reserved.

The following screen shows **Page 2** of the output of the **status trunk 2/*x*** command (where *x* is the trunk group member active on the call, **1 i**n the example) pertaining to this same call. Note the signaling using port 5071 between Communication Manager and Session Manager. Note the media is "**ip-direct**" from the IP Telephone (192.168.7.103) to the inside IP address of Avaya SBCE (10.64.91.50) using codec G.729.

```
status trunk 2/1                                                Page   2 of   3
                              CALL CONTROL SIGNALING

Near-end Signaling Loc: PROCR
  Signaling   IP Address                              Port
   Near-end:  10.64.91.75                           : 5071
    Far-end:  10.64.91.81                           : 5071
 H.245 Near:
  H.245 Far:
   H.245 Signaling Loc:           H.245 Tunneled in Q.931? no

 Audio Connection Type: ip-direct     Authentication Type: None
    Near-end Audio Loc:                         Codec Type: G.729
   Audio      IP Address                              Port
   Near-end:  192.168.7.103                         : 20414
    Far-end:  10.64.91.50                           : 35518

 Video Near:
  Video Far:
 Video Port:
  Video Near-end Codec:               Video Far-end Codec:
```

The following screen shows **Page 3** of the output of the **status trunk** command pertaining to the same call. Note that codec G.729 is used.

```
status trunk 2/1                                                Page   3 of   3
                       SRC PORT TO DEST PORT TALKPATH

src port: T000011
T000011:TX:10.64.91.50:35518/g729/20ms/1-srtp-aescm128-hmac80
S000598:RX:192.168.7.103:20414/g729a/20ms/1-srtp-aescm128-hmac80
```


©2021 Avaya Inc. All Rights Reserved.

10.1.2 Example Incoming Call Referred via Call Vector to PSTN Destination

The following edited and annotated Communication Manager **list trace tac** trace output shows a call incoming on trunk group 2. The PSTN telephone dialed was 866-852-3221. Session Manager can map the number received from Verizon to the VDN extension (x10001), or the incoming call handling table for trunk group 1 can do the same. In the trace below, Session Manager had already mapped the Verizon number to the Communication Manager VDN extension. The call was routed to a Communication Manager vector directory number (VDN 10001) associated with a call vector (call vector 2). The vector answers the call, plays an announcement to the caller, and then uses a "route-to" step to cause a REFER message to be sent with a Refer-To header containing the number configured in the vector. The annotations in the edited trace highlight key behaviors. At the conclusion, the PSTN caller that dialed the Verizon toll-free number is connected to the Referred-to PSTN destination, and no trunks (i.e., from trunk 2 handling the call) are in use.

```
list trace tac *02                                                    Page   1
                              LIST TRACE
time           data
--------Incoming call arrives to Communication Manager-----------------
08:38:39 TRACE STARTED 06/16/2021 CM Release String cold-01.0.890.0-26766
08:38:51 SIP<INVITE sips:10001@avayalab.com SIP/2.0
08:38:51     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:38:51     active trunk-group 2 member 1    cid 0x578
08:38:51    0  0 ENTERING TRACE cid 1400
08:38:51    2  1 vdn e10001 bsr appl   0 strategy 1st-found override n
08:38:51    2  1 AVDN: 10001 AVRD:
08:38:51    2  1 wait 2 secs hearing ringback
--------Vector step plays ringback. 183 with SDP is sent-----------------
08:38:51 SIP>SIP/2.0 183 Session Progress
08:38:51     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:38:51     dial 10001
08:38:51     ring vector 2      cid 0x578
08:38:51     G729 ss:off ps:20
             rgn:2 [10.64.91.50]:35532
             rgn:1 [10.64.91.91]:16394
08:38:51     xoip options: fax:off modem:off tty:US  uid:0x50000b
             xoip ip: [10.64.91.91]:16394
08:38:53    2  2 # Play announcement to caller i...
08:38:53    2  3 announcement 11006
08:38:53 SIP>SIP/2.0 183 Session Progress
08:38:53     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:38:53    2  3      announcement: board M2:00 ann ext: 11006
------Vector plays announcement to caller. 200 OK is sent-------------------
08:38:53 SIP>SIP/2.0 200 OK
08:38:53     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:38:53     active announcement      11006 cid 0x578
08:38:53     hear audio-group 1 board M2 ext 11006 cid 0x578
08:38:53     Connected party  uses public-unknown-numbering
08:38:53 SIP<ACK sips:+18668523221@10.64.91.75:5071;transport=tls;as
08:38:53 SIP<m=1 SIP/2.0

<continued on next page>
```


©2021 Avaya Inc. All Rights Reserved.

```
list trace tac *02                                                    Page   2
                                LIST TRACE
time            data
08:38:53     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:38:55     idle announcement       cid 0x578
08:38:55    2  4 # Refer the call to PSTN Destin...
08:38:55    2  5 route-to number ~r+178633100788 cov y if unconditionally
----------Communication Manager sends REFER------------------------------
08:38:55 SIP>REFER sips:+17863310799@10.64.91.50:5061;transport=tls;
08:38:55 SIP>gsid=8404378b-d7e5-4e13-93ca-5a5931ba819d;sipappsession
08:38:55 SIP>id=app-1eo92k6fdzbwz;wlssfcid=sip-cwmwqhepi59z;asm=1 SI
08:38:55 SIP>P/2.0
08:38:55     Call-ID: bc151a67ef8414655a5e8e62f6b63364
------Communication Manager receives 202 Accepted sent by Verizon IPCC-----
08:38:55 SIP<SIP/2.0 202 Accepted
08:38:55     Call-ID: bc151a67ef8414655a5e8e62f6b63364
------Verizon IPCC sends NOTIFY with sipfrag 100 Trying--------------
08:38:55 SIP<NOTIFY sips:+18668523221@10.64.91.75:5071;transport=tls
08:38:55 SIP<;asm=1 SIP/2.0
08:38:55     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:38:55 SIP>SIP/2.0 200 OK
08:38:55     Call-ID: bc151a67ef8414655a5e8e62f6b63364
             VOIP data from: [10.64.91.91]:16394
08:39:02     Jitter:0 0 0 0 0 0 0 0 0 0: Buff:11 WC:0 Avg:0
08:39:02     Pkloss:0 0 0 0 0 0 0 0 0 0: Oofo:0 WC:0 Avg:0
-------Verizon IPCC sends NOTIFY with sipfrag 200 OK-------------
08:39:03 SIP<NOTIFY sips:+18668523221@10.64.91.75:5071;transport=tls
08:39:03 SIP<;asm=1 SIP/2.0
08:39:03     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:39:03 SIP>SIP/2.0 200 OK
08:39:03     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:39:03    2  5 LEAVING VECTOR PROCESSING cid 1400
------Communication Manager sends a BYE-----------------------------
08:39:03 SIP>BYE sips:+17863310799@10.64.91.50:5061;transport=tls;gs
08:39:03 SIP>id=8404378b-d7e5-4e13-93ca-5a5931ba819d;sipappsessionid
08:39:03 SIP>=app-1eo92k6fdzbwz;wlssfcid=sip-cwmwqhepi59z;asm=1 SIP/
08:39:03 SIP>2.0
08:39:03     Call-ID: bc151a67ef8414655a5e8e62f6b63364
08:39:03     idle trunk-group 2 member 1    cid 0x578

----Trunk is now idle. Caller and Refer-To target are now connected by Verizon--
```

When the initial call arrived from Verizon, it used trunk member 1 in trunk group 2. After the successful transfer with REFER back to Verizon, trunk member 1 is now idle.

```
status trunk 2
                            TRUNK GROUP STATUS
Member   Port     Service State      Mtce Connected Ports
                                    Busy

0002/001 T00011   in-service/idle    no
0002/002 T00012   in-service/idle    no
0002/003 T00013   in-service/idle    no
0002/004 T00014   in-service/idle    no
0002/005 T00015   in-service/idle    no
0002/006 T00016   in-service/idle    no
0002/007 T00017   in-service/idle    no
0002/008 T00018   in-service/idle    no
```


©2021 Avaya Inc. All Rights Reserved.

10.2. Avaya Aura® Session Manager Verification

The Session Manager configuration may be verified via System Manager.

Using the procedures described in **Section 6.1**, access the System Manager GUI. From the **Home** screen, under the **Elements** heading, select **Session Manager**.



The Session Manager Dashboard is displayed. Note that the **Test Passed**, **Alarms**, **Service State** and **Data Replication** columns all show good status.



©2021 Avaya Inc. All Rights Reserved.

In the example, the entry **3/22** under the **Entity Monitoring** column shows that there are alarms on 2 out of the 21 Entities being monitored by Session Manager. Clicking the entry under the **Entity Monitoring** column brings up the **Session Manager Entity Link Connection Status** page. Verify that the state of the Session Manager links of interest, to Communication Manager and the Avaya SBCE under the **Conn. Status** and **Link Status** columns is **UP**, like shown on the screen below.



Session Manager Entity Link Connection Status

This page displays detailed connection status for all entity links from a Session Manager.

Status Details for the selected Session Manager:

All Entity Links for Session Manager: Session Manager

Summary View

16 Items | Filter: Enable

SIP Entity Name	IP Address Family	SIP Entity Resolved IP	Port	Proto.	Deny	Conn. Status	Reason Code	Link Status
Aura Messaging	IPv4	10.64.91.84	5061	TLS	FALSE	UP	200 OK	UP
Breeze	IPv4	10.64.91.18	5061	TLS	FALSE	DOWN	500 Server Internal Error: Destination Unreachable	DOWN
CM-TG1	IPv4	10.64.91.75	5081	TLS	FALSE	UP	200 OK	UP
CM-TG2	IPv4	10.64.91.75	5071	TLS	FALSE	UP	200 OK	UP
CM-TG3	IPv4	10.64.91.75	5061	TLS	FALSE	UP	200 OK	UP
CM-TG4	IPv4	10.64.91.75	5064	TLS	FALSE	UP	200 OK	UP
CM-TG5	IPv4	10.64.91.75	5065	TLS	FALSE	UP	200 OK	UP
CM-TG7	IPv4	10.64.91.75	5067	TLS	FALSE	UP	200 OK	UP
ExperiencePortal	IPv4	10.64.91.90	5061	TLS	FALSE	UP	200 OK	UP
IP500	IPv4	10.64.19.70	5061	TLS	FALSE	DOWN	408 Request Timeout	DOWN
Presence	IPv4	10.64.91.18	5061	TLS	FALSE	DOWN	500 Server Internal Error: Destination Unreachable	DOWN
SBC1	IPv4	10.64.91.50	5061	TLS	FALSE	UP	200 OK	UP
SBC2	IPv4	10.64.91.100	5061	TLS	FALSE	UP	200 OK	UP
SBC2-101	IPv4	10.64.91.101	5061	TLS	FALSE	UP	200 OK	UP
SBCE-ATT	IPv4	10.64.91.40	5061	TLS	FALSE	UP	405 Method Not Allowed	UP

Select : None | Page 1 of 2

Other Session Manager useful verification and troubleshooting tools include:

- **traceSM** – Session Manager command line tool for traffic analysis. Login to the Session Manager command line management interface to run this command.
- **Call Routing Test** - The Call Routing Test verifies the routing for a particular source and destination. To run the routing test, from the System Manager Home screen navigate to **Elements → Session Manager →System Tools → Call Routing Test**. Enter the requested data to run the test.

©2021 Avaya Inc. All Rights Reserved.

10.3. Avaya Session Border Controller for Enterprise Verification

This section illustrates verifications from Avaya Session Border Controller for Enterprise.

10.3.1 Incidents

The Incident Viewer can be accessed from the Avaya top navigation menu as highlighted in the screenshot below.



Use the Incident Viewer to verify Server Heartbeat and to troubleshoot routing failures.



©2021 Avaya Inc. All Rights Reserved.

10.3.2 Server Status

The **Server Status** can be access from the Avaya SBCE top navigation menu by selecting the **Status** menu, and then **Server Status**.



The **Server Status** screen provides information about the condition of the connection to the connected SIP Servers. This functionality requires Heartbeat to be enabled on the SIP Server Configuration profiles, as configured in **Section 8.8**.



©2021 Avaya Inc. All Rights Reserved.

10.3.3 Diagnostics

This screen provides a **Full Diagnostics** tool to verify the link of each interface and ping the configured next-hop gateways and DNS servers. The **Ping Test** tool can be used to ping specific devices from any Avaya SBCE interface.



©2021 Avaya Inc. All Rights Reserved.

10.3.4 Tracing

To take a call trace, navigate to **Monitoring & Logging → Trace** and select the **Packet Capture** tab. Populate the fields for the capture parameters and click **Start Capture** as shown below.



When tracing has reached the desired number of packets the trace will stop automatically, or alternatively, click the **Stop Capture** button at the bottom.



Select the **Captures** tab at the top and the capture will be listed; select the **File Name** and choose to open it with an application like Wireshark.



©2021 Avaya Inc. All Rights Reserved.

11. Conclusion

As illustrated in these Application Notes, Avaya Aura® Communication Manager 8.1, Avaya Aura® Session Manager 8.1, Avaya Experience Portal 8.0 and Avaya Session Border Controller for Enterprise 8.1 can be configured to interoperate successfully with Verizon Business IP Contact Center Services suite. This solution enables inbound toll free calls over a Verizon Business VoIP Inbound SIP trunk service connection. In addition, these Application Notes further demonstrate that the Avaya Aura® Communication Manager implementation of SIP Network Call Redirection (SIP-NCR) can work in conjunction with Verizon's Business IP Contact Center services implementation of SIP-NCR to support call redirection over SIP trunks inclusive of passing User-User Information (UUI).

Please note that the sample configurations shown in these Application Notes are intended to provide configuration guidance to supplement other Avaya product documentation.

©2021 Avaya Inc. All Rights Reserved.

12. Additional References

12.1. Avaya

Avaya product documentation, including the following, is available at http://support.avaya.com

Avaya Aura® Session Manager/System Manager

[1] *Deploying Avaya Aura® Session Manager and Branch Session Manager in Virtualized Environment*, Release 8.1.x, Issue 4, October 2020

[2] *Administering Avaya Aura® Session Manager*, Release 8.1.x, Issue 8, February 2021

[3] *Deploying Avaya Aura® System Manager in Virtualized Environment*, Release 8.1.x, Issue 7, November 2020

[4] *Administering Avaya Aura® System Manager for Release 8.1.x*, Release 8.1.x, Issue 12, May 2021

Avaya Aura® Communication Manager

[5] *Deploying Avaya Aura® Communication Manager in Virtualized Environment*, Release 8.1.x, Issue 6, October 2020

[6] *Administering Avaya Aura® Communication Manager*, Release 8.1.x, Issue 10, March 2021

[7] *Administering Avaya G430 Branch Gateway*, Release 8.1.x, Issue 8, January 2021

[8] *Deploying and Updating Avaya Aura® Media Server Appliance*, Release 8.0.x, Issue 12, December 2020

[9] *Integrating Avaya Aura® Media Server with Avaya Aura® Communication Manager*, Release 8.0.x, May 2020

Avaya Session Border Controller for Enterprise

[10] *Deploying Avaya Session Border Controller for Enterprise on a Virtualized Environment Platform*, Release 8.1.x, Issue 4, December 2020

[11] *Administering Avaya Session Border Controller for Enterprise*, Release 8.1.x, Issue 5, June 2021

Avaya Messaging

[12] *OfficeLink™ Server Installation Guide for Avaya*, July 2019

[13] *Avaya OfficeLink™ Integration with Avaya Aura CM and Session Manager 8*, July 2019

Avaya Experience Portal

[14] *Implementing Avaya Experience Portal on a single server*, Release 8.0, Issue 1.1, October 2020

[15] *Administering Avaya Experience Portal*, Release 8.0, Issue 1.1, October 2020

12.2. Verizon Business

The following documents may be obtained by contacting a Verizon Business Account Representative.

- *Retail VoIP Interoperability Test Plan*
- *Network Interface Specification Retail VoIP Trunk Interface (for non-registering devices)*

©2021 Avaya Inc. All Rights Reserved.

13. Appendix A – Avaya Session Border Controller for Enterprise – Refer Handling

One of the capabilities important to the Experience Portal environment is the Avaya SBCE Refer Handling option. As described in **Section 3.3**, Experience Portal inbound call processing may include call redirection to Communication Manager agents, or other CPE destinations. This redirection is accomplished by having Experience Portal send SIP REFER messaging to the Avaya SBCE. Enabling the Refer Handling option causes the Avaya SBCE to intercept and process the REFER and generate a new SIP INVITE messages back to the CPE (e.g., Communication Manager).

As an additional option, the Refer Handling feature can also specify *URI Group* criteria as a discriminator, whereby SIP REFER messages matching the URI Group criteria are processed by the Avaya SBCE, while SIP REFER messages that do not match the URI Group criteria, are passed through to Verizon.

Create a URI Group for numbers intended for Communication Manager.
Step 1 - Select **Global Profiles → URI Groups** from the left-hand menu.
Step 2 - Select **Add** and enter a descriptive **Group Name**, e.g., **internal-extension**, and select **Next** (not shown).
Step 3 - Enter the following:

- **Scheme**: **sip:/sips:**
- **Type: Regular Expression**.
- **URI: 12[0-9]{3}@.*** This will match 5-digit local extensions starting with 12, e.g., 12001.
- Select **Finish**.



©2021 Avaya Inc. All Rights Reserved.

Step 4 - For additional entries, select **Add** on the right-hand side of the URI Group tab and repeat **Step 3**.



Edit the existing Verizon Server Interworking Profile to enable Refer Handling and assign the newly created URI Group.

Step 1 - Select **Global Profiles → Server Interworking** from the left-hand menu

Step 2 - Select the Verizon Server Interworking Profile created in **Section 8.6.2** and click **Edit**

- Check **Refer Handling**.
- **URI Group: internal-extensions**.
- Select **Finish**.



©2021 Avaya Inc. All Rights Reserved.

©2021 Avaya Inc. All Rights Reserved.
Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at devconnect@avaya.com.

©2021 Avaya Inc. All Rights Reserved.