

#### Avaya Solution & Interoperability Test Lab

# Application Notes for Yealink CP Series Speakerphones (CP700/CP900) and Yealink USB Connect with Avaya Workplace Client for Windows - Issue 1.0

#### **Abstract**

These Application Notes describe the configuration steps required to integrate Yealink CP Series Speakerphones (CP700/ CP900) and Yealink USB Connect with Avaya Workplace Client for Windows. The Yealink CP Series Speakerphones connects to the PC via a USB-A cable. The Yealink USB Connect application is a program that enables remote call control with Yealink CP Series Speakerphones with Avaya Workplace Client for Windows. With Yealink Speakerphone connected to the USB interface on a PC, users can directly answer, end, mute/unmute, hold/resume and adjust volume on the Speakerphone.

Readers should pay attention to **Section 2**, in particular the scope of testing as outlined in **Section 2.1** as well as any observations noted in **Section 2.2**, to ensure that their own use cases are adequately covered by this scope and results.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

#### 1. Introduction

The Yealink CP Series Speakerphones (CP700/CP900) with Yealink USB Connect allows connection and call control of Avaya Workplace Client for Windows (hereafter referred to as Avaya Workplace). In this compliance test, Yealink CP Series Speakerphones connect via USB-A cable to PC. Users can directly answer, end, mute/unmute, hold/resume and adjust volume on the Speakerphone.

# 2. General Test Approach and Test Results

The interoperability compliance test included feature and serviceability testing. The feature testing focused on placing calls with Avaya Workplace, answering and ending calls using the call control button on the Speakerphone, and verifying two-way audio. The call types include calls to voicemail, local extensions, and the PSTN. Call hold and resume, mute and un-mute, and speed dial are also tested.

The serviceability testing focused on verifying the usability of the Speakerphone solution after restarting the Avaya Workplace, restarting the PC and reconnecting the USB cable of Speakerphone to the PC.

Avaya recommends our customers implement Avaya solutions using appropriate security and encryption capabilities enabled by our products. The testing referenced in these DevConnect Application Notes included the enablement of supported encryption capabilities in the Avaya products. Readers should consult the appropriate Avaya product documentation for further information regarding security and encryption capabilities supported by those Avaya products.

Support for these security and encryption capabilities in any non-Avaya solution component is the responsibility of each individual vendor. Readers should consult the appropriate vendor-supplied product documentation for more information regarding those products.

For the testing associated with these Application Notes, the interface between Avaya systems and endpoints utilized enabled capabilities of TLS/SRTP.

DevConnect Compliance Testing is conducted jointly by Avaya and DevConnect members. The jointly-defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect Compliance Testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member's solution.

Avaya's formal testing and Declaration of Conformity is provided only on the headsets/handsets that carry the Avaya brand or logo. Avaya may conduct testing of non-Avaya headset/handset to determine interoperability with Avaya phones. However, Avaya does not conduct the testing of non-Avaya headsets/handsets for: Acoustic Pressure, Safety, Hearing Aid Compliance, EMC regulations, or any other tests to ensure conformity with safety, audio quality, long-term reliability or any regulation requirements. As a result, Avaya makes no representations whether a

particular non-Avaya headset will work with Avaya's telephones or with a different generation of the same Avaya telephone.

Since there is no industry standard for handset interfaces, different manufacturers utilize different handset/headset interfaces with their telephones. Therefore, any claim made by a headset vendor that its product is compatible with Avaya telephones does not equate to a guarantee that the headset will provide adequate safety protection or audio quality.

#### 2.1. Interoperability Compliance Testing

All test cases were performed manually. The following features were verified:

- Placing calls to the voicemail system. Voice messages were recorded and played back to verify that the playback volume and recording level were good.
- Placing calls to internal extensions to verify two-way audio.
- Placing calls to the PSTN to verify two-way audio.
- Answering and ending calls using the call button on the Speakerphone and the soft button on Avaya Workplace.
- Using the call button on the Speakerphone and the soft button on Avaya Workplace to hold and resume the audio.
- Using the volume buttons on the Speakerphone to adjust the audio volume.
- Using the mute button on the Speakerphone and the soft button on Avaya Workplace to mute and un-mute the audio.
- Verifying incoming call notification on Speakerphone base.
- Verifying call ended notification on Speakerphone base.

The serviceability testing focused on verifying the usability of the Speakerphone solution after restarting the Avaya Workplace, restarting the PC and reconnecting the USB cable to the PC.

#### 2.2. Test Results

All test cases passed successfully.

#### 2.3. Support


For support on this Yealink Speakerphone solution, contact Yealink at:

■ Phone: +86-592-5702000

Website: https://ticket.yealink.com/

# 3. Reference Configuration

Figure 1 illustrates the test configuration used to verify the Yealink CP Series Speakerphones (CP700/CP900), Yealink USB Connect with Avaya Workplace Client for Windows. The configuration consists of an Avaya Aura® Communication Manager running on a virtualized server with an Avaya G430 Media Gateway providing connectivity to the PSTN via a simulated public trunk. Avaya Aura® Session Manager was used as the registrar/proxy for Avaya Workplace Client for Windows as SIP softphone and Avaya Aura® System Manager was used to configure Session Manager. Avaya Aura® Messaging was used as the voicemail system. Avaya Aura® Media Server provides the audio media processing. The Yealink USB Connect was installed on the PC together with Avaya Workplace Client for Windows. The Speakerphone is connected via USB-A cable to the PC.



**Figure 1: Test Configuration** 

# 4. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided.

Equipment/Software	Release/Version		
Avaya Aura® Communication Manager	R018x.01.0.890.0- 26095		
Avaya G430 Media Gateway  • MGP	41.16.0		
Avaya Aura® System Manager	8.1.2.0.0611367		
Avaya Aura® Session Manager	8.1.2.1.812101		
Avaya Aura® Media Server	8.0.2.93		
Avaya Aura® Messaging	7.1 SP2		
Avaya Workplace Client running on Windows 10 Pro	3.9.0.84.8		
Yealink CP700/CP900 Speakerphones using USB-A cable	FW 100.420.0.20		
Yealink USB Connect for Windows	0.32.10.0		

# 5. Configure Avaya Aura® Communication Manager

The information provided in this section describes the verification of Communication Manager System Capacity for this solution.

It is implied a working Communication Manager system is already in place, including dial plans and SIP trunks to a Session Manager. For all other provisioning information such as initial installation and configuration, please refer to the product documentation in **Section 11**.

#### 5.1. Verify System Capacity

Using Avaya Site Administrator Emulation Mode, use the **display system-parameters customer-options** command to determine the values of user license for **Maximum Off-PBX Telephones** allowed in the system. One OPS station is required per SIP user.

```
display system-parameters customer-options
                                                                Page
                                                                      1 of 12
                               OPTIONAL FEATURES
    G3 Version: V18
                                                 Software Package: Enterprise
      Location: 2
                                                 System ID (SID): 1
      Platform: 28
                                                 Module ID (MID): 1
                                                          USED
                           Platform Maximum Ports: 81000 385
                                Maximum Stations: 41000
                                                            186
                         Maximum XMOBILE Stations: 41000
               Maximum Off-PBX Telephones - EC500: 41000
               Maximum Off-PBX Telephones - OPS: 41000
                                                             33
                                                             0
               Maximum Off-PBX Telephones - PBFMC: 41000
               Maximum Off-PBX Telephones - PVFMC: 41000
                                                              0
               Maximum Off-PBX Telephones - SCCAN:

Maximum Survivable Processors: 313
                                                               0
        (NOTE: You must logoff & login to effect the permission changes.)
```

On Page 2 of the system-parameters customer-options form, verify that the number of Maximum Administered SIP Trunks and Maximum Concurrently Registered IP Stations supported by the system is sufficient.


If there is insufficient capacity in either one of these parameters, contact an authorized Avaya sales representative.

display system-parameters customer-options		Page	2 of	12
OPTIONAL FEATURES				
IP PORT CAPACITIES		USED		
Maximum Administered H.323 Trunks:	12000	90		
Maximum Concurrently Registered IP Stations:	18000	17		
Maximum Administered Remote Office Trunks:	12000	0		
Max Concurrently Registered Remote Office Stations:	18000	0		
Maximum Concurrently Registered IP eCons:	414	0		
Max Concur Reg Unauthenticated H.323 Stations:	100	0		
Maximum Video Capable Stations:	41000			
Maximum Video Capable IP Softphones:	18000	2		
Maximum Administered SIP Trunks:	40000	38		
Max Administered Ad-hoc Video Conferencing Ports:	24000	0		
Max Number of DS1 Boards with Echo Cancellation:	999	0		
(NOTE: You must logoff & login to effect the permission changes.)				

# 6. Configure Avaya Aura® Session Manager


This section describes aspects of the Session Manager configuration required for Avaya Workplace to register. It is assumed that the Domains, Locations, SIP Entities, Entity Links, Routing Policies, Dial Patterns and Application Sequences have been configured where appropriate for Communication Manager, Session Manager and Aura® Messaging.

Session Manager is managed via System Manager. Using a web browser, access https://<ip-addr of System Manager>/SMGR. In the Log On screen, enter appropriate User ID and Password and click the Log On button.



# 6.1. Verify Session Manager Ports for SIP endpoint registration

Each Session Manager Entity must be configured so that the SIP Endpoint can register to it. From the home page, under **Elements**, click **Routing** → **SIP Entities** (not shown) and select the Session Manager entity used for registration. Make sure that **TCP**, **UDP** and **TLS** entries are present. During the compliance test, Avaya Workplace Client for Windows registered to the Session Manager using TLS transport.




#### 6.2. Add SIP User

The addition of SIP User will not be detailed here. Refer to details in adding user in the administration document for Avaya Aura® Session Manager in [4].


# 7. Configure Avaya Workplace Client for Windows

Avaya Workplace is a SIP soft phone application that provides users with access to Unified Communications (UC) services. This section shows how to configure the Yealink CP700/CP900 Speakerphone to use with Avaya Workplace.

From Avaya Workplace window, navigate to **Settings** → **User Preferences** → **Audio/Video**.



Select Echo Cancelling Speakerphone (Yealink CP700 Audio) for *Microphone* and the same for *Speaker* as shown below. It is optional for *Ringing on incoming calls* to be set. For Yealink CP900 Speakerphone, select the appropriate *Microphone* and *Speaker* settings.



# 8. Configure Yealink CP700/CP900 Speakerphone Solutions

This section covers the steps to integrate Yealink CP700/CP900 Speakerphone with Avaya Workplace, including:

- Installing the Yealink USB Connect software
- Connect the Speakerphone

**Note:** After successfully performing this procedure, the Speakerphone will be detected in Avaya Workplace as described in **Section 7**.


#### 8.1. Installing the Yealink USB Connect Software

This software can be obtained from Yealink at <a href="http://www.yealink.com/">http://www.yealink.com/</a>. Installation of the software is done through executing the setup file and following the prompt.

# 8.2. Connect the Speakerphone

Plug the Yealink CP700/CP900 Speakerphone to the USB port of the PC. The device drivers will automatically be installed.

Open the Yealink USB Connect program installed on the PC. Below shows the status of the Yealink CP700 connected.




# 9. Verification Steps

This section verifies that the Yealink Speakerphone has been successfully integrated with Avaya Workplace PC.


1. To verify that the Speakerphone has been successfully connected for use with Avaya Workplace, open the Yealink USB Connect program and observed that the CP700/CP900 is detected as in **Section 8.2**. From the **Yealink USB Connect** program, select the **setup icon** on the top right. Click the **Softphone Settings**.



2. Run the Avaya Workplace and open the Yealink USB Connect. Check that the **Preferred Softphone** shows **Avaya IX Workplace** (**Ready**) state.



3. Run the Avaya Workplace and verify that the **Preferred Softphone** shows **Avaya IX Workplace** (**Ready**). Make incoming and outgoing calls and verify that calls can be established with two-way audio. For incoming calls, answer the call by pressing the call button on the Speakerphone.



- 4. End the call by pressing the same call button on the Speakerphone.
- 5. Verify also that the Speakerphone is able to remotely control call functions such as answer, mute/un-mute, hold/resume and adjust the volume. Call Hold is done by pressing the call button once. Pressing the call button again will resume the call. Similarly, such call control functions could be done on the Avaya Workplace.

#### 10. Conclusion

These Application Notes describe the configuration steps required to integrate Yealink CP Series Speakerphones (CP700 CP900), Yealink USB Connect with Avaya Workplace Client for Windows. All test cases were completed successfully.

#### 11. Additional References

This section references the Avaya and Yealink documentation that are relevant to these Application Notes.

The following Avaya product documentation can be found at <a href="http://support.avaya.com">http://support.avaya.com</a>.

- [1] Administering Avaya Aura® Communication Manager, Release 8.1.x, Issue 6, Mar 2020
- [2] Planning for and Administering Avaya IX<sup>TM</sup> Workplace Client for Android, iOS, Mac and Windows, Sep 25, 2020.
- [3] Using Avaya IX<sup>TM</sup> Workplace Client for Android, iOS, Mac, and Windows, Aug 4, 2020.
- [4] Administering Avaya Aura® Session Manager, Release 8.1.x, Issue 6, Aug 2020.

The following Yealink documentation can be found at <a href="http://www.yealink.com">http://www.yealink.com</a>.

[5] Yealink USB Speakerphone CP700 & CP900 User Guide, Version1.0, Mar 2020.

#### ©2020 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and TM are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at <a href="mailto:devconnect@avaya.com">devconnect@avaya.com</a>.