

Avaya Solution & Interoperability Test Lab

Application Notes for Integrated Research's Prognosis for Unified Communication R11.7 with Avaya Aura® Application Enablement Services R8.1 - Issue 1.0

Abstract

These Application Notes describe the procedures for configuring Prognosis for Unified Communication R11.7 (Prognosis) to interoperate with Avaya Aura® Application Enablement Services R8.1.

Prognosis provides real-time monitoring and management solutions for IP telephony networks. Prognosis provides visibility of Avaya and other vendor's IP Telephony solutions from a single console. Prognosis monitors directly to Application Enablement Services using SNMP connection.

Readers should pay attention to **Section 2**, in particular the scope of testing as outlined in **Section 2.1** as well as the observations noted in **Section 2.2**, to ensure that their own use cases are adequately covered by this scope and results.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

1. Introduction

These Application Notes describe the compliance tested configuration used to validate Prognosis for Unified Communication R11.7 (herein after referred to as Prognosis) with Avaya Aura® Application Enablement Services (AES) R8.1. Prognosis uses Simple Network Management Protocol (SNMP) to monitor AES server, link availability and utilization.

2. General Test Approach and Test Results

The general test approach was to verify Prognosis using SNMP connection to monitor and display system status from AES.

DevConnect Compliance Testing is conducted jointly by Avaya and DevConnect members. The jointly-defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect Compliance Testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member's solution.

Avaya recommends our customers implement Avaya solutions using appropriate security and encryption capabilities enabled by our products. The testing referenced in these DevConnect Application Notes included the enablement of supported encryption capabilities in the Avaya products. Readers should consult the appropriate Avaya product documentation for further information regarding security and encryption capabilities supported by those Avaya products.

Support for these security and encryption capabilities in any non-Avaya solution component is the responsibility of each individual vendor. Readers should consult the appropriate vendor-supplied product documentation for more information regarding those products.

For the testing associated with these Application Notes, the interface between Avaya systems and the Prognosis did not include use of any specific encryption features as requested by Integrated Research.

2.1. Interoperability Compliance Testing

The feature test of the interoperability compliance testing was to verify Prognosis using web interface to display correct information of AES.

- Verify that the server statistics information for the AES is populated on Prognosis display: SNMP Availability, Prognosis Raised Alerts, Link Status, TSAPI Client Connections and DMCC Sessions.
- Verify that the list of AES links is visible in Prognosis: ASAI Link, CVLAN Link, DLG CTI Link, License, Server, SNMP Status, TSAPI CTI Link and TSAPI TLink.
- For each of the links, click on the links to view utilization details.

2.2. Test Results

All test cases were passed and met the requirements as shown in **Section 2.1** with following observation:

• The following links were not tested along with its detail since there is no available connection or device exists: CVLAN Link and DLG CTI Link.

2.3. Support

For technical support on Integrated Research Prognosis, contact the Integrated Research Support Team at:

Hotline: +61 (2) 9966 1066Email: support@ir.com

3. Reference Configuration

Figure 1 illustrates the test configuration used to verify the Prognosis application with Avaya Aura® Application Enablement Services. The configuration consists of a duplex Avaya Aura® Communication Manager (System A) with an Avaya G430 Media Gateway, and Avaya Aura® Media Server. Another simplex Avaya Aura Communication Manager (System B) was configured with an Avaya G450 Media Gateway. Both provides CTI links to Application Enablement Services. Avaya Aura® Session Manager was configured via Avaya Aura® System Manager to provide SIP Deskphones. Avaya Session Border Controller for Enterprise was used to complete a SIP trunk connection to simulate a PSTN connection to the Enterprise solution.




Figure 1: Test Configuration Diagram

4. Equipment and Software Validated

The following equipment and software were used for the compliance test provided:

Equipment/Software	Release/Version
Avaya Aura® Communication Manager	R018x.01.0.890.0
(System A)	R8.1.0.2.0 – SP2
	Update ID 01.0.890.0-25578
Avaya Aura® Media Server	R8.0.1.121
G430 Media Gateway	41.16.0
- MGP	
Avaya Aura® Enablement Services	8.1.0.0.0.9-1 with Super patch 1
Avaya Aura® Communication Manager	R018x.01.0.890.0
(System B)	R8.1.0.2.0 – SP2
	Update ID 01.0.890.0-25578
G450 Media Gateway	41.16.0
- MGP	
Avaya Aura® System Manager	System Manager 8.1.1.0
	Build No. – 8.1.0.0.733078
	Software Update Revision No:
	8.1.1.0.0310503
	Feature Pack 1
Avaya Aura® Session Manager	Session Manager R8.1 FP1
	Build No. – 8.1.0.0.810015
J100 Series IP Telephones	
- J179	4.0.2.1.3 (SIP)
- J129	6.8202 (H323)
96x1 Series IP Telephones	
- 9641G	7.1.6.1.3 (SIP)
- 9611G	6.8202 (H323)
Prognosis for Unified Communications	11.7
running on Windows Server 2016	

Note: All Avaya Aura® systems and Prognosis runs on VMware 6.x virtual platform.

5. Configure Avaya Aura® Communication Manager

The configuration of Communication Manager and AES is assumed to be in place and will not be discussed in this document. For more information of how to configure Communication Manager and AES, please refer to **Section 11**.

6. Configure Avaya Aura® Session Manager


The configuration of Session Manager is assumed to be in place and will not be discussed in this document. For more information of how to configure Session Manager, please refer to **Section 11**.

7. Configure Avaya Aura® Application Enablement Services

The initial administration of Application Enablement Services and the connection to Communication Manager is assumed to be in place and will not be covered here. This section only covers the configuration of SNMP connection of Application Enablement Services that is required for the purpose of administering Prognosis.

AES is configured via the AES Management web interface. In order to access the web interface, enter <a href="https://<ip-addr>/">https://<ip-addr>/ as the URL in an internet browser, where <ip-addr> is the IP address of the AES. Log in using the appropriated login credential. The screen shown below is displayed.

Note: All of the screens in this section are shown after the AES had been configured. Click **Save** button to save the screen parameters configured on Application Enablement Services if needed.



7.1. Configure SNMP Connection

To configure SNMP Connection, navigate to **Utilities** \rightarrow **SNMP** \rightarrow **SNMP Agent**. The SNMP Agent page is displayed in the right. In the **SNMP Agent**, configure the following parameters as shown below.

• Tick **Enable SNMP Version 2c** and enter the desired security name, in this case "avaya123". This security name will be used in Prognosis configuration.

AVAYA	Application Enable Management
Utilities SNMP SNMP Agent	
▶ AE Services Communication Manager	SNMP Agent
Interface High Availability	MIB II System Group Data: Location: Unknown
LicensingMaintenance	Contact: Unknown SNMP Protocol Access:
NetworkingSecurity	Enable SNMP Version 1 Community Name:
StatusUser Management	€ Enable SNMP Version 2c
▼ Utilities	Community Name: avaya123 Enable SNMP Version 3
Diagnostics Email Notification	User Name:
▶ HMDC	Authentication Protocol: None ▼ Authentication Password:
Product ID SNMP Agent	Privacy Protocol: None ▼ Privacy Password:


Navigate to **Authorized IP Addresses for SNMP Access** from the same **SNMP Agent** settings. Enter IP address of the Prognosis monitoring server. This will allow the Prognosis server to access the AE server via SNMP.

- Select Following IP Addresses.
- **IP Address 1**: enter Prognosis IP address, example: 10.1.10.124.


Authorized IP Addresses for SNMP Access*
O No Access
Any IP Addresses
Following IP Addresses
IP Address 1: 10.1.10.124
IP Address 2:
IP Address 3:
IP Address 4:
IP Address 5:
Apply Changes Cancel Changes Note: There is no ip access restriction on Software Only for SNMP Version 3.

8. Configure Prognosis

This section describes the configuration of Prognosis required to interoperate with Application Enablement Services. Log in to the Prognosis with administrative privileges. Launch the Prognosis Administration by clicking **Start** \rightarrow **All Programs** \rightarrow **Prognosis** \rightarrow **Administration** and log in with the appropriate password.



The **Prognosis Administration** homepage is displayed as shown below.



8.1. Administer Avaya Aura® Enablement Service Configuration

Click Add System and scroll below to Contact Centers.

Contact Centers



Select **Avaya Aura Application Enablement Service** from drop-down menu. Click **Add** to add a new AES. In this test configuration, the following entries are added for AES with display name of **AES81** and with IP addresses of **10.1.10.70**.

The following settings were used during the compliance test.

Basic Details:


Display Name: AES81IP address: 10.1.10.70Customer Name: Avaya

• Site Name: DevCon Lab

SNMP Connection Details:


- Select Use SNMP Version 2c
- Community String: As configured in Section 7.1

Leave the **Databases and Thresholds** as checked. Click **Add** to affect the addition.




8.2. Verifying Configurations with Prognosis Client


On Prognosis server, click **Start** \rightarrow **All Programs** \rightarrow **Prognosis** \rightarrow **Prognosis Client** to start the Windows Client application. Log in with the appropriate credentials.




To check the configurations of the AES to be monitored, expand **Configurations** of the Monitoring Node on the left pane, right-click on **AVAYA_CONTACT** and select **Properties**.




The **AES** entry configured earlier is displayed below:



To check the configurations of the password to be monitored, expand Configurations of the Monitoring Node on the left pane, right-click on **PASSWORDS** and select **Properties**.




The password entries are displayed. In the compliance test, the first entry of AES was added **snmpv2c:AES81** with the password (Community String) as configured in **Section 8.1**.




9. Verification Steps

This section provides the tests that can be performed to verify proper configuration of AES and Prognosis. Log in to the Prognosis with administrative privileges. Launch the Prognosis View by clicking Start \rightarrow All Programs \rightarrow Prognosis \rightarrow Prognosis Client as in Section 8.2. Select on the left pane under Knowledge \rightarrow IP Telephony Manager \rightarrow Virtualization \rightarrow All Contact Centers.



Click the **AES81** on the right plane (not shown), a new page shows **Avaya AES** general status of the monitored AES such as AES Server, Status, SNMP Availability, Link Status, DMCC sessions etc., ... as shown below. Details of the **Link Status** can be viewed by clicking the individual CTI link **Type**.



10. Conclusion

These Application Notes describe the procedures for configuring the Integrated Research Prognosis for Unified Communications R11.7 to interoperate with Avaya Aura® Application Enablement Services R8.1. During compliance testing, all test cases were completed successfully with observation noted in **Section 2.2**.

11. Additional References

The following Avaya documentations can be obtained on the http://support.avaya.com.

- [1] Administering Avaya Aura® Communication Manager, Release 8.1.x, Issue 5, Nov 2019.
- [2] Administering Avaya Aura® Session Manager, Release 8.1.1, Issue 2, Oct 2019.
- [3] Administering Avaya Aura® Application Enablement Services, Release 8.1.x, Issue 3, Oct 2019.

Prognosis documentations are provided in the online help that comes with the software package.

©2020 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and TM are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at devconnect@avaya.com.